



National Transportation Safety Board Aviation Accident Final Report

Location:	FOLEY, MN	Accident Number:	CHI94LA144
Date & Time:	05/01/1994, 2020 CDT	Registration:	N4104D
Aircraft:	Helio H-800	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE PILOT-IN-COMMAND HAD FLOWN APPROXIMATELY 2.3 HOURS AFTER HIS INITIAL DEPARTURE WITH 45 GALLONS OF FUEL IN THE AMPHIBIOUS FLOAT EQUIPPED AIRPLANE. HIS ESTIMATION OF FUEL CONSUMPTION WAS 39 GALLONS PER HOUR (GPH) AT TAKEOFF POWER AND 23 GPH AT CRUISE. SEVERAL TOUCH AND GO LANDINGS WERE PERFORMED DURING THE FLIGHT. WHILE IN CRUISE FLIGHT A TOTAL LOSS OF ENGINE POWER OCCURRED AND A FORCED LANDING WAS MADE ON A GRAVEL ROAD. DURING LANDING, THE FLOAT NOSE WHEELS DUG INTO SOFT GRAVEL AND THE AIRPLANE FLIPPED OVER. POST CRASH INVESTIGATION REVEALED NO ENGINE ANOMOLIES, NO EVIDENCE OF FUEL IN THE TANKS, NOR ANY INDICATION OF FUEL SPILLAGE ON THE GROUND. THE PILOT STATED HE BELIEVED HE EXHAUSTED HIS FUEL SUPPLY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT-IN-COMMAND'S FAILURE TO PERFORM ACCURATE FUEL CONSUMPTION CALCULATIONS. A FACTOR WAS THE SOFT GRAVEL ROAD LANDING AREA.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL
Phase of Operation: CRUISE

Findings

1. FLUID,FUEL - EXHAUSTION
 2. (C) FUEL CONSUMPTION CALCULATIONS - INACCURATE - PILOT IN COMMAND
-

Occurrence #2: FORCED LANDING
Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: NOSE OVER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (F) AIRPORT FACILITIES,RUNWAY/LANDING AREA CONDITION - LOOSE GRAVEL/SANDY

Factual Information

On May 1, 1994, at 2020 hours central daylight time, an amphibian Helio H-800, N4104D, operated by T. J. Farms of St. Cloud, Minnesota, was substantially damaged 10 miles northeast of St. Cloud Municipal Airport, St. Cloud, Minnesota. The pilot experienced a total loss of engine power and made a forced landing on a gravel road. The amphibious float equipped airplane went over an embankment, dragged a float tip in soft gravel, and came to a stop upside down. The private pilot was uninjured. Visual meteorological conditions existed at the time of the accident and winds were calm. The flight originated at Princeton Municipal Airport, Princeton, Minnesota, at 2015 hours central standard time to reposition the airplane to a private strip at Long Lake, southeast of St. Cloud, Minnesota. No flight plan was filed.

Installation of amphibious floats had just been completed on the airplane. The pilot stated he had departed Cambridge Municipal Airport, Cambridge, Minnesota, 2.3 tachometer hours earlier with an estimated 45 gallons of fuel, performed touch and go landings, and was on his final leg of this flight. The pilot also stated he believes he exhausted his fuel supply. The fuel consumption of the Lycoming IO-720A engine installed on the H-800 is 33 gallons per hour (gph) at takeoff rated power and 23 gph at 75% cruise power as per Lycoming data. This was confirmed by the pilot and FAA inspector on scene. Post crash investigation revealed no fuel in the tanks, nor any indication of fuel spillage on the ground below the wreckage.

Pilot Information

Certificate:	Private	Age:	39, Male
Airplane Rating(s):	Single-engine Land; Single-engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	04/06/1993
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	446 hours (Total, all aircraft), 74 hours (Total, this make and model), 25 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Helio	Registration:	N4104D
Model/Series:	H-800 H-800	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	H-17
Landing Gear Type:	Amphibian	Seats:	4
Date/Type of Last Inspection:	10/29/1993, Annual	Certified Max Gross Wt.:	4000 lbs
Time Since Last Inspection:	30 Hours	Engines:	1 Reciprocating
Airframe Total Time:	886 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-720 A/B
Registered Owner:	T. J. FARMS, LTD.	Rated Power:	400 hp
Operator:	THOMAS J. HAMMER	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	STC, 1024 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	2051 CDT	Direction from Accident Site:	250°
Lowest Cloud Condition:	Scattered / 8000 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	5°C / -2°C
Precipitation and Obscuration:			
Departure Point:	PRINCETON, MN (PNM)	Type of Flight Plan Filed:	None
Destination:	LONG LAKE, MN	Type of Clearance:	None
Departure Time:	2015 CDT	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): MATTHEW L THOMAS **Report Date:** 12/07/1994

Additional Participating Persons: O. T FRAMPTON; MINNEAPOLIS, MN

Publish Date:

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov, or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).