



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	BROOMFIELD, CO	<b>Accident Number:</b>	FTW94FA141
<b>Date &amp; Time:</b>	05/01/1994, 1220 MDT	<b>Registration:</b>	N1905Y
<b>Aircraft:</b>	MOONEY M20E	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	2 Fatal
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

---

## HISTORY OF FLIGHT

On May 1, 1994, at 1220 mountain daylight time, N1905Y, a Mooney M20E, was destroyed during a forced landing in Broomfield, Colorado. The private pilot and passenger were fatally injured. Visual meteorological conditions prevailed.

Shortly after taking off from runway 11L at the Jefferson County Airport, the pilot requested clearance to make an immediate landing; he did not indicate the nature of his emergency. A witness said he heard a loud metallic noise coming from the engine as the airplane passed overhead. He said the pilot made a steep right bank in an attempt to land on runway 29L and impacted terrain.

## WRECKAGE AND IMPACT INFORMATION

A ground scar was located abeam the 2,000 foot distance-to-go marker of runway 11L, between runways 11L and 11R. Just beyond this scar was a 60 foot gouge in the earth, aligned on a magnetic heading 250 degrees. At the end of this gouge was a 40 foot wide and 10 foot deep ravine. The airplane was found on the bank of the ravine on a magnetic heading of 080 degrees.

The propeller assembly remained attached to the engine but one blade was broken off. All three blades exhibited chordwise scratches on the cambered surfaces and were S-curved midspan. The empennage was severed just aft of the baggage compartment. The left wing remained attached to the fuselage but had a circumferential crack at the inboard aileron hinge point. The flap was broken off. The right wing lay next to the fuselage but was twisted 180 degrees.

## MEDICAL AND PATHOLOGICAL INFORMATION

An autopsy was conducted by the Jefferson County Coroner's Office, Golden, Colorado. In

addition, FAA's Civil Aeromedical Institute (CAMI) conducted a toxicology screen. Trace amounts of pseudoephedrine was detected in blood and urine, and guaiphenesin was detected in urine. Acetaminophen was detected in blood (6.900 ug/ml, ug/g) and urine (152.600 ug/ml, ug/g). According to a CAMI toxicologist, acetaminophen is found to Tylenol; pseudoephedrine is a decongestant, and guaiphenesin is an expectorant. On his most recent medical examination dated October 13, 1993, the pilot indicated he was taking medications that included acetaminophen and pseudoephedrine. The toxicologist was unable to say definitively whether any of these medications, either taken singularly or together, may have been contributory to the accident.

## TESTS AND RESEARCH

Engine disassembly revealed the crankshaft had failed at the crankcheek between numbers 3 and 4 connecting rod journals. The number 4 cylinder lower right base nut and the number 3 cylinder upper left base nut were finger tight. The upper right base nuts on numbers 2 and 4 cylinders broke free approximately 400 inch-pounds. The number 1 cylinder lower right and left base nuts and the number 3 cylinder lower right base nut loosened at less than 500 inch-pounds. All other base nuts loosened at less than 350 inch-pounds. Metal shavings were found inside the left magneto mounting on the accessory case, on the oil suction screen, and in the oil sump. There were two breaks on the bottom of the crankcase below the numbers 3 and 4 cylinders. The engine received a major overhaul on January 11, 1991. Total engine time was 4,412 hours: 266 hours since major overhaul and 11 hours since a 100-hour inspection.

The crankshaft was sent to NTSB's metallurgical laboratory for analysis. According to its report, the crankshaft failed as the result of "fatigue cracking that originated from the radius on the aft end on the number 3 connecting rod journal and propagated through most of the crankcheek before final separation." There was "no evidence of metallurgical or manufacturing defects" in the crankshaft.

The airplane had been modified by two Supplemental Type Certificates (STCs). The engine was equipped with a Rayjay turbocharger (SE32WE) and a McCauley "BlackMac" 3-blade propeller (SA704NE). According to a spokesman for U.S. Propeller Service in East Haddon, Connecticut, holder of STC SA704NE, the company will not install the "BlackMac" propeller on an airplane with a turbocharged engine because certification vibratory tests were made on normally aspirated engines only. No data exists for turbocharged engines.

Maintenance records indicate that after its installation on January 17, 1991, the propeller was removed on March 28, 1991, "for blade angle check," and on March 19, 1991, for "static balance" and "re-index prop #1 blade 180 degrees." On May 23, 1991, the propeller received a "dynamic balance --- before .55 IPS, after .1 IPS."

## ADDITIONAL INFORMATION

The wreckage was released to the owner's representative on May 3, 1994. The crankshaft was released on August 15, 1994.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	42, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim.	<b>Last FAA Medical Exam:</b>	10/13/1993
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	560 hours (Total, all aircraft), 347 hours (Total, this make and model), 502 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	MOONEY	<b>Registration:</b>	N1905Y
<b>Model/Series:</b>	M20E M20E	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	No
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	288
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	03/25/1994, 100 Hour	<b>Certified Max Gross Wt.:</b>	2575 lbs
<b>Time Since Last Inspection:</b>	11 Hours	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	4412 Hours	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	IO-360-A1A
<b>Registered Owner:</b>	VERBOSH, GEORGE M.	<b>Rated Power:</b>	200 hp
<b>Operator:</b>	VERBOSH, GEORGE M.	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	BJC, 5671 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1229 MDT	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 7000 ft agl	Visibility	60 Miles
Lowest Ceiling:	Broken / 20000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	14° C / -1° C
Precipitation and Obscuration:			
Departure Point:	(BJC)	Type of Flight Plan Filed:	None
Destination:	(BJC)	Type of Clearance:	VFR
Departure Time:	1218 MDT	Type of Airspace:	Class D

## Airport Information

Airport:	JEFFERSON COUNTY (BJC)	Runway Surface Type:	Asphalt
Airport Elevation:	5657 ft	Runway Surface Condition:	Dry
Runway Used:	29L	IFR Approach:	
Runway Length/Width:	7000 ft / 75 ft	VFR Approach/Landing:	Forced Landing

## Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Fatal	Latitude, Longitude:	

## Administrative Information

Investigator In Charge (IIC):	ARNOLD W SCOTT,
Additional Participating Persons:	ROBERT C BUNDERSON; DENVER, CO
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .