



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	RED BLUFF, CA	<b>Accident Number:</b>	LAX95LA177
<b>Date &amp; Time:</b>	05/02/1995, 1136 PDT	<b>Registration:</b>	N6636R
<b>Aircraft:</b>	BEECH C23	<b>Injuries:</b>	2 Serious
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

## Analysis

THE PILOT SAID THAT WHEN HE TRIED TO MAKE A THROTTLE ADJUSTMENT IT HAD NO EFFECT ON THE ENGINE RPM. AFTER ENTERING DOWNWIND ABEAM HIS TOUCHDOWN POINT, HE SHUT DOWN THE ENGINE AND ATTEMPTED TO GLIDE THE REMAINDER OF THE DISTANCE. THE AIRCRAFT TOUCHED DOWN SHORT OF THE RUNWAY AND STRUCK AN EMBANKMENT. AN INSPECTION OF THE AIRCRAFT REVEALED THAT THE THROTTLE LINKAGE HAD SEPARATED FROM THE CARBURETOR THROTTLE ARM. THE BOLT, CASTELLATED NUT, AND WASHER WHICH SECURES THE ASSEMBLY TOGETHER WERE NOT PRESENT. THE ENGINE WAS REINSTALLED IN THE AIRCRAFT FOLLOWING A MAJOR OVERHAUL, 1 MONTH AND 2 OPERATING HOURS PRIOR TO THE ACCIDENT. AN ANNUAL INSPECTION WAS ALSO COMPLETED AND SIGNED OFF AT THAT TIME. THE MECHANIC WHO PERFORMED THE ENGINE REINSTALLATION SAID THAT THE BOLT HAD BEEN REINSTALLED AND THAT A COTTER PIN HAD ALSO BEEN INSTALLED IN THE PROCESS. THE MECHANIC WHO PERFORMED THE ANNUAL INSPECTION REPORTED THAT HE HAD NOT LOOKED THAT CLOSELY AT THE ENGINE SINCE IT HAD JUST BEEN INSTALLED AND INSPECTED BY ANOTHER MECHANIC. THE MANUFACTURER REPORTED THAT THE DESIGN OF THE ASSEMBLY DOES NOT PLACE LOADS ON THE BOLT THAT WOULD BE SUFFICIENT TO PRODUCE AN OVERLOAD FAILURE.

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the separation of the throttle linkage due to improper installation, and the pilot's misjudgement of the glide path necessary to reach the runway prior to shutting down the engine.

## Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation: CRUISE - NORMAL

### Findings

1. (C) THROTTLE/POWER LEVER, LINKAGE - DISCONNECTED
2. (C) MAINTENANCE, INSTALLATION - IMPROPER - COMPANY MAINTENANCE PERSONNEL
3. (C) MAINTENANCE, INSPECTION - INADEQUATE - COMPANY MAINTENANCE PERSONNEL

Occurrence #2: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: APPROACH - VFR PATTERN - DOWNWIND

### Findings

#### 4. ENGINE SHUTDOWN - PERFORMED - PILOT IN COMMAND

-----  
Occurrence #3: FORCED LANDING  
Phase of Operation: APPROACH - VFR PATTERN - DOWNWIND  
-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings  
5. TERRAIN CONDITION - BERM  
6. (C) DISTANCE/ALTITUDE - MISJUDGED - PILOT IN COMMAND

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	66
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Instrument Rating(s):</b>	Airplane
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	2067 hours (Total, all aircraft), 532 hours (Total, this make and model), 1989 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	BEECH	<b>Registration:</b>	N6636R
<b>Model/Series:</b>	C23 C23	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	DONALD EUGENE LANDEN	<b>Engine Manufacturer:</b>	LYCOMING
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	O-360--A4J
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

### Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	RBL, 349 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	Broken / 2500 ft agl	<b>Wind Speed/Gusts, Direction:</b>	10 knots / , 160°
<b>Temperature:</b>	17° C	<b>Visibility</b>	30 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	HALF MOON BAY, CA (HAF)	<b>Destination:</b>	, CA (RBL)

### Airport Information

<b>Airport:</b>	RED BLUFF (RBL)	<b>Runway Surface Type:</b>	Asphalt
<b>Runway Used:</b>	15	<b>Runway Surface Condition:</b>	Dry
<b>Runway Length/Width:</b>	5984 ft / 150 ft		

## Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude, Longitude:			

## Administrative Information

Investigator In Charge (IIC):	ROBERT R CRISPIN	Adopted Date:	09/24/1995
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .		

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.