



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	SAND POINT, AK	<b>Accident Number:</b>	ANC95TA067
<b>Date &amp; Time:</b>	06/02/1995, 1940 AKD	<b>Registration:</b>	N125FG
<b>Aircraft:</b>	PIPER PA-18-150	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation -		

## Analysis

THE PILOT REPORTED HE HAD LANDED THE 29' TUNDRA TIRE EQUIPPED TAIL WHEEL AIRPLANE ON THE HARD SURFACED RUNWAY AND WAS SLOWING TO TAXI SPEED WHEN THE AIRPLANE SUDDENLY VEERED TO THE RIGHT. HE APPLIED FULL LEFT BRAKE AND RUDDER, BUT WAS UNABLE TO STRAIGHTEN THE AIRPLANE BEFORE THE LEFT MAIN LANDING GEAR COLLAPSED. SUBSEQUENT EXAMINATION OF THE TAILWHEEL STEERING MECHANISM FOUND THE ANTI-CASTORING LIMITS WERE BELOW THE MANUFACTURER'S RECOMMENDED BREAK FREE FORCE, WHICH ALLOWED THE AIRPLANE TO TURN FASTER AND MORE FREELY TO THE RIGHT THAN COMMANDED BY THE RUDDER CONTROL INPUTS. CONVERSATIONS WITH PILOTS WHO HAVE EXTENSIVE EXPERIENCE WITH TUNDRA TIRES DISCLOSED THAT AIRPLANES SO EQUIPPED ARE MUCH MORE DIFFICULT TO HANDLE ON HARD SURFACED RUNWAYS THAN AIRPLANES WITH CONVENTIONAL TIRES.

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The premature castoring of the tailwheel steering mechanism. A factor associated the accident is the added degree of difficulty in handling airplanes equipped with oversize 'tundra' tires.

## Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER  
Phase of Operation: LANDING - ROLL

### Findings

1. (C) LANDING GEAR, TAILWHEEL LOCK - UNLATCHED
2. (F) DIRECTIONAL CONTROL - DIMINISHED
3. DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

-----  
Occurrence #2: MAIN GEAR COLLAPSED  
Phase of Operation: LANDING - ROLL

## Pilot Information

<b>Certificate:</b>	Airline Transport; Flight Instructor	<b>Age:</b>	37
<b>Airplane Rating(s):</b>	Multi-engine Land; Multi-engine Sea; Single-engine Land; Single-engine Sea	<b>Instrument Rating(s):</b>	Airplane
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	Airplane Single-engine
<b>Flight Time:</b>	2450 hours (Total, all aircraft), 85 hours (Total, this make and model), 2290 hours (Pilot In Command, all aircraft), 62 hours (Last 90 days, all aircraft), 60 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	PIPER	<b>Registration:</b>	N125FG
<b>Model/Series:</b>	PA-18-150 PA-18-150	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	STATE OF ALASKA	<b>Engine Manufacturer:</b>	LYCOMING
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	O-320-A2B
<b>Flight Conducted Under:</b>	Part 91: General Aviation -		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	, 0 ft msl	<b>Weather Information Source:</b>	Pilot
<b>Lowest Ceiling:</b>	None / 0 ft agl	<b>Wind Speed/Gusts, Direction:</b>	5 knots / , 310°
<b>Temperature:</b>	10° C	<b>Visibility</b>	20 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	PORT MOLLER, AK	<b>Destination:</b>	(SDP)

## Airport Information

<b>Airport:</b>	SAND POINT (SDP)	<b>Runway Surface Type:</b>	Asphalt
<b>Runway Used:</b>	31	<b>Runway Surface Condition:</b>	Dry
<b>Runway Length/Width:</b>	4000 ft / 150 ft		

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>			

## Administrative Information

Investigator In Charge (IIC): JAMES D LA BELLE Adopted Date: 11/08/1995

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.