



National Transportation Safety Board Aviation Accident Final Report

Location:	GENESE0, NY	Accident Number:	NYC95LA131
Date & Time:	06/01/1995, 1430 EDT	Registration:	N43705
Aircraft:	TAYLORCRAFT BC-12	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Serious, 1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE AIRPLANE LANDED AT A LOCAL AIRPORT, WHERE THE PILOT PURCHASED AUTO FUEL FROM A VENDOR. PLASTIC CONTAINERS WERE USED TO TRANSPORT THE FUEL TO THE AIRPLANE. DURING INITIAL CLIMB AFTER TAKEOFF, THE ENGINE LOST POWER AND THE PILOT MADE A FORCED LANDING. DURING THE LANDING THE AIRPLANE NOSED OVER. EXAMINATION REVEALED THE AIRPLANE'S FUEL TANKS ALL CONTAINED AUTO FUEL, AND THE CARBURETOR BOWL CONTAINED WATER AND SEDIMENT. THE PLASTIC CONTAINERS USED TO TRANSPORT THE FUEL ALSO CONTAINED WATER AND SEDIMENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate preflight inspection, which failed to detect water-contaminated fuel which resulted in the loss of engine power. Also causal was the pilot's failure to maintain airspeed during the forced landing, which resulted in the inadvertent stall/spin and collision with the terrain.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) FLUID,FUEL - CONTAMINATION,WATER
 2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND
 3. FLUID,FUEL - STARVATION
-

Occurrence #2: FORCED LANDING
Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: DESCENT - EMERGENCY

Findings

4. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND
 5. STALL/SPIN - INADVERTENT - PILOT IN COMMAND
-

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Factual Information

On June 1, 1995, at 1430 eastern daylight time, a Taylorcraft BC-12, N43705, was substantially damaged during a forced landing after takeoff from the Geneseo Airport, Geneseo, New York. The private pilot was seriously injured and the passenger received minor injuries. Visual meteorological conditions prevailed, for the personal flight originating at Geneseo. No flight plan had been filed for the flight conducted under 14 CFR Part 91.

The pilot and passenger flew from Lancaster, New York, to the Geneseo Airport (D52), the day of the accident. While at D52, the pilot purchased auto fuel from a local vendor to refuel his airplane, and used plastic containers to transport the fuel. After about 45 minutes of ground time at D52, the pilot and passenger boarded the airplane for the return trip to Lancaster.

In the NTSB Form 6120.1/2, the pilot stated that he performed a soft field takeoff at D52, and during the initial climb the engine lost power. He then observed trees and power lines at the end of the runway, and elected to attempt a landing to the left of the runway.

The pilot further stated:

...Airplane proceeded to glide normally, then at approximately 100 feet, the nose of the aircraft dropped straight down and the aircraft plunged to the ground...

In a written statement, a witness to the accident said:

...I heard an aircraft engine miss. I looked north towards the runway and saw a blue and white aircraft at about 100 feet. Its engine quit, and it turned and dived vertically to the left, hitting the ground.

A Federal Aviation Administration Airworthiness Inspector examined the wreckage at the accident site. The Inspector's report stated that the airplane's three fuel tanks contained auto fuel, and the carburetor bowl contained water and sediment. The Inspector also examined the plastic containers used to transport the auto fuel to the airplane. His report stated, "...it appears the same sediments and water drained from the carburetor bowl were found in the plastic containers..."

Pilot Information

Certificate:	Private	Age:	70, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	11/16/1993
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	402 hours (Total, all aircraft), 183 hours (Total, this make and model), 402 hours (Pilot In Command, all aircraft), 67 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	TAYLORCRAFT	Registration:	N43705
Model/Series:	BC-12 BC-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	7364
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	07/28/1994, Annual	Certified Max Gross Wt.:	1200 lbs
Time Since Last Inspection:	94 Hours	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	A-65-8
Registered Owner:	BERNARD CHESNA	Rated Power:	65 hp
Operator:	BERNARD CHESNA	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24° C
Precipitation and Obscuration:			
Departure Point:	(D77)	Type of Flight Plan Filed:	None
Destination:	LANCASTER, NY (D77)	Type of Clearance:	None
Departure Time:	1430 EDT	Type of Airspace:	Class G

Airport Information

Airport:	GENESE0 (D52)	Runway Surface Type:	Grass/turf
Airport Elevation:	560 ft	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	4695 ft / 90 ft	VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ROBERT L PEARCE	Report Date:	12/04/1995
Additional Participating Persons:	PEDRO L MUNOZ; ROCHESTER, NY		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).