



National Transportation Safety Board Aviation Accident Factual Report

Location:	MALONE, NY	Accident Number:	NYC95LA137
Date & Time:	07/01/1995, 1150 EDT	Registration:	CGMEZ
Aircraft:	FIELD VARI-EZE	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None

Flight Conducted Under: Part 91: General Aviation - Personal

On July 1, 1995, at 1150 eastern daylight time, a homebuilt VARI-EZE, CGMEZ, was substantially damaged during a forced landing to the Malone-Dufort Airport (MAL), Malone, New York. The private pilot was not injured. Visual meteorological conditions prevailed, for the personal flight that departed MAL, at 1130. No flight plan had been filed for the flight conducted under 14 CFR Part 91.

In the NTSB Form 6120.1/2, the pilot stated that he had completed three loose formation passes over runway 23, with another homebuilt airplane. He added power at the completion of the last low pass, and noticed a vibration 1 to 2 seconds later. This was followed by a loss of propeller thrust and high engine RPM.

The pilot secured the engine, and due to personnel to his left, and trees directly ahead and to the right, he initiated a turn back to the runway. At the completion of the 180 degree turn, he observed the airplane from the formation flight approaching head-on. The pilot then performed a landing to a rough field, adjacent to runway 23. During the landing roll, the main landing gear and left wing separated from the airplane.

The pilot stated that initial examination of the wreckage revealed that the propeller shaft had failed at the junction of the middle bearing inner ring.

The pilot further stated:

Prior to removal of the PSRU [propeller speed reduction unit], a professional mechanical engineer and several other knowledgeable people inspected the failed PSRU. The PSRU vendor was also consulted by phone. It was agreed by all...the cause was bending induced fatigue failure, induced by thermal expansion of the PSRU back plate. This caused the front bearing to rise while the center and rear bearings were held rigid by the common housing. This induced a slight bend in the shaft with the stress focused right at the center bearing inner ring.

The PSRU was sent to the Transportation Safety Board (TSB) of Canada, for further examination. The TSB of Canada report stated:

...the shaft failed in a progressive manner from fatigue cracking at the stress concentration provided by the change in shaft diameter...The material of construction was shown to be a unalloyed steel, in the normalized condition, resulting in a relatively low strength material for the application. The fatigue resistance of the part would certainly have been improved by the use of the intended AISI 4140 alloy material...

The airplane was built in 1984, and flown 566 hours with a Lycoming, O-234 engine. In 1994, the Lycoming engine was replaced by a Subaru, EA-81. In addition, a synchronous belt PSRU was installed. This was a "two bearing" unit, that drove the propeller at a ratio of 1.84 to 1. The airplane accumulated another 125 hours with this installation.

During the winter of 1994/1995, the PSRU was replaced with a one-of-a-kind unit. This unit utilized a third bearing to provide support for a longer propeller shaft. According to the pilot's statement, the new unit was ground tested for 8 hours, and flown for 49 flight hours, prior to the failure.

Pilot Information

Certificate:	Private	Age:	49, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	04/26/1995
Occupational Pilot:	Last Flight Review or Equivalent:		
Flight Time:	960 hours (Total, all aircraft), 720 hours (Total, this make and model), 910 hours (Pilot In Command, all aircraft), 49 hours (Last 90 days, all aircraft), 32 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	FIELD	Registration:	CGMEZ
Model/Series:	VARI-EZE VARI-EZE	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental	Serial Number:	M001
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	1050 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	740 Hours	Engine Manufacturer:	Subaru
ELT:	Not installed	Engine Model/Series:	EA-81
Registered Owner:	NIGEL G. FIELD	Rated Power:	110 hp
Operator:	NIGEL G. FIELD	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	7 Miles
Lowest Ceiling:	Broken / 4500 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29° C
Precipitation and Obscuration:			
Departure Point:	(MAL)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1130 EDT	Type of Airspace:	Class E

Airport Information

Airport:	MALONE-DUFORT (MAL)	Runway Surface Type:	
Airport Elevation:	786 ft	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced Landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ROBERT L PEARCE
Additional Participating Persons:	ALLEN BELCHER; ALBANY, NY
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .