



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	SAINT JOHNS, AZ	<b>Accident Number:</b>	LAX96FA106
<b>Date &amp; Time:</b>	02/05/1996, 0950 MST	<b>Registration:</b>	N131T
<b>Aircraft:</b>	Convair C-131E	<b>Injuries:</b>	4 Fatal
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Ferry		

## Analysis

Witnesses observed the aircraft departing from runway 14 with a rolling start. They said the aircraft rotated at the departure end of the runway and remained in ground effect with an excessive, nose high attitude. It then struck the airport perimeter fence, a barrier wall, and power lines. Power line wires were dragged through a residential area, resulting in additional damage. The airplane then crashed in a pasture and burned. Investigation revealed the airplane had been loaded to a gross weight (GW) of 50,870 lbs. Its maximum GW was limited to 48,000 lbs at sea level with the use of antidetonation injection (ADI) fluid and 40,900 lbs without ADI. Density altitude at the airport was 6200 feet. For conditions at the airport, maximum GW for takeoff with ADI and 15 degrees of flaps was 43,205 lbs; without ADI and with 13 degrees of flaps, maximum GW was 38,909 lbs. The airplane flaps were found in the retracted position, but there was no performance data for takeoff with the flaps retracted. No ADI fluid was found in the line to the right engine, although it was intact; the ADI tank was destroyed; the ADI line to the left engine was damaged. The airplane was being flown under provision of a ferry permit, which did not provide for the cargo or the two passengers that were aboard. The first pilot (PIC) had accrued about 8 hours of flight experience in the make and model of airplane.

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: inadequate preflight planning and preparation by the first pilot (PIC), his failure to ensure the aircraft was properly loaded within limitations, his failure to use proper flaps for takeoff, his failure to use ADI assisted takeoff, and his resultant failure to attain sufficient airspeed to climb after takeoff. Factors relating to the accident were: the high density altitude, and the PIC's lack of experience in the make and model of airplane.

## Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT  
Phase of Operation: TAKEOFF - INITIAL CLIMB

### Findings

1. (C) PREFLIGHT PLANNING/PREPARATION - INADEQUATE - PILOT IN COMMAND
2. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT - PILOT IN COMMAND
3. (C) AIRCRAFT WEIGHT AND BALANCE - EXCEEDED - PILOT IN COMMAND
4. (C) FLAPS - NOT USED - PILOT IN COMMAND
5. (F) WEATHER CONDITION - HIGH DENSITY ALTITUDE
6. (C) AIRSPEED - NOT ATTAINED - PILOT IN COMMAND
7. OBJECT - WALL/BARRICADE
8. OBJECT - WIRE, TRANSMISSION

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: DESCENT - UNCONTROLLED

## Pilot Information

<b>Certificate:</b>	Airline Transport; Commercial	<b>Age:</b>	61
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land	<b>Instrument Rating(s):</b>	Airplane
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	Airplane Multi-engine; Airplane Single-engine
<b>Flight Time:</b>	18400 hours (Total, all aircraft), 8 hours (Total, this make and model), 12000 hours (Pilot In Command, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Convair	<b>Registration:</b>	N131T
<b>Model/Series:</b>	C-131E C-131E	<b>Engines:</b>	2 Reciprocating
<b>Operator:</b>	ROBERTUS S. KELDER	<b>Engine Manufacturer:</b>	P&W
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	R-2800-CB16
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Ferry		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	SOW, 6412 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	Broken / 0 ft agl	<b>Wind Speed/Gusts, Direction:</b>	4 knots / , 190°
<b>Temperature:</b>	12° C	<b>Visibility</b>	40 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	(SJN)	<b>Destination:</b>	BROWNSVILLE, TX (BRO)

## Airport Information

<b>Airport:</b>	ST JOHNS IND AIRPARK (SJN)	<b>Runway Surface Type:</b>	Asphalt
<b>Runway Used:</b>	14	<b>Runway Surface Condition:</b>	Dry
<b>Runway Length/Width:</b>	5323 ft / 75 ft		

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 Fatal	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>	2 Fatal	<b>Aircraft Fire:</b>	On-Ground
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>			

## Administrative Information

Investigator In Charge (IIC): THOMAS H WILCOX      Adopted Date: 10/04/1996

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.