



National Transportation Safety Board Aviation Accident Final Report

Location:	GEORGETOWN, CA	Accident Number:	LAX96LA217
Date & Time:	06/01/1996, 0948 PDT	Registration:	N9332F
Aircraft:	Hughes 269B	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None

Flight Conducted Under: Part 91: General Aviation - Instructional

Analysis

During a dual instructional lesson, the CFI initiated a practice autorotation from 1,000 feet above ground level (agl) while in the traffic pattern. The CFI reported that as the helicopter descended through 800 feet agl, all engine power was suddenly lost and the practice maneuver turned into a forced landing. Just prior to experiencing the engine power loss, all instruments had been in the green. The CFI further stated that the helicopter touched down softly at the approach end of the runway with a forward speed between 2 and 3 miles per hour. Thereafter, the helicopter tipped forward, shook violently, and the main rotor blade contacted the airframe which resulted in substantial damage.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: loss of engine power for undetermined reason(s), while practicing an autorotation, which resulted in a forced landing; and the flight instructor's misjudged landing flare during the emergency autorotation/landing.

Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: APPROACH

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

2. AUTOROTATION - PERFORMED - PILOT IN COMMAND(CFI)

Occurrence #3: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (C) FLARE - MISJUDGED - PILOT IN COMMAND(CFI)

Factual Information

On June 1, 1996, at 0948 hours Pacific daylight time, the pilot of a Hughes 269B, N9332F, initiated a practice autorotation from 1,000 feet above ground level (agl) while in the traffic pattern at the Georgetown Airport, Georgetown, California. At the time, the certified flight instructor (CFI) was providing dual instruction to his student. The aircraft was substantially damaged and there were no injuries. The flight originated at 0920 from private property in Foresthill, California.

The CFI reported that as the helicopter descended through 800 feet agl, all engine power was suddenly lost and the practice maneuver turned into a forced landing. Just prior to experiencing the engine power loss, all instruments had been "in the green." The CFI further stated that the helicopter touched down softly at the approach end of the runway with a forward speed between 2 and 3 miles per hour. Thereafter, the helicopter tipped forward, shook violently, and the main rotor blade contacted the airframe which resulted in substantial damage.

Pilot Information

Certificate:	Flight Instructor; Commercial	Age:	25, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Helicopter	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	06/07/1995
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1433 hours (Total, all aircraft), 53 hours (Total, this make and model), 53 hours (Pilot In Command, all aircraft), 53 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hughes	Registration:	N9332F
Model/Series:	269B 269B	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	690039
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	06/01/1996, Annual	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	70 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3200 Hours	Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	HIO-360-A1A
Registered Owner:	RICK PATTERSON, INC.	Rated Power:	180 hp
Operator:	ERIK VANDAGRIFF	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	150 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24° C
Precipitation and Obscuration:			
Departure Point:	FORESTHILL, CA (Q61)	Type of Flight Plan Filed:	None
Destination:	, CA (Q61)	Type of Clearance:	None
Departure Time:	0920 PDT	Type of Airspace:	Class G

Airport Information

Airport:	GEORGETOWN (Q61)	Runway Surface Type:	Asphalt
Airport Elevation:	2623 ft	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	2980 ft / 60 ft	VFR Approach/Landing:	Simulated Forced Landing; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	WAYNE POLLACK	Report Date:	01/08/1997
Additional Participating Persons:			
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsbt.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).