



National Transportation Safety Board Aviation Accident Final Report

Location:	RIMROCK, WA	Accident Number:	SEA96LA108
Date & Time:	06/01/1996, 1500 PDT	Registration:	N2965N
Aircraft:	Cessna 120	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The pilot attempted to take off from a 2,471-foot-long rough turf runway. He reported that the takeoff attempt went normally until the airplane reached a speed of 40 to 45 MPH and that the airplane did not accelerate beyond that speed. Unable to accelerate or to get airborne by the point on the runway at which he was accustomed to doing so, the pilot aborted the takeoff and initiated braking. The tailwheel-equipped airplane nosed over onto its back about 200 feet short of the runway end. After the accident, an FAA inspector computed the airplane to be 32 pounds over maximum gross weight. The U.S. Government and Washington state airport directories indicated that the unattended airport was closed from October 1 through June 1. Density altitude at the airport was calculated to be 3,424 feet.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's delay in aborting the takeoff, and his excessive use of brakes while decelerating the airplane during the aborted takeoff. Factors relating to the accident were: the pilot's loading the airplane above its maximum gross weight, high density altitude, and the rough surface of the runway.

Findings

Occurrence #1: NOSE OVER

Phase of Operation: TAKEOFF - ABORTED

Findings

1. (F) AIRCRAFT WEIGHT AND BALANCE - EXCEEDED - PILOT IN COMMAND
2. (F) WEATHER CONDITION - HIGH DENSITY ALTITUDE
3. (C) ABORTED TAKEOFF - DELAYED - PILOT IN COMMAND
4. (C) BRAKES(NORMAL) - EXCESSIVE - PILOT IN COMMAND
5. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION - ROUGH/UNEVEN
6. AIRPORT/FACILITIES - CLOSED

Factual Information

On June 1, 1996, at approximately 1500 Pacific daylight time, a Cessna 120, N2965N, sustained substantial damage when it nosed over during an aborted takeoff at Tieton State Airport near Rimrock, Washington. The private pilot received a minor injury; his single passenger was uninjured. Visual meteorological conditions prevailed and no flight plan was filed for the 14 CFR 91 local flight.

The pilot was attempting to take off on runway 20, which according to the U.S. Government Airport/Facility Directory (A/FD) is a 2,471 by 140 foot turf runway with a rough surface. The airport elevation is 2,961 feet above sea level. The pilot reported that the takeoff proceeded normally until the airplane reached an indicated airspeed of 40 to 45 MPH, but that "after that the indicated airspeed didn't increase." He reported what happened during the rest of the accident sequence as follows:

After landing and taking off about 30 or 40 times from this strip, and in this airplane, over the last five or six years, I knew where I should be developing lift and able to get the mains off the rough ground and build airspeed in ground effect. This was not happening. Even though the airspeed indicator had not risen over about 40 or 45 I was still attempted [sic] to ease the yoke back and see if the airplane wanted to fly....The plane still did not want to lift into ground effect. Based on previous experience I should have had the plane developing lift before the camp ground [just beyond midfield according to a hand-drawn sketch furnished with the pilot's statement.] When I passed the camp ground, went a little further and still was not developing lift, I pulled all the power...and started applying the [brakes]. I eased back on the yoke lowering the tail to the ground and then continued to hold the yoke in my gut while applying brakes. As we slowed I applied more brakes....The tail rose and I saw the nose go down as we nosed over the front and came to rest upside down...approximately 200 [feet] from the end of the strip.

The pilot reported the weather at the airport as clear, 30 miles visibility, temperature 72 degrees F, and altimeter setting 30.80 inches Hg, with no precipitation or restrictions to visibility. He stated in his narrative that the wind sock at the top of the field "was hanging limp at the time I launched." Based on the reported temperature and altimeter setting and the field elevation, density altitude was computed by the investigator to be 3,424 feet.

The FAA investigator assigned to the accident, an operations air safety inspector from the Flight Standards District Office at Renton, Washington, furnished a post-accident weight and balance computation which indicated (based on weight and balance data in the aircraft records, and fuel and occupant loading reported by the pilot) that the aircraft's gross weight at the time of the accident was 32 pounds over its maximum gross weight (1,482 pounds actual versus 1,450 pounds maximum.)

The pilot made the following recommendations on his accident report as to how the accident could have been prevented: "(1) greater power (2) less weight (3) abort sooner (4) go easier on the brakes as airplane slows."

The A/FD and the Pilot's Guide to Washington Airports (published by the Washington State Department of Transportation Aeronautics Division, which also maintains the unattended airport) both indicate that Tieton State Airport is closed from October 1 through June 1. The A/FD contains an instruction to contact the state Aeronautics Division prior to use of the

airport.

Pilot Information

Certificate:	Private	Age:	38, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	05/05/1995
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	428 hours (Total, all aircraft), 300 hours (Total, this make and model), 329 hours (Pilot In Command, all aircraft), 8 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2965N
Model/Series:	120 120	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	13223
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	06/12/1995, Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	200 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3276 Hours	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	C-85-12F
Registered Owner:	YAKIMA 65N FLYING CLUB	Rated Power:	85 hp
Operator:	LYNN L. HARDEN	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	30 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	22° C
Precipitation and Obscuration:			
Departure Point:	(WA49)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1500 PDT	Type of Airspace:	Class G

Airport Information

Airport:	TIETON STATE (WA49)	Runway Surface Type:	Grass/turf
Airport Elevation:	2961 ft	Runway Surface Condition:	Rough
Runway Used:	20	IFR Approach:	None
Runway Length/Width:	2471 ft / 140 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	GREGG	NESEMEIER	Report Date:	04/03/1997
Additional Participating Persons:				
Publish Date:				
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .			

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).