



# National Transportation Safety Board

## Aviation Accident Data Summary

<b>Location:</b>	DAYTONA BEACH, FL	<b>Accident Number:</b>	MIA97LA054
<b>Date &amp; Time:</b>	01/01/1997, 1341 EST	<b>Registration:</b>	N5813G
<b>Aircraft:</b>	Cessna 150K	<b>Injuries:</b>	2 Serious
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

### Analysis

Before the first of several legs of flight, the pilot used a wooden stick to confirm the fuel quantity, since one of the fuel gauges was inoperative. He then departed, performed airwork, and continued to a landmark, where a flyby was performed. The pilot landed at an airport, remained a short time, then during the preflight, he noted that the fuel quantity indicated about 1/2. The flight departed, and the pilot flew to another airport, and performed a full stop landing with taxiback. He then departed on a return flight to the original departure airport, where he performed two touch-and-go landings. During the takeoff roll of the third touch-and-go, the pilot noted that the engine was not producing full power; however, with insufficient runway remaining to stop, he elected to continue. About 200 feet above ground level, the engine coughed, then the propeller stopped. Subsequently, the airplane collided with concrete blocks during a forced landing. The pilot stated to a police officer that he believed the engine quit because he ran out of fuel. Postcrash examination of the airplane by an FAA inspector revealed 3.0 gallons of fuel remaining in the fuel tanks. According to the airplane type certificate data sheet, the unusable fuel quantity was 3.5 gallons. Following recovery of the airplane, the engine was started, and it operated to 750 rpm. Impact damage precluded operating the engine to a higher rpm.

### Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's improper planning/decision, by failing to ensure there was sufficient fuel for continued flight, which resulted in fuel exhaustion and subsequent collision with objects (concrete blocks) during a forced landing. Factors relating to the accident were: a partially inoperative fuel gauge, which provided a false fuel indication, and the pilot's operation of the airplane with the known deficiency.

### Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: TAKEOFF

#### Findings

1. (C) PLANNING/DECISION - IMPROPER - PILOT IN COMMAND
2. (F) ENGINE INSTRUMENTS,FUEL QUANTITY GAGE - FALSE INDICATION
3. (F) OPERATION WITH KNOWN DEFICIENCIES IN EQUIPMENT - INTENTIONAL - PILOT IN COMMAND
4. (C) FLUID,FUEL - EXHAUSTION
5. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY LANDING AFTER TAKEOFF  
-----

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT  
Phase of Operation: EMERGENCY LANDING

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	23
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Instrument Rating(s):</b>	None
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	138 hours (Total, all aircraft), 3 hours (Total, this make and model), 87 hours (Pilot In Command, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N5813G
<b>Model/Series:</b>	150K 150K	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	WILLIAM BECK	<b>Engine Manufacturer:</b>	Continental
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	O-200-A
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	DAB, 35 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	None / 0 ft agl	<b>Wind Speed/Gusts, Direction:</b>	5 knots / , 100°
<b>Temperature:</b>	23° C	<b>Visibility</b>	10 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	(DAB)	<b>Destination:</b>	(DAB)

## Airport Information

<b>Airport:</b>	DAYTONA BEACH INT'L (DAB)	<b>Runway Surface Type:</b>	Asphalt
<b>Runway Used:</b>	7R	<b>Runway Surface Condition:</b>	Dry
<b>Runway Length/Width:</b>	3197 ft / 100 ft		

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Serious	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>			

## Administrative Information

Investigator In Charge (IIC): TIMOTHY W MONVILLE

Adopted Date: 09/30/1997

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.