



National Transportation Safety Board Aviation Accident Final Report

Location:	WESTPORT, OK	Accident Number:	FTW98LA085
Date & Time:	01/02/1998, 1640 CST	Registration:	N201LG
Aircraft:	Mooney M20J	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None

Flight Conducted Under: Part 91: General Aviation - Personal

Analysis

After an uneventful 50-minute cross-country flight, the pilot entered the landing pattern and observed the windsock indicating winds from 190 at 10-15 knots. After a normal downwind, base, and final approach, and about 160 yards down the runway, the aircraft was about to touch down when it started to veer to the left. The pilot attempted to stabilize directional control by applying right rudder and adding power. A gust of wind then 'lifted the right wing to a 20 degree' bank and turned the aircraft further to the left, which aligned the nose of the airplane toward some tree tops. Subsequently, the airplane impacted the trees, and settled to the ground, upright, and nose low. The pattern was flown with 1/2 flaps selected on base and full flaps on final. The pilot said that the winds at the accident site were from 190 degrees at 12 knots, gusting to 15 knots. Reported winds, 28 miles east of the accident site, were from 190 degrees at 16 knots, gusting to 25 knots. Inspection of the wind sock showed that it was functioning properly.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate compensation for the existing wind conditions. A factor was gusty winds.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

1. (F) WEATHER CONDITION - GUSTS
2. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

3. OBJECT - TREE(S)

Factual Information

On January 2, 1998, at 1640 central standard time, a Mooney M20J airplane, N201LG, registered to and operated by the pilot, collided with trees following a loss of control while landing on runway 21 at Keystone Airpark, Westport, Oklahoma. The aircraft was substantially damaged and the private pilot, the sole occupant, was not injured. No flight plan was filed and visual meteorological conditions prevailed for the Title 14 CFR Part 91 personal flight, which originated from Poteau, Oklahoma, at 1550.

In a written statement, the pilot reported that after an uneventful 50 minute cross country flight, he entered the landing pattern at Keystone and observed the windsock which indicated winds from 190 at 10 to 15 knots. He reported that, after a normal downwind, base, and final approach, he crossed the threshold and approximately 160 yards down the runway, the aircraft was about to touchdown when it started to veer to the left. The pilot attempted to stabilize directional control by applying right rudder and adding power. He stated that, a gust of wind then "lifted the right wing to a 20 degree" bank and turned the aircraft further to the left, which aligned the nose of the airplane toward some tree tops. Subsequently, the airplane impacted the trees, and settled to the ground, upright, and nose low.

Examination of the wreckage by an FAA inspector revealed that the fuselage and empennage were buckled, and the right wing was separated at the root.

The pilot flew the standard VFR pattern with 1/2 flaps selected on base and full flaps on final. He reported the winds at the accident site to be from 190 degrees at 12 knots, gusting to 15 knots. The reported winds at Tulsa, Oklahoma, located about 28 miles east of the accident site, were from 190 degrees at 16 knots, gusting to 25 knots. Inspection of the wind sock after the accident showed that it was intact and functioning properly. Examination of the aircraft by an FAA inspector after the accident did not reveal any preexisting control system anomalies that could have contributed to the accident. The pilot did not report any control problems with the aircraft during the flight.

Pilot Information

Certificate:	Private	Age:	61, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	08/28/1996
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	2505 hours (Total, all aircraft), 2100 hours (Total, this make and model), 2404 hours (Pilot In Command, all aircraft), 26 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N201LG
Model/Series:	M20J M20J	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	24-0460
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	12/23/1995, Annual	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:	259 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1723 Hours	Engine Manufacturer:	Lycoming
ELT:	Installed	Engine Model/Series:	IO-360-A3B6D
Registered Owner:	RICHARD L. MOORE	Rated Power:	200 hp
Operator:	RICHARD L. MOORE	Operating Certificate(s) Held:	None
Operator Does Business As:	N/A	Operator Designator Code:	N/A

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	TUL, 638 ft msl	Distance from Accident Site:	28 Nautical Miles
Observation Time:	1640 CST	Direction from Accident Site:	90°
Lowest Cloud Condition:	Scattered / 2500 ft agl	Visibility	10 Miles
Lowest Ceiling:	Overcast / 3200 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	16 knots / 25 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	16° C / 10° C
Precipitation and Obscuration:			
Departure Point:	POTEAU, OK (RKR)	Type of Flight Plan Filed:	None
Destination:	, OK (4F1)	Type of Clearance:	None
Departure Time:	1550 CST	Type of Airspace:	Class E

Airport Information

Airport:	KEYSTONE AIRPARK (NONE)	Runway Surface Type:	Asphalt
Airport Elevation:	980 ft	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	4000 ft / 55 ft	VFR Approach/Landing:	Full Stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ALEXANDER LEMISHKO	Report Date:	12/08/1998
Additional Participating Persons:	JERRY YATES; OKLAHOMA CITY, OK		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsbt.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).