



National Transportation Safety Board Aviation Accident Factual Report

Location:	INDEPENDENCE, OR	Accident Number:	SEA93LA146
Date & Time:	07/01/1993, 1755 PDT	Registration:	N6LG
Aircraft:	DOELLEFELD RV6A	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Fatal

Flight Conducted Under: Part 91: General Aviation - Personal

On July 1, 1993, at approximately 1755 Pacific daylight time(PDT), an experimental Doellefeld RV6A, N6LG, impacted the terrain about one-half mile from Independence Airport, Independence, Oregon. The FAA certificated private pilot, who was the sole occupant of the aircraft, received fatal injuries, and the aircraft was destroyed. The personal pleasure flight, which had departed the same location less than one minute earlier, was in visual meteorological conditions at the time of the accident. The aircraft was not on a filed flight plan, and there was no report of an ELT activation.

According to witnesses and family members, the aircraft, which had been built by the pilot, was on its second flight of the afternoon after receiving its FAA airworthiness inspection earlier that day. The first flight, which lasted about 25 minutes, was reported to have gone well with no significant problems with performance or controllability.

After the first flight, the pilot removed the cowling, checked the aircraft over for condition, and then rested for a while prior to the next flight.

At the beginning of the second flight, which took place about two hours after the first flight had terminated, the pilot taxied onto the runway, and announced over his radio that he was taking off. He started his takeoff roll to the north and then, according to witnesses, the aircraft veered suddenly to the left just prior to liftoff. As the aircraft departed the left side of the runway it became airborne, climbed steeply to about 400 feet above the ground (AGL), and then executed a steep left turn. The aircraft's left turn brought it to a position near the downwind, where it continued in a southerly direction. After flying about two-thirds of the length of the runway, the aircraft banked to the left and descended toward the ground with what appeared to witnesses to be an accelerating airspeed. Just before it impacted the terrain, the aircraft was seen to roll rapidly to near 90 degrees of bank. According to the FAA, impact scars and wreckage distribution show that it impacted the ground right wing down at a pitch angle of greater than 45 degrees nose down. The witnesses said that the aircraft then seemed to cartwheel, ending up inverted, and burst into flames as it slid approximately 300 feet through a field off the south end of the airport.

During the time that the aircraft was airborne, the witnesses did not notice any of the precise and distinct flight control movements that had been observed during the earlier flight. Instead, according to the witnesses, it appeared that the aircraft was not under complete positive control as it climbed, and then descended into the ground. Witnesses on the ground, and also in a chase aircraft in the air, reported that from the time the aircraft lifted off until it impacted the ground, they saw no movement from the pilot of the RV6. The pilot of a chase plane, who had radio contact with the RV6A pilot prior to the takeoff, also said that he did not receive any response when he attempted several times to communicate with the RV6A pilot after the aircraft lifted off.

A forensic toxicology examination, which was completed by the FAA Toxicology and Accident Research Laboratory, did not detect any Carboxyhemoglobin, Cyanide or Ethanol in the specimens. A positive indication of 15.900 (ug/ml, ug/g) Salicylate was detected in the urine.

An inspection of the wreckage by the FAA, with assistance from the designer of the prototype aircraft, did not reveal any pre- impact malfunctions, anomalies or manufacturing defects. A pair of locking pliers were found in the wreckage of the fuselage, but there was no evidence, either on the pliers or the airframe, which indicated that these had in any way interfered with the control of the aircraft.

Pilot Information

Certificate:	Private	Age:	71, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	04/20/1992
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	1350 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	DOELLEFELD	Registration:	N6LG
Model/Series:	RV6A RV6A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental	Serial Number:	9131946
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	07/01/1993, Annual	Certified Max Gross Wt.:	1600 lbs
Time Since Last Inspection:	1 Hours	Engines:	1 Reciprocating
Airframe Total Time:	1 Hours	Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	O-320-D
Registered Owner:	DOELLEFELD, GERHARD E	Rated Power:	150 hp
Operator:	DOELLEFELD, GERHARD E	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 4000 ft agl	Visibility	30 Miles
Lowest Ceiling:	Broken / 11000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22° C / 11° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1830 PDT	Type of Airspace:	Class G

Airport Information

Airport:	INDEPENDENCE AIRPORT (7S5)	Runway Surface Type:	Asphalt
Airport Elevation:	175 ft	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	3070 ft / 60 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	On-Ground
Total Injuries:	1 Fatal	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ORRIN K ANDERSON
Additional Participating Persons:	JOE INKS; HILLSBORO, OR
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .