



## National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	PARKMAN, WY	<b>Accident Number:</b>	DEN99LA092
<b>Date &amp; Time:</b>	06/01/1999, 1100 MDT	<b>Registration:</b>	N7052L
<b>Aircraft:</b>	Hughes 269A	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Minor

**Flight Conducted Under:** Part 91: General Aviation - Personal

---

On June 1, 1999, approximately 1100 mountain daylight time, a Hughes 269A helicopter, N7052L, owned and operated by the pilot, was substantially damaged after colliding with terrain during initial climb following takeoff from a field near Parkman, Wyoming. The airline transport rated pilot, the sole occupant aboard, sustained minor injuries. The aircraft was being operated under Title 14 CFR Part 91, and no flight plan had been filed for the flight to Laurel, Montana. Visual meteorological conditions prevailed.

According to the pilot, he departed Laurel at 0900 to check out a camp in the Bighorn National Forest. He stated that he was concerned with the aircraft's performance, but had flown at similar altitudes with cooler temperatures. With his passenger aboard, he performed an out of ground effect hover at 60 feet above ground level (agl). The field's elevation was 7,200 mean sea level (msl). He stated that the aircraft hovered with maximum available power at 2,900 rpm. He entered forward flight and attempted to land in an open field at an elevation of 6,200 feet msl. He aborted his first landing due to downdrafts, and his second attempt was successful.

During departure from the field, he elected to perform a practice takeoff without his passenger to test the aircraft's performance. The helicopter flew normally after effective translational lift (ETL) was achieved, and he climbed out at  $V_y$  (40 knots), the aircraft's best rate of climb speed. Shortly after clearing a 75-foot ridge 100 to 150 yards from the takeoff field just after coming out of ground effect, the aircraft encountered a downdraft and subsequently began to lose altitude. The power required for the helicopter to climb was greater than the power available. The pilot banked the aircraft to the right to avoid two tall trees. The helicopter impacted the ground through 60 to 80 feet of trees, and came to rest in an inverted position. The pilot stated that there were no mechanical problems, and that the engine was running on impact.

The pilot performed an upwind takeoff, and the wind was from 045 degrees at 5 knots, gusting to 15 knots. Density altitude at the time of the accident was calculated to be 7,578 feet. According to calculated weight and performance data, the gross weight of the aircraft at the time of departure was approximately 1,232 lbs. With a maximum takeoff of 2,900 rpm, the maximum available horsepower was 132, and a maximum manifold pressure of 22.2 inches Hg.

At an indicated airspeed of 35 knots, the maximum obstacle clearance height was calculated to be 75 feet, with a maximum distance of 800 feet.

## Pilot Information

<b>Certificate:</b>	Airline Transport; Flight Instructor; Commercial	<b>Age:</b>	44, Male
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land; Single-engine Sea	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane Multi-engine; Airplane Single-engine; Helicopter; Instrument Airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim.	<b>Last FAA Medical Exam:</b>	02/12/1999
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	12600 hours (Total, all aircraft), 200 hours (Total, this make and model), 11750 hours (Pilot In Command, all aircraft), 100 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Hughes	<b>Registration:</b>	N7052L
<b>Model/Series:</b>	269A 269A	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	No
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	980962
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	100 Hour	<b>Certified Max Gross Wt.:</b>	1670 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	HIO-360-B1A
<b>Registered Owner:</b>	KENT W. POTTER	<b>Rated Power:</b>	180 hp
<b>Operator:</b>	KENT W. POTTER	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 5000 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots / 15 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	45°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	13° C
Precipitation and Obscuration:			
Departure Point:	(NONE)	Type of Flight Plan Filed:	None
Destination:	LAUREL, MT (6S8)	Type of Clearance:	None
Departure Time:	1055 MDT	Type of Airspace:	Class G

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

## Administrative Information

Investigator In Charge (IIC):	B. BEACH SCOTT
Additional Participating Persons:	OWEN R JONES; CASPER, WY
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .