



National Transportation Safety Board Aviation Accident Data Summary

Location:	STITES, ID	Accident Number:	SEA00TA013
Date & Time:	11/02/1999, 1118 PST	Registration:	N5388V
Aircraft:	Hiller UH-12E	Injuries:	2 Serious, 1 None
Flight Conducted Under:	Public Aircraft		

Analysis

During a low-altitude fish survey, the helicopter experienced a separation of a control rotor while leveling off from a climb to about 400 feet above ground level (AGL). The pilot initiated an emergency descent but, due to severely reduced cyclic controllability resulting from the separation, was unable to avoid power lines in the aircraft's emergency descent flight path. The helicopter struck the power lines about 50 feet AGL and fell to the ground, landing hard but upright. Post-accident examination disclosed a fatigue failure in the cuff which retains the control rotor blade. The fatigue originated on two opposite sides of a retaining bolt hole that appeared to have been unevenly hand chamfered or deburred during original manufacture of the cuff, with gouging and sharp-bottomed dents visible at the origins. However, while a company mechanic had signed off an Airworthiness Directive (AD) requiring recurring inspection of the cuff about two months/56 flight hours before the accident, post-accident examination disclosed evidence indicative of inadequate inspection and maintenance of the assembly, including: old dried grease between the cuff and control rotor blade spar, large areas of the spar missing required paint with associated corrosion areas, and zinc chromate primer in corrosion pits. The FAA-approved Hiller service bulletin referenced by the AD contains procedures for inspection of spar tube retention bolt holes for 'elongation, corrosion, burrs, pitting or fretting' and associated repair procedures, but does not contain any instructions to inspect or repair bolt holes in the control rotor cuff for those same conditions.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: Inadequate inspection of the control rotor cuff by a company mechanic and subsequent fatigue fracture of the cuff, resulting in an inflight separation of the control rotor blade. Factors contributing to the accident were: inadequate quality control during manufacture; insufficiently defined manufacturer's inspection and repair procedures; inadequate FAA approval of the manufacturer's inspection and repair procedures; power lines in the helicopter's emergency descent flight path; and reduced aircraft controllability following the control rotor separation.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: CLIMB - TO CRUISE

Findings

1. (C) ROTOR SYSTEM,MAIN ROTOR BLADE CUFF - FATIGUE
2. (C) MAINTENANCE,INSPECTION - INADEQUATE - COMPANY MAINTENANCE PERSONNEL
3. (F) INADEQUATE QUALITY CONTROL - MANUFACTURER
4. (F) CONDITION(S)/STEP(S) INSUFFICIENTLY DEFINED - MANUFACTURER

- 5. (F) INADEQUATE CERTIFICATION/APPROVAL,AIRCRAFT - FAA(ORGANIZATION)
- 6. ROTOR SYSTEM,MAIN ROTOR BLADE - SEPARATION

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT
Phase of Operation: DESCENT - EMERGENCY

Findings

- 7. (F) OBJECT - WIRE,TRANSMISSION
- 8. (F) AIRCRAFT CONTROL - REDUCED
- 9. CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Pilot Information

Certificate:	Commercial	Age:	63
Airplane Rating(s):	Single-engine Land	Instrument Rating(s):	Airplane; Helicopter
Other Aircraft Rating(s):	Helicopter	Instructor Rating(s):	None
Flight Time:	32275 hours (Total, all aircraft), 22000 hours (Total, this make and model), 228 hours (Last 90 days, all aircraft), 87 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Hiller	Registration:	N5388V
Model/Series:	UH-12E UH-12E	Engines:	1 Reciprocating
Operator:	JAMES R. POPE	Engine Manufacturer:	Lycoming
Operating Certificate(s) Held:	On-demand Air Taxi (135)	Engine Model/Series:	VO-540-C2A
Flight Conducted Under:	Public Aircraft		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Weather Information Source:	Pilot
Lowest Ceiling:	None / 0 ft agl	Wind Speed/Gusts, Direction:	Calm / ,
Temperature:	18° C	Visibility	50 Miles
Precipitation and Obscuration:			
Departure Point:	CLARKSTON, WA	Destination:	GRANGEVILLE, ID

Wreckage and Impact Information

Crew Injuries:	2 Serious, 1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude, Longitude:			

Administrative Information

Investigator In Charge (IIC):	GREGG NESEMEIER	Adopted Date:	05/16/2001
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.