



National Transportation Safety Board Aviation Incident Factual Report

Location:	BIRMINGHAM, AL	Incident Number:	ATL011A001
Date & Time:	10/01/2000, 1618 CDT	Registration:	N69826
Aircraft:	McDonnell Douglas MD-80	Aircraft Damage:	Minor
Defining Event:		Injuries:	1 Minor, 146 None
Flight Conducted Under:	Part 121: Air Carrier - Scheduled		

On October 1, 2000, central daylight time, a McDonnell Douglas MD-80, N69826, operated by Continental Airlines as Flight 1579, experienced an electrical fire during cruise flight at flight level 310 near Birmingham, Alabama. Flight 1579 was operated under the provisions of Title 14 CFR Part 121 as a scheduled domestic passenger flight from Atlanta, Georgia, to Houston, Texas. The flight departed Hartsfield International Airport in Atlanta, Georgia, at approximately 1720 eastern daylight time with two air transport pilots, one jump-seat rider, three flight attendants, and 141 passengers on board. The airplane sustained minor damage and the jump-seat rider received minor injuries; there were no other injuries reported. Visual weather conditions prevailed at the time of the incident, and Flight 1579 operated on an instrument flight rules flight plan.

According to the pilot, approximately 15 minutes into the flight, the cockpit filled with smoke and he heard a loud popping sound and saw sparks emitting from the jump seat area. The jump seat rider reported that he heard an explosion and leaned forward to avoid heat, which he felt on his left shoulder. When the jump seat rider looked at his left shoulder, he noticed that his shirt was burning. He extinguished the fire on his shirt, and put on his oxygen mask, since the cockpit was filled with smoke. The pilot declared an emergency and initiated a descending right turn. The flight diverted into Birmingham, Alabama, and landed without further incident.

According to the Continental Fleet Campaign Directive, (FCD), the registration certificate holder was modified on September 28, 2000. The FCD called for the holder to be modified in order to prevent loss of the certificate or damage of the certificate that would preclude dispatch of the airplane. The FCD required maintenance personnel to drill two small pilot holes just above the top of the certificate, and, in the case of mounting on a metal wall, install two screws into the pilot holes. A note is included on the FCD that allows alternate length screws to be used as required.

The examination of the airplane disclosed a 2 by 1 1/2 inch fire-damaged hole in the left jump seat wall. Several heavy gauge electrical wires were welded together on the opposite side of the wall. There were also four 50-ampere circuit breakers popped on the left circuit breaker

panel behind the pilot's seat. The hole also included an area of the left edge of the registration certificate holder. The plastic cover of the registration certificate holder was melted in this area and soot damage was evident for several inches around the hole. The registration certificate holder was attached to the wall by 8 screws that extended into the cavity where the electrical fire occurred. The hole appeared to be on the left side, middle position of the certificate holder. This screw was missing; all of the seven other screws were present. The screws immediately above and below this middle position on the left side extended is approximately 0.5 inches into the cavity where the electrical fire occurred. The missing segments of wire were aligned with the center of the hole in the wall, and also with the position of the middle screw. At the point of the missing wire segments, a screw similar to that placed above and below the missing middle screw could have extended into the wiring. There is no mention in the FCD of steps that should be taken to insure that no damage is done to items on the other side of the wall either during the drilling process or by the screws themselves once they are inserted into the holes.

Corrective actions that Continental Airlines have taken are to remove all certificate holders that are on the EPC wall and to install a new 3-slot certificate holder on the galley wall, which has a honeycomb backing. According to the Engineering Authorization, the best location for the certificate holder approximately 32.5 inches from the floor, 3 inches below the lowest coat hook, and 4.5 inches in from the cockpit door.

Pilot Information

Certificate:	Airline Transport	Age:	52, Male
Airplane Rating(s):	Multi-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	05/03/2000
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	McDonnell Douglas	Registration:	N69826
Model/Series:	MD-80 MD-80	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Transport	Serial Number:	MD-80-82
Landing Gear Type:		Seats:	172
Date/Type of Last Inspection:	09/06/2000, Continuous Airworthiness	Certified Max Gross Wt.:	149500 lbs
Time Since Last Inspection:		Engines:	2 Turbo Jet
Airframe Total Time:	39417 Hours	Engine Manufacturer:	P&W
ELT:		Engine Model/Series:	JT8D
Registered Owner:	FIRST SECURITY BANK NA TRUSTEE	Rated Power:	7700 hp
Operator:	CONTINENTAL AIRLINES	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	CO

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	BHM, 644 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1453 CDT	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 8000 ft agl	Visibility	10 Miles
Lowest Ceiling:	Broken / 20000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	29° C / 11° C
Precipitation and Obscuration:			
Departure Point:	ATLANTA, GA (ATL)	Type of Flight Plan Filed:	IFR
Destination:	HOUSTON, TX (IAH)	Type of Clearance:	
Departure Time:	0000	Type of Airspace:	Class C

Airport Information

Airport:	BIRMINGHAM AIRPORT (BHM)	Runway Surface Type:	Asphalt
Airport Elevation:	644 ft	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 Minor, 5 None	Aircraft Damage:	Minor
Passenger Injuries:	141 None	Aircraft Fire:	In-Flight
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 146 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	PHILLIP POWELL
Additional Participating Persons:	RONALD P BLITZ SCOTT WARREN; WASHINGTON, DC,
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .