



National Transportation Safety Board Aviation Incident Final Report

Location:	MINNEAPOLIS, MN	Incident Number:	CHI89IA083
Date & Time:	05/02/1989, 1440 CDT	Registration:	N434AA
Aircraft:	MCDONNELL DOUGLAS DC-9-82	Aircraft Damage:	Minor
Defining Event:		Injuries:	96 None

Flight Conducted Under: Part 121: Air Carrier - Scheduled

Analysis

THE FLIGHT CREW REPORTED THAT WHILE IN CRUISE FLIGHT AT 33,000 FEET, THEY EXPERIENCED A HYDRAULIC SYSTEM FAILURE. THEY MANUALLY EXTENDED THE LANDING GEAR FOR LANDING AND MADE AN UNEVENTFUL NO FLAPS/NO SLATS LANDING. POST-ACCIDENT INVESTIGATION REVEALED THAT THE LOSS OF HYDRAULIC PRESSURE IN BOTH SYSTEMS WAS DUE TO THE FAILURE OF PTU S/O VALVE BODY ATTACH SCREWS ON THE LEFT SYSTEM VALVE. THIS ALLOWED THE LEFT VALVE BODY TO SEPERATE FROM THE REMAINING ASSEMBLY, PORTING LEFT SYSTEM HYDRAULIC FLUID OVERBOARD, AND SUBSEQUENTLY DEPRESSURIZING THE RIGHT SYSTEM (ALTHOUGH THERE WAS NO LOSS OF RIGHT SYSTEM HYDRAULIC FLUID). THE MANUFACTURER HAD A RE-DESIGNED, STRONGER UNIT AVAILABLE TO OPERATORS; THIS IMPROVED UNIT HAD STRONGER VALVE BODY ATTACH SCREWS, WELDED VALVE BODIES, STEEL GEARS, AND A SHEAR PIN IN THE MOTOR-TO-VALVE GEAR TRAIN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be: FAILURE OF THE HYDRAULIC POWER TRANSFER UNIT SHUT-OFF (PTU S/O) VALVE DUE TO FAILED (FATIGUED) VALVE BODY ATTACH SCREWS.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: CRUISE - NORMAL

Findings

1. (C) HYDRAULIC SYSTEM,SHUTOFF VALVE - FAILURE,TOTAL
2. (C) HYDRAULIC SYSTEM - NO PRESSURE

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. (C) TERRAIN CONDITION - RUNWAY
4. (C) HYDRAULIC SYSTEM - UNAVAILABLE

Factual Information

Pilot Information

Certificate:	Airline Transport	Age:	39, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	12/12/1988
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	7450 hours (Total, all aircraft), 150 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MCDONNELL DOUGLAS	Registration:	N434AA
Model/Series:	DC-9-82 DC-9-82	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Transport	Serial Number:	49452
Landing Gear Type:	Retractable - Tricycle	Seats:	172
Date/Type of Last Inspection:	Continuous Airworthiness	Certified Max Gross Wt.:	140000 lbs
Time Since Last Inspection:		Engines:	2 Turbo Fan
Airframe Total Time:		Engine Manufacturer:	P&W
ELT:	Installed, not activated	Engine Model/Series:	JT8D-217A
Registered Owner:	AMERICAN AIRLINES	Rated Power:	14500 lbs
Operator:	AMERICAN AIRLINES	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	AALA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	MSP, 841 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1500 CDT	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	20 Miles
Lowest Ceiling:	Broken / 7000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	290°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	13° C / -3° C
Precipitation and Obscuration:			
Departure Point:	SEATTLE, WA (SEA)	Type of Flight Plan Filed:	IFR
Destination:	CHICAGO, IL (ORD)	Type of Clearance:	IFR
Departure Time:	0940 PDT	Type of Airspace:	Class E

Airport Information

Airport:	MINNEAPOLIS ST PAUL INTL (MSP)	Runway Surface Type:	Asphalt; Concrete
Airport Elevation:	841 ft	Runway Surface Condition:	Dry
Runway Used:	29L	IFR Approach:	
Runway Length/Width:	10000 ft / 200 ft	VFR Approach/Landing:	Full Stop

Wreckage and Impact Information

Crew Injuries:	6 None	Aircraft Damage:	Minor
Passenger Injuries:	90 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	96 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	JODI L REEVES	Report Date:	08/26/1992
Additional Participating Persons:	G. PHILLIPS; WASHINGTON, DC J. MEYER; MINNEAPOLIS, MN B. BUDOVEC; LONG BEACH, CA B. RICHARDS; TULSA, OK		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinquiry@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).