



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	SAINT PAUL, MN	<b>Accident Number:</b>	MKC90LA021
<b>Date &amp; Time:</b>	11/02/1989, 0436 CST	<b>Registration:</b>	N3174S
<b>Aircraft:</b>	BELL 206L-3	<b>Injuries:</b>	3 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Positioning - Air Medical (Unspecified)		

## Analysis

DRG AN EMERGENCY MEDICAL SVC (EMS/MEDEVAC) FLT, THE PLT ENCTRD STRONGER HEADWINDS THAN EXPECTED. AFTER DELIVERING A PATIENT, HE ESTIMATED 12 MIN OF FUEL WAS REMAINING. SINCE THE FLT TO HIS HOME BASE WOULD TAKE ABOUT 6 MIN, HE ELECTED TO RETURN WITHOUT REFUELING. WHILE ARRIVING ABEAM OF HIS DESTN, A FUEL BOOST PUMP LIGHT ILLUMINATED. THE PLT SAID HE EXPEDITED HIS APCH, BUT AT ABOUT 50' AGL, A 2ND BOOST PUMP LIGHT ILLUMINATED. THE ENG THEN LOST POWER FROM FUEL EXHAUSTION. SUBSEQUENTLY, THE HELICOPTER WAS DAMAGED DRG AN EMERGENCY AUTOROTATION (AT NIGHT).

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER PLANNING/DECISION BY THE PILOT, WHICH RESULTED IN FUEL EXHAUSTION DUE TO AN INADEQUATE SUPPLY OF FUEL. DARKNESS WAS A RELATED FACTOR.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL  
Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

### Findings

1. (C) PLANNING/DECISION - IMPROPER - PILOT IN COMMAND
2. (C) FLUID,FUEL - EXHAUSTION
3. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING  
Phase of Operation: DESCENT - EMERGENCY

### Findings

4. AUTOROTATION

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER  
Phase of Operation: LANDING - FLARE/TOUCHDOWN

### Findings

5. (F) LIGHT CONDITION - DARK NIGHT

## Pilot Information

<b>Certificate:</b>	Airline Transport; Flight Instructor; Commercial	<b>Age:</b>	40
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land; Single-engine Sea	<b>Instrument Rating(s):</b>	Airplane; Helicopter
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Instructor Rating(s):</b>	
<b>Flight Time:</b>	4436 hours (Total, all aircraft), 1435 hours (Total, this make and model), 4063 hours (Pilot In Command, all aircraft), 74 hours (Last 90 days, all aircraft), 26 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	BELL	<b>Registration:</b>	N3174S
<b>Model/Series:</b>	206L-3 206L-3	<b>Engines:</b>	1 Turbo Shaft
<b>Operator:</b>	AIR METHODS, INC.	<b>Engine Manufacturer:</b>	ALLISON
<b>Operating Certificate(s) Held:</b>	On-demand Air Taxi (135)	<b>Engine Model/Series:</b>	250-C30B
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Positioning - Air Medical (Unspecified)		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Night/Dark
<b>Observation Facility, Elevation:</b>	MSP, 841 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	Overcast / 1100 ft agl	<b>Wind Speed/Gusts, Direction:</b>	4 knots / , 300°
<b>Temperature:</b>	-2° C	<b>Visibility</b>	4 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	MINNEAPOLIS, MN (MY65)	<b>Destination:</b>	

## Airport Information

<b>Airport:</b>	HOLMAN FLD (STP)	<b>Runway Surface Type:</b>	Asphalt
<b>Runway Used:</b>	27	<b>Runway Surface Condition:</b>	Dry
<b>Runway Length/Width:</b>	200 ft / 300 ft		

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	2 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>			

## Administrative Information

Investigator In Charge (IIC): JOHN R HRUBAN Adopted Date: 04/13/1992

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.