



National Transportation Safety Board Aviation Accident Data Summary

Location:	HIGH ISL BLK595, GM	Accident Number:	FTW84FA216
Date & Time:	05/01/1984, 1400 CDT	Registration:	N763AL
Aircraft:	SIKORSKY S-76A	Injuries:	2 None
Flight Conducted Under:	Part 135: Air Taxi & Commuter - Non-scheduled		

Analysis

DURING CRUISE FLIGHT AT 500 FT OVER GULF WATERS, THE LEFT ENGINE SUSTAINED A MASSIVE, UNCONTAINED, EXPLOSIVE FAILURE. SHARPNEL PENETRATED THE RIGHT ENGINE, WHICH FAILED FROM DAMAGE. SHARPNEL ALSO PENETRATED THE AC AND DC JUNCTION BOXES, CAUSING COMPLETE ELECTRICAL FAILURE (NO MAYDAY CALL POSSIBLE). SHARPNEL FURTHER SEVERED THE TAIL ROTOR DRIVE SHAFT AND PENETRATED THE ACFT FUEL SYSTEM; FIRE BROKE OUT IN THE TRANSMISSION AREA AND THE COCKPIT FILLED WITH SMOKE. USING THE CO-PLT'S SIDE WINDOW FOR VISUAL ACQUISITION OF THE WATER SURFACE, A SUCCESSFUL AUTOROTATION WAS PERFORMED. HOWEVER, THE ACFT ROLLED OVER AND SANK SINCE THE EMERGENCY FLOATATION GEAR IS ELECTRICALLY OPERATED AND FAILED TO DEPLOY. AFTER SUCCESSFUL EVACUATION BY ALL OCCUPANTS, PLT RETURNED TO THE INVERTED ACFT AND DEPLOYED LIFE RAFTS. INVESTIGATION REVEALED LEFT ENGINE COMPRESSOR-TO-TURBINE COUPLING HAD FAILED IN FATIGUE. TURBINE WENT OVERSPEED AND BURST UNDER CENTRIFUGAL LOADS.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - MECH FAILURE/MALF
Phase of Operation: CRUISE - NORMAL

Findings

1. (C) TURBINE ASSEMBLY,SHAFT - FATIGUE
 2. TURBINE ASSEMBLY,TURBINE WHEEL - OVERSPEED
 3. TURBINE ASSEMBLY,TURBINE WHEEL - BURST
-

Occurrence #2: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION
Phase of Operation: CRUISE

Findings

4. (F) ELECTRICAL SYSTEM - DISABLED
 5. (F) FUEL SYSTEM - FIRE
 6. (F) ROTOR DRIVE SYSTEM,TAIL ROTOR DRIVE SHAFT - SEPARATION
-

Occurrence #3: FORCED LANDING
Phase of Operation: DESCENT - EMERGENCY

Findings
7. FUSELAGE, CREW COMPARTMENT - SMOKE

Occurrence #4: ROLL OVER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
8. TERRAIN CONDITION - WATER, ROUGH
9. AUTOROTATION - PERFORMED - PILOT IN COMMAND
10. (F) MISC ROTORCRAFT, EMERGENCY FLOATATION GEAR - DISABLED

Pilot Information

Certificate:	Airline Transport	Age:	37
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Instrument Rating(s):	Airplane; Helicopter
Other Aircraft Rating(s):	Helicopter	Instructor Rating(s):	None
Flight Time:	5092 hours (Total, all aircraft), 348 hours (Total, this make and model), 3839 hours (Pilot In Command, all aircraft), 53 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	SIKORSKY	Registration:	N763AL
Model/Series:	S-76A S-76A	Engines:	2 Turbo Shaft
Operator:	AIR LOGISTIC INC.	Engine Manufacturer:	ALLISON
Operating Certificate(s) Held:	On-demand Air Taxi (135)	Engine Model/Series:	250-C30S
Flight Conducted Under:	Part 135: Air Taxi & Commuter - Non-scheduled		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Weather Information Source:	Pilot
Lowest Ceiling:	None / 0 ft agl	Wind Speed/Gusts, Direction:	6 knots / , 11°
Temperature:	23° C	Visibility	5 Miles
Precipitation and Obscuration:			
Departure Point:	HI ISL BLK 595, GM	Destination:	FREEMPORT, TX

Airport Information

Airport:		Runway Surface Type:	
Runway Used:	0	Runway Surface Condition:	
Runway Length/Width:			

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	In-Flight

Latitude, Longitude:

Administrative Information

Investigator In Charge (IIC):	ARMOND V EDWARDS	Adopted Date:	
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.