



National Transportation Safety Board Aviation Accident Final Report

Location:	MEADVILLE, PA	Accident Number:	NYC83FA016
Date & Time:	11/01/1982, 0900 EST	Registration:	N402DL
Aircraft:	CESSNA 402B	Aircraft Damage:	Substantial
Defining Event:		Injuries:	3 None
Flight Conducted Under:	Part 135: Air Taxi & Commuter - Non-scheduled		

Analysis

THE PILOT APPROACHED HIGH AND FAST FOR LANDING ON RUNWAY 4. THE WIND WAS FROM 240 DEG AT 10 TO 12 KTS. THE AIRCRAFT FLOATED AND AFTER TOUCHDOWN, THE PILOT WAS UNABLE TO STOP ON THE WET, DOWNSLOPING RUNWAY. AFTER DEPARTING THE RUNWAY, THE AIRCRAFT CONTINUED DOWN A STEEPER SLOPE AND INTO AN AREA OF BRUSH AND TREES. ALL THREE GEAR COLLAPSED, THERE WAS LEADING EDGE SPAR DAMAGE ON BOTH WINGS, AND THE RIGHT SIDE FUSELAGE SKIN, FORWARD OF THE RIGHT WING, WAS DAMAGED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - TAILWIND
 2. (F) WRONG RUNWAY - SELECTED - PILOT IN COMMAND
 3. (C) DISTANCE - MISJUDGED - PILOT IN COMMAND
 4. (C) AIRSPEED - MISJUDGED - PILOT IN COMMAND
 5. (C) GO-AROUND - NOT PERFORMED - PILOT IN COMMAND
 6. (F) AIRPORT FACILITIES,RUNWAY/LANDING AREA CONDITION - DOWNHILL
 7. (F) AIRPORT FACILITIES,RUNWAY/LANDING AREA CONDITION - WET
 8. (F) AIRCRAFT PERFORMANCE,HYDROPLANING CONDITION - WATER
-

Occurrence #2: COMPLETE GEAR COLLAPSED

Phase of Operation: LANDING - ROLL

Findings

9. (F) TERRAIN CONDITION - DOWNHILL
 10. (F) TERRAIN CONDITION - HIGH VEGETATION
 11. LANDING GEAR - OVERLOAD
-

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings

12. (F) OBJECT - TREE(S)

Factual Information

Pilot Information

Certificate:	Airline Transport	Age:	32, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Single-engine; Instrument Airplane	Toxicology Performed:	
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	09/17/1982
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	5500 hours (Total, all aircraft), 400 hours (Total, this make and model), 4700 hours (Pilot In Command, all aircraft), 165 hours (Last 90 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N402DL
Model/Series:	402B 402B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:		Serial Number:	402 B0598
Landing Gear Type:	Retractable - Tricycle	Seats:	7
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	6300 lbs
Time Since Last Inspection:	42 Hours	Engines:	2 Reciprocating
Airframe Total Time:	2592 Hours	Engine Manufacturer:	CONTINENTAL
ELT:	Installed	Engine Model/Series:	TSIO-520
Registered Owner:	DARNE, INC.	Rated Power:	300 hp
Operator:	DARNE, INC.	Operating Certificate(s) Held:	On-demand Air Taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Unknown / 0 ft agl	Visibility	4 Miles
Lowest Ceiling:	Overcast / 1000 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	/ 0°C
Precipitation and Obscuration:			
Departure Point:	ALLENTOWN, PA	Type of Flight Plan Filed:	IFR
Destination:	DALLAS, TX (DAL)	Type of Clearance:	
Departure Time:	0725	Type of Airspace:	

Airport Information

Airport:	PORT MEADVILLE	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft	Runway Surface Condition:	Wet
Runway Used:	4	IFR Approach:	Localizer Only
Runway Length/Width:	3050 ft / 100 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Report Date:	11/01/1983
Additional Participating Persons:		
Publish Date:		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .	

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).