



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	New Braunfels, TX	<b>Accident Number:</b>	FTW03LA034
<b>Date &amp; Time:</b>	11/01/2002, 1550 CST	<b>Registration:</b>	N77UA
<b>Aircraft:</b>	Rockwell 690B	<b>Injuries:</b>	3 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Executive/Corporate		

## Analysis

The gear in transient light remained illuminated during the initial climb. After recycling the gear and observing the light was still on, the pilot visually checked to ensure that the gear was retracted. After leveling off at 16,000 feet the pilot noticed the ball was not centered and added rudder trim to compensate. Two minutes later the airplane began to yaw and shake violently, followed by an uncommanded roll to the left of about 70 degrees with about a 10 to 15 degree pitch down attitude. The pilot manually disconnected the autopilot and reduced power. After losing 1,000 feet, control of the airplane was regained. Power was added and the airplane climbed back to 16,000 feet. After leveling off the pilot tentatively put pressure on each flight control to assess the problem and stability of the airplane. No adverse reactions to control inputs were noted, with the exception of a slight buffet approaching 200 to 210 knots. Power was then reduced to maintain a cruise speed below 200 knots. During the descent the airplane was slipping badly and the ball was all the way to the right, but the pilot was able to compensate with roll input. After a normal landing the pilot noticed the rudder horn and approximately 18 inches of the trailing rudder had separated from the aircraft. The rear of the fuselage was wrinkled on both sides of the horizontal stabilizer, and the vertical stabilizer was wrinkled. The forward one-half of the left nose gear door was bent aft approximately 90 degrees. A subsequent search for the missing top 18 inches of the trailing rudder proved unsuccessful. The top 24 inches of the remaining rudder was sectioned and sent to the NTSB Materials Laboratory Division, Washington, D.C., for examination. The Senior Metallurgist noted that the fracture surfaces observed were consistent with overstress separations. No evidence of pre-existing damage such as corrosion or fatigue was found.

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:  
The in-flight separation of the top of the rudder assembly for undetermined reasons.

## Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION  
Phase of Operation: CRUISE - NORMAL

### Findings

1. FLIGHT CONTROL, RUDDER - SEPARATION

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	52
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land	<b>Instrument Rating(s):</b>	Airplane; Helicopter
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	10485 hours (Total, all aircraft), 4425 hours (Total, this make and model), 10300 hours (Pilot In Command, all aircraft)		

## Co-Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	43
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land	<b>Instrument Rating(s):</b>	Airplane
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	
<b>Flight Time:</b>	6315 hours (Total, all aircraft), 246 hours (Total, this make and model), 5500 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Rockwell	<b>Registration:</b>	N77UA
<b>Model/Series:</b>	690B	<b>Engines:</b>	2 Turbo Prop
<b>Operator:</b>	University of Arkansas	<b>Engine Manufacturer:</b>	Garrett
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	TPE 331-251K
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Executive/Corporate		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	BAZ, 651 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	Broken / 1850 ft agl	<b>Wind Speed/Gusts, Direction:</b>	14 knots / , 50°
<b>Temperature:</b>	-8° C	<b>Visibility</b>	8 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Austin, TX (AUS)	<b>Destination:</b>	Corpus Christi, TX (CRP)

## Wreckage and Impact Information

<b>Crew Injuries:</b>	2 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>	29.790000, -98.605000		

## Administrative Information

Investigator In Charge (IIC): Thomas M Little

Adopted Date: 11/25/2003

Investigation Docket: NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at [pubinq@ntsb.gov](mailto:pubinq@ntsb.gov), or at 800-877-6799. Dockets released after this date are available at <http://dms.nts.gov/pubdms/>.

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.