



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	Oso, WA	<b>Accident Number:</b>	SEA04LA063B
<b>Date &amp; Time:</b>	04/01/2004, 1700 PST	<b>Registration:</b>	N400WJ
<b>Aircraft:</b>	Glaser-Dirks DG-400	<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

## Analysis

While flying in trail along a ridgeline at the same altitude, the pilot of the Glaser-Dirks (lead glider) made a left turn, while the pilot of the Glasflugel (trailing glider) remained on course over the ridgeline. The Glasflugel pilot reported that he recalled that the Glaser-Dirks was at his 10:00 position when he encountered turbulence and he looked down to check his airspeed. When he looked back up, he lost sight of the Glaser-Dirks and assumed that he had rolled out to run the ridgeline to the south. The Glasflugel pilot continued along the ridgeline to the north when the Glaser-Dirks pilot transmitted to the Glasflugel pilot to "watch out/it." The Glasflugel pilot looked around to his left and spotted the other glider about 80 feet away at his 8:00 position and converging at the same altitude. The Glasflugel pilot reacted by making a right banking turn. During this maneuver, the left wing tip of the Glasflugel glider came up under the right wing of the Glaser-Dirks glider. The left wing tip of the Glasflugel contacted the underside of the right wing of the Glaser-Dirks about 13 feet 5 inches outboard of the wing root resulting in the outboard section of the right wing separating in flight. The pilot of the Glaser-Dirks was fatally injured, while the pilot of the Glasflugel was able to bail-out and deploy his parachute.

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot of the Glaser-Dirks (lead glider) failure to maintain clearance from the Glasflugel (trailing glider) resulting in a mid-air collision while maneuvering.

## Findings

Occurrence #1: MIDAIR COLLISION  
Phase of Operation: MANEUVERING

### Findings

1. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	48
<b>Airplane Rating(s):</b>	None	<b>Instrument Rating(s):</b>	None
<b>Other Aircraft Rating(s):</b>	Glider	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	204 hours (Total, all aircraft), 1 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Glaser-Dirks	<b>Registration:</b>	N400WJ
<b>Model/Series:</b>	DG-400	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	William S. Burhen	<b>Engine Manufacturer:</b>	Rotax
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	505
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	AWO, 137 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	None	<b>Wind Speed/Gusts, Direction:</b>	8 knots / , 310°
<b>Temperature:</b>	12° C	<b>Visibility</b>	10 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Arlington, WA (AWO)	<b>Destination:</b>	

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Latitude, Longitude:</b>	48.239722, -121.900000		

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Debra J Eckrote	<b>Adopted Date:</b>	09/29/2004
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .		

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.