



National Transportation Safety Board Aviation Accident Factual Report

Location:	Falmouth, MA	Accident Number:	IAD05LA030
Date & Time:	01/01/2005, 1400 EST	Registration:	N333EG
Aircraft:	Beech G35	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None

Flight Conducted Under: Part 91: General Aviation - Personal

On January 1, 2005, about 1400 eastern standard time, a Beech G35, N333EG, was substantially damaged during a collision with trees while taxiing for takeoff at Falmouth Airpark (5B6), Falmouth, Massachusetts. The certificated private pilot and passenger were not injured. Visual meteorological conditions prevailed, and no flight plan was filed. The personal flight, destined for Plymouth Municipal Airport (PYM), Plymouth, Massachusetts, was conducted under 14 CFR Part 91.

The pilot was interviewed via telephone and submitted a written statement. He stated that he performed a preflight inspection of the airplane, then started the engine while parked on the apron adjacent to his hangar.

The pilot increased the throttle in order to start the airplane moving over snow that had accumulated on the apron and taxiway. He then reduced the throttle after the airplane began accelerating; however, the engine continued to run at a higher rpm. The pilot tried again to reduce the throttle, to no avail. The airplane continued to accelerate at a "higher than normal" rate across the taxiway.

The pilot then applied full right rudder pedal and right brake, but the airplane did not respond, and continued to slide on the snow. The airplane impacted a line of trees, on the opposite side of the taxiway, head-on.

Additionally, the pilot reported that after the accident he and a friend inspected the throttle and carburetor. He reported hearing a "snapping sound" and felt a "binding" of the throttle cable.

The pilot's hangar was located in a residential area of the Falmouth Airpark. Access to the runway was provided via a 50-foot wide grass taxiway that ran perpendicular to the apron immediately in front of the pilot's hangar. Examination of pictures taken by the pilot on the day of the accident revealed that the taxiway and the grass portion of the apron in front of the hangar, was covered with patches of snow.

The airplane was a 1956 Beech G35, and had accumulated 3,430 total flight hours at the time of the accident. The airplane's most recent annual inspection was performed on June 1, 2004, and the airplane had accumulated 64 flight hours since that date.

The pilot held a private pilot certificate with a rating for airplane single engine land, and a third class medical certificate. At the time of the accident he reported 796 hours of total flight experience, and 47 hours of flight experience in make and model.

A Federal Aviation Administration (FAA) inspector examined the airplane on January 10, 2005. The inspector found that the throttle was stiff, but he could only duplicate the snapping sound heard by the pilot once, and noted a very slight vibration within the throttle. The inspector also found that the throttle moved completely from the idle to the full power position with no obstruction or hindrance.

Pilot Information

Certificate:	Private	Age:	58, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--w/ waivers/lim.	Last FAA Medical Exam:	10/04/2004
Occupational Pilot:		Last Flight Review or Equivalent:	10/04/2004
Flight Time:	796 hours (Total, all aircraft), 47 hours (Total, this make and model), 737 hours (Pilot In Command, all aircraft), 15 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N333EG
Model/Series:	G35	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	D-4636
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	06/01/2004, Annual	Certified Max Gross Wt.:	2775 lbs
Time Since Last Inspection:	64 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3430 Hours as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	E-225-8
Registered Owner:	On file	Rated Power:	225 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	FMH, 43 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	1355 EST	Direction from Accident Site:	360°
Lowest Cloud Condition:	Scattered / 25000 ft agl	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	11 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	13° C / -1° C
Precipitation and Obscuration:			
Departure Point:	Falmouth, MA (5B6)	Type of Flight Plan Filed:	None
Destination:	Plymouth, MA (PYM)	Type of Clearance:	None
Departure Time:	1400 EST	Type of Airspace:	Class G

Airport Information

Airport:	Falmouth Airpark (5B6)	Runway Surface Type:	Unknown
Airport Elevation:	43 ft	Runway Surface Condition:	Unknown
Runway Used:	NA	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	41.585556, -70.540278

Administrative Information

Investigator In Charge (IIC):	Robert L Pearce
Additional Participating Persons:	Eduard Spalzer; FAA/FSDO; Boston, MA
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .