



National Transportation Safety Board Aviation Accident Factual Report

Location:	Iliamna, AK	Accident Number:	ANC06LA043
Date & Time:	04/03/2006, 1000 AKD	Registration:	N36291
Aircraft:	Taylorcraft BC12-65	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

On April 3, 2006, about 1000 Alaska daylight time, a wheel-equipped Taylorcraft BC12-65 airplane, N36291, sustained substantial damage during a forced landing following a loss of engine power, about 16 miles northwest of Iliamna, Alaska. The airplane was being operated as a visual flight rules (VFR) cross-country personal flight under Title 14, CFR Part 91, when the accident occurred. The solo private certificated pilot sustained minor injuries. Visual meteorological conditions prevailed, and no flight plan was filed. The flight originated about 0930, from a remote off-airport site about 40 miles southwest of Iliamna, and was en route to Iliamna when the accident occurred.

During a telephone conversation with the National Transportation Safety Board (NTSB) investigator-in-charge (IIC), on April 4, the pilot related that during the flight to Iliamna, weather conditions consisted of ceilings between 600 and 800 feet, along with winds of 25 knots and blowing snow. As the flight progressed towards Iliamna, he noted a rough running engine and a slight reduction in engine rpm. He said that the application of carburetor heat and engine emergency procedures did not remedy the engine roughness, which was followed by a rapid loss of engine power, and subsequent loss of altitude. The pilot said that he was unable to restore adequate engine power to maintain level flight, and he selected a snow-covered plateau as a forced landing site. He said that terrain features around the forced landing site required a downwind approach. Just before touch down on the soft, snow-covered terrain, he said the left wing stalled and struck the ground, causing the airplane to cartwheel to the left. The airplane sustained structural damage to the left wing and fuselage.

In the pilot's written report that was submitted along with the NTSB Pilot/Operator Aircraft Accident Report (NTSB Form 6120.1/2), dated April 25, he reported that weather conditions at the time of the accident were, in part: Visibility, 2 miles; clouds and sky condition, 2,000 feet broken; wind, 090 degrees at 20 knots, gusting to 35 knots; temperature, 20 degrees F, with light snow showers and blowing snow. In the section of the form that inquires about and mechanical malfunction/failure, he wrote: "Carb Icing."

Pilot Information

Certificate:	Private	Age:	56, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With Waivers/Limitations	Last FAA Medical Exam:	02/01/2005
Occupational Pilot:		Last Flight Review or Equivalent:	07/01/2005
Flight Time:	164 hours (Total, all aircraft), 100 hours (Total, this make and model), 164 hours (Pilot In Command, all aircraft), 33 hours (Last 90 days, all aircraft), 9 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Taylorcraft	Registration:	N36291
Model/Series:	BC12-65	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	3209
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	08/01/2005, Annual	Certified Max Gross Wt.:	1200 lbs
Time Since Last Inspection:	80 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3129.3 Hours at time of accident	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	A65-8
Registered Owner:	Debra Schneider & Mitchell Rausa	Rated Power:	65 hp
Operator:	Debra Schneider & Mitchell Rausa	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	2 Miles
Lowest Ceiling:	Broken / 2000 ft agl	Visibility (RVR):	
Wind Speed/Gusts:	20 knots / 35 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-7° C
Precipitation and Obscuration:	Light - Blowing - Snow		
Departure Point:	ILIAMNA, AK	Type of Flight Plan Filed:	None
Destination:	ILIAMNA, AK (ILI)	Type of Clearance:	None
Departure Time:	0930 ADT	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	59.733333, -155.376389

Administrative Information

Investigator In Charge (IIC):	Clinton O Johnson
Additional Participating Persons:	John P Jones; Anchorage FSDO
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .