



National Transportation Safety Board Aviation Accident Factual Report

Location:	Somis, CA	Accident Number:	LAX06FA222
Date & Time:	07/01/2006, 1140 PDT	Registration:	N615M
Aircraft:	Raytheon Aircraft Company A36	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	2 Fatal, 2 Serious
Flight Conducted Under:	Part 91: General Aviation - Personal		

HISTORY OF FLIGHT

On July 1, 2006, about 1140 Pacific daylight time, a Raytheon Aircraft Company A36, N615M, impacted level terrain near Somis, California. The pilot/owner operated the airplane under the provisions of 14 Code of Federal Regulations Part 91. The private pilot and one passenger sustained serious injuries, two other passengers were killed. A majority of the airplane was thermally consumed in the post impact fire. The personal cross-country flight departed Santa Barbara Municipal Airport (SBA), Santa Barbara, California, at 1100 en route to Wiley Post Airport, Bethany, Oklahoma. Day visual meteorological conditions prevailed, and no flight plan had been filed.

The manager at the Hawthorne Automated Flight Service Station (AFSS), Hawthorne, California, reported that the pilot received an abbreviated weather briefing the morning of the accident, but did not file a flight plan. The pilot indicated his destination for the day was Wiley Post Airport via Prescott, Arizona, and New Mexico. The following morning (July 2) the route of flight was through Indiana and New England, with an ultimate destination of New Hampshire.

According to a Federal Aviation Administration (FAA) Quality Assurance specialist (AWP 505), the flight departed SBA about 1100. The pilot requested a direct flight at 9,500 feet to Prescott. At 1129, Southern California Terminal Radar Approach Control (SCT) radar identified the accident airplane 20 nautical miles (nm) southeast of SBA. The SCT controller was in contact with the pilot for 3.5 minutes. During this time the pilot indicated that he wanted to divert to Oxnard Airport (OXR), Oxnard, California, to "check a few things out." The SCT controller reported that he did not hear any alarm in the pilot's voice, nor did the pilot report any major problems.

The SCT controller then handed the pilot off to a controller at Point Mugu Approach (NDT). During the frequency change, the SCT controller reported to the NDT controller that the pilot was turning back to OXR with engine problems. At no time had the pilot specified what the nature of the problem was. The NDT controller asked if the pilot wanted to declare an

emergency, to which the pilot replied negatively. Shortly thereafter the pilot indicated that he wanted to divert to Camarillo Airport (CMA), Camarillo, California.

At 1137, the pilot was given a frequency change to CMA tower. When the pilot contacted the CMA controller, he was not able to provide his current location. While the controller was attempting to locate the airplane, the pilot selected the "identify" feature of the transponder enabling the controller to radar identify the airplane 3 miles north of the airport at 1,000 feet; the controller then cleared the pilot for landing. The pilot's last transmission was that he was not going to make the airport, and declared an unspecified emergency.

Camarillo tower Automated Weather Observation System (AWOS) reported weather at 1155 as winds from 260 degrees at 8 knots; visibility 10 statute miles; clear sky conditions; temperature 24 degrees Celsius; dew point 12 degrees Celsius; and altimeter setting 29.89 inches of Mercury (InHg).

A friend of the family stated that she spoke to the accident pilot while he was in the hospital. He told her that they were supposed to leave on June 29, in order to get their children to camp by July 3. He also told her that the seating arrangement was as follows:

Books in the right front seat

Pilot in the left front seat

One child seated directly behind the pilot

His spouse in the right forward facing seat

The other child in the rear right seat

The dog in the back on the left side

Luggage spread out on the floor underneath the passengers' feet

To date, the pilot has not returned the National Transportation Safety Board Pilot/Operator Aircraft Accident Report Form 6120.1/2, nor has he responded to numerous follow-up attempts by the Investigator-In-Charge to make a statement as to what the problem was that he was having during the flight.

The surviving passenger, a young child, was not able to provide a statement.

PERSONNEL INFORMATION

A review of Federal Aviation Administration (FAA) airman records revealed that the 44 year

old pilot held a private pilot certificate with an airplane single-land rating.

The pilot held a third-class medical certificate issued on December 01, 2004. It had no limitations or waivers.

No personal flight records were made available by the pilot to the National Transportation Safety Board. The aeronautical experience listed in this report was obtained from a review of the airmen FAA records on file in the Airman and Medical Records Center located in Oklahoma City, Oklahoma. On the pilot's December 1, 2004, medical application, he reported a total time of 2,200 hours.

AIRCRAFT INFORMATION

The airplane was a 2000 Raytheon Aircraft Company A36, serial number E-3344. A review of the airplane's logbooks revealed a total airframe time of 151.0 hours at the last annual inspection. An annual inspection was completed by Preferred Aviation Company, Goleta, California, and returned to service on February 10, 2006.

The airplane was equipped with a Teledyne Continental Motors IO-550-B (39) engine, serial number 684144. The last annual inspection performed on the engine was February 10, 2006, by Preferred Aviation Company, at a total time of 151.0 hours.

A Hartzell propeller model PHC-C3YF-1RF, serial number EE3524 was installed on the engine new on August 30, 2000, by Cutter Aviation Deer Valley Inc., Phoenix, Arizona. An annual inspection had been completed on January 01, 2004, with a total time of 66.2 hours.

Fueling records obtained from Mercury Air Center - Santa Barbara, Inc., Goleta, California, established that the airplane was last fueled on June 30, 2004, with the addition of 49.40 gallons of 100 LL-octane aviation fuel.

COMMUNICATIONS

The airplane was in contact with the following radar facilities: Santa Barbara Approach Control (SBA), Southern California Terminal (SCT) radar Approach Burbank Sector (BUR), and Departure Sector (LAX), Point Mugu Approach (NDT), and Camarillo Tower.

At 1838Z, CMA received a radio transmission from the pilot of N615M that reported he was inbound for landing. He reported north of the airport, and was then instructed to proceed eastbound and report a four-mile final for runway 26.

At 1839Z, the pilot stated that he needed to make an emergency landing. The controller cleared him to land on runway 26. The pilot reported that he would not be able to make the airport.

At 1840Z, the pilot reported that he was over a "bunch of nurseries." There were no additional transmissions received from the pilot.

According to the CMA controller personnel statements, the pilot was unsure of his position when he checked in. He initially reported that he was northwest of the field, and then north of the airport. He was then cleared to land on runway 26. In the next transmission, the pilot requested to land immediately, and then reported that he could not make the airport.

Coordinating transmissions between BUR and NDT:

At 18:34:27, the BUR controller reported to the NDT controller that he thought he was having some "engine problems or something." The airplane was 5 miles North West of the Fillmore VOR, wanting to land at Oxnard and "check some things out." The NDT controller asked if the pilot was declaring an emergency. The BUR controller reported that the pilot was not declaring an emergency.

At 18:37:00, The NDT controller asked if the pilot had information "echo" at Oxnard, and if he was declaring an emergency. The pilot stated that he was not declaring an emergency, and they just "would like to land" at Oxnard. The NDT controller reported that the BUR controller had made it seem like he (the accident pilot) was having some kind of a problem.

At 18:37:29, the NDT controller asked if the pilot was familiar with the area. The pilot reported that he had never landed at Oxnard before. The controller told the pilot that the airport was at his twelve o'clock, about 12 miles away. The pilot then asked if the airport was "...right over here? Or is this Camarillo?"

At 18:37:49 the NDT controller answered back, that there was an airport at the pilot's ten o'clock position at 7 miles, after Camarillo airport, and that Oxnard airport was closer to the shoreline.

At 18:37:55, the pilot requested to land at Camarillo. The NDT controller acknowledged the request. The controller then gave the pilot the current weather information (X-ray) for Camarillo.

At 18:38:29, the pilot was provided with Camarillo Tower's frequency. The last contact that NDT had with the accident pilot was at 18:38:35, when the pilot said "Thank you."

RADAR INFORMATION

The Safety Board IIC reviewed Pt. Mugu Approach's recorded radar data for the period of 18:27:20 until 18:40:45. At the initial contact time (18:27:20), radar identified the accident airplane at 9,000 feet at a groundspeed of 120 knots. At 18:30:30, the airplane was 7.5 miles from the Fillmore VOR at 9,700 feet at a groundspeed of 130 knots. For about 7 seconds the altitude fluctuated between 9,000 feet to 9,700 feet, and then down to 7,900 feet. The

airplane's groundspeed fluctuated between 120 knots to 150 knots, and then down to 80 knots.

At 18:34:42, (controller coordination between BUR and NDT) the radar target return was at 7,500 feet at a groundspeed of 90 knots. For the next second, the airplane descended down to 6,900 feet, and the groundspeed remained at 90 knots.

From 18:35:17 until 18:37:57, the airplane descended to 3,400 feet, with the groundspeed fluctuating between 100, 110, and 120 knots.

The last 3 seconds between 18:38:31 to 18:40:45, the airplane descended from 2,200 feet to 600 feet, with no recorded groundspeed.

Radar data recorded the airplane's last position as 45 miles east of SBA, about 5 miles north of CMA. It should be noted that the last radar return was within a 1/2 mile south of Santa Paula Airport (SZP), Santa Paula, California.

WRECKAGE AND IMPACT INFORMATION

The airplane came to rest upright in a drainage ditch adjacent to an asphalt road located between two lemon orchards. The road (Center Street) and the drainage ditch were oriented along an east/west direction. The entire fuselage of the airplane was located in the drainage ditch; the empennage came to rest on the north side of the drainage ditch on a magnetic bearing of 250 degrees, and the engine came to rest on the south side of the drainage ditch on a magnetic bearing of 160 degrees, both in their relative normal position.

The airframe was examined on scene, as well as, a visual inspection of the engine. Both examinations revealed no obvious preimpact mechanical malfunctions. The engine had separated from the airframe. All three propeller blades remained connected to the propeller hub; two of the blades were undamaged and straight, the third blade was bent 1-foot outboard of the hub with chordwise scratching evident on the propeller blade tip.

MEDICAL AND PATHOLOGICAL INFORMATION

The FAA, Forensic Toxicology Research Team, Oklahoma City, performed a toxicological analysis from samples obtained during the pilot's admission to the hospital. Tests for carbon monoxide, cyanide, and volatiles were not performed. Limited testing performed on the small amount of submitted specimens revealed N-desmethylocitalopram detected in serum.

A review of the pilot's December 1, 2004, airman medical application revealed that the pilot had reported that he was not currently using any medication, and he responded "no" to the question "mental disorders of any sort; depression, anxiety, etc." Records from the pilot's hospitalization following the accident reported under the MEDICAL HISTORY section that the pilot was currently taking Lexapro (escitalopram), and his past history included depression. Burned medical records located in the airplane from March and July 2005, showed a

prescription for Lexapro.

A friend of the family reported that the pilot had been taking Lexapro for 2 years, and that he had recently begun a prescription for Xanax (alprazolam). She asked him if he had flown since he had started taking the Xanax, to which he replied negatively. The friend categorized the accident pilot's general demeanor the week before the accident as sleep deprived and exhausted.

TESTS AND RESEARCH

Investigators examined the engine at Ray's Aircraft in Santa Paula, California, on July 3, 2006. The engine was shipped to Teledyne Continental Motors, Mobile, Alabama, for further inspection on February 12, 2007. Examination of the recovered engine and system components revealed no evidence of any preimpact mechanical malfunctions that would have precluded normal operation.

Pilot Information

Certificate:	Private	Age:	44, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	Yes
Medical Certification:	Class 3	Last FAA Medical Exam:	12/01/2004
Occupational Pilot:		Last Flight Review or Equivalent:	10/01/2004
Flight Time:	2200 hours (Total, all aircraft), 40 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Raytheon Aircraft Company	Registration:	N615M
Model/Series:	A36	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	E-3344
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	02/01/2006, Annual	Certified Max Gross Wt.:	3650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	151 Hours as of last inspection	Engine Manufacturer:	Teledyne Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-550-B (39)
Registered Owner:	Robert J. Santoro, Jr.	Rated Power:	300 hp
Operator:	Robert J. Santoro, Jr.	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	CMA, 77 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	1155 PDT	Direction from Accident Site:	180°
Lowest Cloud Condition:	Clear	Visibility:	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	26°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Santa Barbara, CA (SBA)	Type of Flight Plan Filed:	None
Destination:	OKLAHOMA CITY, OK (PWA)	Type of Clearance:	VFR
Departure Time:	1100 PDT	Type of Airspace:	

Airport Information

Airport:	CAMARILLO (CMA)	Runway Surface Type:	
Airport Elevation:	77 ft	Runway Surface Condition:	
Runway Used:	NA	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Precautionary Landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:	2 Fatal, 1 Serious	Aircraft Fire:	On-Ground
Ground Injuries:	N/A	Aircraft Explosion:	On-Ground
Total Injuries:	2 Fatal, 2 Serious	Latitude, Longitude:	34.272778, -119.071944

Administrative Information

Investigator In Charge (IIC):	Tealeye C Cornejo
Additional Participating Persons:	Frank L Motter; Federal Aviation Administration; Van Nuys, CA Mike Gibbons; Raytheon Aircraft Company; Wichita, KS Josh Cawthra; Teledyne Continental Motors; Mobile, AL
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .