



National Transportation Safety Board Aviation Accident Data Summary

Location:	Argyle, FL	Accident Number:	DEN06MA119
Date & Time:	09/01/2006, 1115 CDT	Registration:	N6569L
Aircraft:	Mitsubishi MU-2B-35	Injuries:	1 Fatal
Flight Conducted Under:	Part 91: General Aviation - Positioning		

Analysis

Prior to the accident flight, the pilot obtained a preflight weather briefing and filed an instrument flight rules flight plan. The briefer noted no adverse weather conditions along the route. The airplane departed the airport at 0853, and climbed to FL190. The first two hours of the flight was uneventful, and the aircraft was handed off to Jacksonville Air Route Traffic Control Center (ZJX ARTCC) at 1053. The pilot contacted ZJX Crestview sector at 1054:45 with the airplane level at FL190. At 1102, the Crestview controller broadcasted an alert for Significant Meteorological Information (SIGMET) 32E, which pertained to thunderstorms in portions of Florida southwest of the pilot's route. At 1103, the controller cleared to the airplane to descend to 11,000 feet and the pilot again acknowledged. At 1110:21, the pilot was instructed to contact Tyndall Approach. The pilot checked in with the Tyndall RAPCON North Approach controller at 1110:39. The pilot was told to expect a visual approach. Shortly thereafter, the pilot transmitted, "...we're at 11,000, like to get down lower so we can get underneath this stuff." The controller told the pilot to stand by and expect lower [altitude] in 3 miles. About 15 seconds later, the controller cleared to pilot to descend to 6,000 feet, and the pilot acknowledged. At 1112:27, the pilot was instructed to contact Tyndall Approach on another frequency. The airplane's position at that time was just northwest of REBBA intersection. The Panama sector controller cleared the pilot to descend to 3,000 feet at his discretion, and the pilot acknowledged. There was no further contact with the airplane. The controller attempted to advise the pilot that radar contact was lost, but repeated attempts to establish communications and locate the airplane were unsuccessful. A witness, located approximately 1 mile south of the accident site, reported he heard a "loud bang," looked up and observed the airplane in a nose down spiral. The witness reported there were parts separating from the airplane during the descent. The witness stated it was raining and there was lightning and thunder in the area. Local authorities reported that the weather "was raining real good with lightning and the thunderstorm materialized very quickly." The main wreckage came to rest near the edge of a swamp in tree covered and high grassy terrain. The left wing, left engine, and the left wing tip tank were located in a wooded area approximately 0.6 miles northwest of the main wreckage. The left wing separated from the airplane inboard of the left engine and nacelle. Examination of the fracture surfaces indicated that both the front and rear spars failed from "catastrophic static up-bending overstress..." The airplane flew through an intense to extreme weather radar echo containing a thunderstorm. Although the controllers denied that there was any weather displayed ahead of the airplane, recorded radar and display data indicated that moderate to extreme precipitation was depicted on and near the route of flight. During the flight, the pilot was given no real-time information on the weather ahead. The airplane was equipped with a weather radar system and the system provided continuous en route weather information relative to cloud formation, rainfall rate, thunderstorms, icing conditions, and storm detection up to a distance of 240 miles. No anomalies were noted with the airframe and engines.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

the pilot's inadvertent flight into thunderstorm activity that resulted in the loss of control, design limits of the airplane being exceeded and subsequent in-flight breakup. A contributing factor was the failure of air traffic control to use available radar information to warn the pilot he was about to encounter moderate, heavy, and extreme precipitation along his route of flight,

Findings

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: DESCENT - NORMAL

Findings

1. (F) IN FLIGHT WEATHER AVOIDANCE ASSISTANCE - NOT ISSUED - ATC PERSONNEL(ARTCC)
2. (C) FLIGHT INTO ADVERSE WEATHER - INADVERTENT - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: DESCENT - UNCONTROLLED

Findings

3. (C) AIRCRAFT CONTROL - NOT MAINTAINED - PILOT IN COMMAND
4. (C) DESIGN STRESS LIMITS OF AIRCRAFT - EXCEEDED - PILOT IN COMMAND
5. (C) WING,SPAR - FAILURE

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Findings

6. TERRAIN CONDITION - GROUND

Pilot Information

Certificate:	Airline Transport; Flight Instructor; Commercial	Age:	64
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Instrument Rating(s):	Airplane
Other Aircraft Rating(s):	None	Instructor Rating(s):	Airplane Multi-engine; Instrument Airplane
Flight Time:	30780 hours (Total, all aircraft), 10000 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Mitsubishi	Registration:	N6569L
Model/Series:	MU-2B-35	Engines:	2 Turbo Prop
Operator:	Berg Steel Pipe Corp.	Engine Manufacturer:	Garrett
Operating Certificate(s) Held:	None	Engine Model/Series:	TPE331-6-252M
Flight Conducted Under:	Part 91: General Aviation - Positioning		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument Conditions	Condition of Light:	Day
Observation Facility, Elevation:	CEW, 213 ft msl	Weather Information Source:	Weather Observation Facility
Lowest Ceiling:	Broken / 6500 ft agl	Wind Speed/Gusts, Direction:	Calm / ,
Temperature:	23° C	Visibility	10 Miles
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Tulsa, OK (TUL)	Destination:	Argyle, FL

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude, Longitude:	30.685556, -86.033611		

Administrative Information

Investigator In Charge (IIC):	Aaron M Sauer	Adopted Date:	07/25/2007
Note:	The NTSB traveled to the scene of this accident.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.ntsb.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.