



National Transportation Safety Board Aviation Accident Factual Report

Location:	Oakley, KS	Accident Number:	DEN07CA097
Date & Time:	06/01/2007, 1800 CDT	Registration:	N836RV
Aircraft:	Stevenson RV-6	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

According to the pilot, while on short final approach approximately 10 feet above ground level (agl), he added a little power to the engine and then heard a "loud pop" sound. Subsequently, the airplane stalled and the left wing impacted the grass runway. The airplane bounced, impacted trees and a fence, and came to rest inverted adjacent to the runway. The private pilot, who was the sole occupant and co-owner of the airplane, sustained minor injuries. Examination of the airplane revealed the vertical stabilizer and rudder were crushed. No anomalies were noted with the airframe and engine.

Pilot Information

Certificate:	Private	Age:	60, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:	Class 3	Last FAA Medical Exam:	08/01/2006
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	210 hours (Total, all aircraft), 35 hours (Total, this make and model), 3 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Stevenson	Registration:	N836RV
Model/Series:	RV-6	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Normal	Serial Number:	21865
Landing Gear Type:	Tailwheel	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Superior
ELT:		Engine Model/Series:	XPIO-360
Registered Owner:	Walter A. Stevenson	Rated Power:	
Operator:	Walter A. Stevenson	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:		Visibility	
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	Oakley, KS	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	CDT	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	NA	IFR Approach:	Visual
Runway Length/Width:		VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	1 Minor	Latitude, Longitude:	39.109722, -100.816389

Administrative Information

Investigator In Charge (IIC):	Aaron M Sauer
Additional Participating Persons:	
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinquiry@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .