



National Transportation Safety Board Aviation Accident Final Report

Location:	Duluth, MN	Accident Number:	CHI07CA253
Date & Time:	08/01/2007, 1037 CDT	Registration:	N5016E
Aircraft:	Cessna 180A	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The airplane was substantially damaged when it impacted terrain during an aborted landing attempt on runway 14, 3050 feet long, by 75 feet wide, dry asphalt. The pilot stated that as he was lowering the tailwheel to the runway, he impacted two geese. The airplane started to "turn to the right" while the pilot tried to correct using left brake, left rudder, and right aileron control inputs. The pilot then added full engine power "to get back in the air." The left wing subsequently contacted the runway and the airplane "flipped on its back" and came to rest inverted.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control, which resulted in impact with terrain during an attempted aborted landing. A factor in the accident was the geese impacted during the landing roll.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings

1. TERRAIN CONDITION - RUNWAY
2. (F) OBJECT - ANIMAL(S)

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

3. TERRAIN CONDITION - RUNWAY
4. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: LANDING - ABORTED

Findings

5. TERRAIN CONDITION - RUNWAY

Factual Information

Pilot Information

Certificate:	Private	Age:	43, Male
Airplane Rating(s):	Single-engine Land; Single-engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without Waivers/Limitations	Last Medical Exam:	03/01/2006
Occupational Pilot:		Last Flight Review or Equivalent:	10/01/2006
Flight Time:	622 hours (Total, all aircraft), 450 hours (Total, this make and model), 590 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	Cessna	Registration:	N5016E
Model/Series:	180A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	50316
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	07/01/2007, Annual	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2553 Hours	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-470R
Registered Owner:	On file	Rated Power:	230 hp
Operator:	On file	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Observation Facility, Elevation:	DYT, 610 ft msl	Observation Time:	1034 CDT
Distance from Accident Site:	0 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:		Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Clear	Temperature/Dew Point:	28°C / 20°C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	21 knots/ 25 knots, 220°	Visibility (RVR):	
Altimeter Setting:	29.84 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Two Harbors, MN (TWM)	Type of Flight Plan Filed:	None
Destination:	Duluth, MN (DYT)	Type of Clearance:	None
Departure Time:	1000 CDT	Type of Airspace:	

Airport Information

Airport:	RICHARD B HELGESON (DYT)	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	3050 ft / 75 ft	VFR Approach/Landing:	Full Stop; Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None		

Administrative Information

Investigator In Charge (IIC):	John M Brannen	Adopted Date:	08/30/2007
Additional Participating Persons:			
Publish Date:			
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.