



National Transportation Safety Board Aviation Accident Data Summary

Location:	Lafayette, IN	Accident Number:	CHI08CA035
Date & Time:	11/01/2007, 1714 EDT	Registration:	N5912Q
Aircraft:	Mooney M20E	Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Business		

Analysis

The airplane was in cruise flight at 6,500 feet when the engine began to run roughly. The pilot verified both magnetos were functioning properly, switched fuel tanks, and manipulated the throttle without any improvement in engine operation. He informed air traffic control of the loss of engine power and was subsequently cleared to land at an airport about 8 nm north of his position. The engine continued to run roughly as he maneuvered for the airport. The airplane impacted rising terrain that preceded the runway threshold. The airplane came to rest within 100 feet of the threshold. The airplane received substantial damage to the right wing and engine firewall. The nose and right main landing gear collapsed during the landing. The left main landing gear remained fully extended. Examination of the engine revealed that the number 3 cylinder had separated from the engine case. Further examination showed that the number 3 connecting rod had separated from the crankshaft. The connecting rod cap, two rod bolts, and two nuts were found separated inside the engine case. One of the rod bolts was bent and fractured approximately mid-span. One-half of this bolt remained with the rod cap. The bolt's fracture surface exhibited a cup/cone shape, consistent with an overload failure. The threaded region of this bolt was undamaged. One of the nuts had undamaged threads. The first three threads adjacent to the flat side of the remaining nut were damaged. The remaining rod bolt was intact, but the three threads from the end were damaged consistent with the damage noted on the second nut. The last engine overhaul was completed on November 19, 1972. The engine had accumulated 820 hours since that overhaul.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The improper installation of the connecting rod bolts during major overhaul, which resulted in the separation of the connecting rod from the crankshaft in flight. Contributing to the accident was the rising terrain encountered during touchdown and the subsequent landing gear collapse.

Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - NONMECHANICAL
Phase of Operation: CRUISE - NORMAL

Findings

1. (C) ENGINE ASSEMBLY,CONNECTING ROD CAP - SEPARATION
2. (C) ENGINE ASSEMBLY,CONNECTING ROD BOLT - LOOSE PART/BOLT/NUT/CLAMP/ETC
3. (C) MAINTENANCE,OVERHAUL,MAJOR - INADEQUATE - OTHER MAINTENANCE PERSONNEL

Occurrence #2: FORCED LANDING
Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #3: HARD LANDING
Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

- 4. (F) TERRAIN CONDITION - RISING
- 5. (F) LANDING GEAR - COLLAPSED

Pilot Information

Certificate:	Private	Age:	58
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Instrument Rating(s):	None
Other Aircraft Rating(s):	None	Instructor Rating(s):	None
Flight Time:	855 hours (Total, all aircraft), 46 hours (Total, this make and model), 11 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	Mooney	Registration:	N5912Q
Model/Series:	M20E	Engines:	1 Reciprocating
Operator:	G & W Aviation, LLC	Engine Manufacturer:	Lycoming
Air Carrier Operating Certificate:	None	Engine Model/Series:	IO-360-A1A
Flight Conducted Under:	Part 91: General Aviation - Business		

Meteorological Information and Flight Plan

Observation Facility, Elevation:	LAF, 606 ft msl	Weather Information Source:	Weather Observation Facility
Conditions at Accident Site:	Visual Conditions	Lowest Ceiling:	None
Condition of Light:	Day	Wind Speed/Gusts, Direction:	5 knots, 360°
Temperature:	12° C / -6° C	Visibility	10 Miles
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	La Porte, IN (PPO)	Destination:	Springfield, TN (M91)

Airport Information

Airport:	Purdue University Airport (LAF)	Runway Surface Type:	Asphalt
Runway Used:	5	Runway Surface Condition:	Dry
Runway Length/Width:	4225 ft / 1288 ft		

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None

Administrative Information

Investigator In Charge (IIC):	Andrew T Fox	Adopted Date:	01/31/2008
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.