



# National Transportation Safety Board Aviation Accident Data Summary

---

<b>Location:</b>	Auxvasse, MO	<b>Accident Number:</b>	CEN09CA092
<b>Date &amp; Time:</b>	12/05/2008, 1400 CST	<b>Registration:</b>	N1521Q
<b>Aircraft:</b>	CESSNA 150	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Instructional		

---

## Analysis

The pilot departed the local airport with intent of practicing traffic pattern work and basic flight maneuvers. After 3 touch and go maneuvers, the pilot departed the traffic pattern and flew the airplane to the designated practice area. After performing a couple 360-degree turns and slow flight, the pilot attempted a power-off stall. In order to prepare for the power-off stall, the pilot retarded the throttle and applied the carburetor heat. During the recovery of the power-off stall, the pilot "rapidly" applied engine power, closed the carburetor heat, and the engine lost power. The pilot attempted to restart the engine, however, the restart was unsuccessful. The pilot elected to perform an emergency off-airport landing. During the forced landing to a field, the pilot landed the airplane in a downwind direction and was high on the final approach. The pilot stated that he should have slipped the airplane during the approach which would have allowed for "use of more of the chosen field...a longer flare and a lighter touchdown at a lower airspeed." The airplane impact crops and terrain and came to rest on its nose. Examination of the airplane revealed the firewall was buckled. According to a designated pilot examiner, the rapid throttle application can result in engine flooding and subsequent engine failure.

## Flight Events

Maneuvering - Loss of engine power (total)  
Landing - Off-field or emergency landing

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's improper engine recovery procedures after a power-off stall which resulted in a loss of engine power. Contributing factors were the pilot's improper off-field landing procedures, and the lack of suitable terrain for the forced landing.

## Findings

Aircraft-Aircraft power plant-Engine (reciprocating)-(general)-Failure  
Personnel issues-Action/decision-Action-Incorrect action performance-Pilot - C  
Personnel issues-Task performance-Planning/preparation-(general)-Pilot - F  
Environmental issues-Physical environment-Terrain-Rough terrain-Contributed to outcome - F

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	56
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Instrument Rating(s):</b>	None
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	92 hours (Total, all aircraft), 33 hours (Total, this make and model), 53 hours (Pilot In Command, all aircraft), 24 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Manufacturer:</b>	CESSNA	<b>Registration:</b>	N1521Q
<b>Model/Series:</b>	150 L	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	David S. Hollabaugh	<b>Engine Manufacturer:</b>	CONTINENTAL
<b>Air Carrier Operating Certificate:</b>	None	<b>Engine Model/Series:</b>	O200
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Instructional		

## Meteorological Information and Flight Plan

<b>Observation Facility, Elevation:</b>	COU	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Lowest Ceiling:</b>	None
<b>Condition of Light:</b>	Day	<b>Wind Speed/Gusts, Direction:</b>	10 knots, 220°
<b>Temperature:</b>	-1 °C / -12 °C	<b>Visibility</b>	10 Miles
<b>Precipitation and Obscuration:</b>			
<b>Departure Point:</b>	Fulton, MO (FTT)	<b>Destination:</b>	Fulton, MO (FTT)

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Aaron M Sauer	<b>Adopted Date:</b>	12/24/2008
<b>Note:</b>	This accident report documents the factual circumstances of this accident as described to the NTSB.		
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

---

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.