



National Transportation Safety Board Aviation Accident Final Report

Location:	Payson, AZ	Accident Number:	WPR09CA106
Date & Time:	02/01/2009, 1305 MST	Registration:	N5423L
Aircraft:	GRUMMAN AA-5	Aircraft Damage:	Substantial
Defining Event:	Hard landing	Injuries:	2 None
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The AWOS reported winds were from 101 degrees at 11 knots, but another airplane was landing on runway 24, so the pilot announced that he would follow that airplane for landing. His approach was high and fast and he applied full flaps early and reduced the engine power to idle. The pilot reported encountering gusty wind conditions during the approach, but felt that he had the landing under control. The airplane was nearing touchdown, about midfield, when it suddenly descended and landed hard on the runway and bounced back into the air. The pilot said that the airspeed was about 60 miles per hour (mph), with no stall warning horn heard. The airplane was aligned with the runway centerline, and he felt that the airplane was under control, so he applied a small amount of power to cushion the touchdown. The airplane touched down and then bounced back into the air again. The pilot said that the bounce was smaller and it appeared that the airplane was slower as well. The airplane finally settled onto the runway; however, the right main landing gear touched down with more force and the airplane veered to the left of the runway and into a drainage swale. He was worried that the airplane would run into buildings or other aircraft, and since the airspeed was at 55 mph, he decided to get the airplane back into the air. He proceeded with the go-around, and once the airplane accelerated to 80 mph, he retracted the flaps. At this point, the right wing struck the windsock pole and the airplane began to sink back to the ground. He placed the airplane in a nose high attitude in hopes of clearing the airport perimeter fence; however, the airplane struck the fence and cartwheeled before coming to rest upright.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate recovery from a bounced landing and failure to maintain directional control. Contributing to the accident was the crosswind condition.

Findings

Aircraft	Directional control - Not attained/maintained (Cause)
Personnel issues	Incorrect action performance - Pilot (Cause) Aircraft control - Pilot (Cause)
Environmental issues	Crosswind - Response/compensation (Factor)

Factual Information

History of Flight

Landing-flare/touchdown	Hard landing (Defining event)
Landing-landing roll	Loss of control on ground Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	25, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without Waivers/Limitations	Last Medical Exam:	05/08/2006
Occupational Pilot:	No	Last Flight Review or Equivalent:	06/29/2007
Flight Time:	112 hours (Total, all aircraft), 10 hours (Total, this make and model), 48 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	GRUMMAN	Registration:	N5423L
Model/Series:	AA-5	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal; Utility	Serial Number:	AA5-0323
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:		Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320
Registered Owner:	Plane Options Inc.	Rated Power:	
Operator:	Plane Options Inc.	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Observation Facility, Elevation:	PRC, 5100 ft msl	Observation Time:	1253 MST
Distance from Accident Site:	58 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:	290°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Clear	Temperature/Dew Point:	14° C / -8° C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	10 knots/ 17 knots, 340°	Visibility (RVR):	
Altimeter Setting:	30.17 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Chandler, AZ (CHD)	Type of Flight Plan Filed:	None
Destination:	Payson, AZ (PAN)	Type of Clearance:	None
Departure Time:	1221 MST	Type of Airspace:	

Airport Information

Airport:	Payson Airport (PAN)	Runway Surface Type:	Asphalt
Airport Elevation:	5157 ft	Runway Surface Condition:	Dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	5500 ft / 75 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	
Total Injuries:	2 None		

Administrative Information

Investigator In Charge (IIC):	Tealeye Cornejo	Adopted Date:	05/12/2009
Additional Participating Persons:	Daren DuFriend; Federal Aviation Administration; Scottsdale, AZ		
Publish Date:	05/12/2009		
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.