



# National Transportation Safety Board Aviation Accident Final Report

---

<b>Location:</b>	Baker, CA	<b>Accident Number:</b>	WPR09LA177
<b>Date &amp; Time:</b>	04/02/2009, 1630 PDT	<b>Registration:</b>	N222G
<b>Aircraft:</b>	CESSNA 337G	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	2 Minor
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Personal		

---

## Analysis

The pilot was in cruise flight when both engines began to sputter and lose power. He attempted a restart of each engine but was unsuccessful. He estimated that the wind was out of the southeast at 40 knots and he wanted to turn into the wind for the landing, but could only get to a gravel road, which had a crosswind. He lowered the landing gear at the last instant in an attempt to cushion the landing, and kept the left wing low into the wind. The left wing contacted a gravel berm along the left side of the road, and the airplane spun around on the road. The landing gear fractured and separated and the airplane came to rest with the right wing on the ground. Recovery personnel drained 27 gallons of fuel from the left tank and 1.5 gallons from the right tank; the fuel selector valves were positioned for normal cruise flight. During a followup examination of the airplane no anomalies were noted. Fuel supplies were plumbed into the aircraft fuel system at both the left and right wing fuel tanks and both engines were started and run at various power settings. The investigation could not determine the reason for the power loss.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A total loss of engine power for undetermined reasons.

## Findings

---

<b>Environmental issues</b>	Rough terrain - Contributed to outcome Crosswind - Not specified
<b>Not determined</b>	Not determined - Unknown/Not determined (Cause)

## Factual Information

On April 2, 2009, about 1630 Pacific daylight time, a Cessna 337G, N222G, encountered uneven terrain during a forced landing near Baker, California. The pilot/owner was operating the airplane under the provisions of 14 Code of Federal Regulations (CFR) Part 91. The certificated airline transport pilot and one passenger sustained minor injuries; the airplane sustained substantial damage to the airframe and wings. The cross-country personal flight departed Corona, California, at 1545, with a planned destination of Henderson, Nevada. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot reported that he was in cruise flight when both engines began to sputter and lose power. He attempted a restart, but was unsuccessful. He stated that the airplane was losing altitude rapidly. He headed toward Interstate 15 thinking that he would be found quicker. He estimated that the wind was out of the southeast at 40 knots. He wanted to turn into the wind for the landing, but could only get to a gravel road, which had a crosswind. He lowered the landing gear at the last instant in an attempt to cushion the landing, and kept the left wing low into the wind. The left wing contacted a gravel berm along the left side of the road, and the airplane spun around on the road. The landing gear fractured and separated; the airplane came to rest with the right wing on the ground.

Recovery personnel reported that they drained 27 gallons of fuel from the left tank, and 1.5 gallons from the right tank.

The Safety Board investigator-in-charge (IIC) examined the airplane and engines.

The IIC removed the top spark plugs from the front engine. All spark plugs were clean and oval shaped with no mechanical deformation. The spark plug electrodes were gray in color, which corresponded to normal operation according to the Champion Aviation Check-A-Plug AV-27 Chart.

The IIC manually rotated the crankshaft with the propeller. The crankshaft rotated freely, and the valves moved approximately the same amount of lift in firing order. The gears in the accessory case turned freely, and he obtained thumb compression on all cylinders in firing order. He connected the spark plugs to the respective ignition harness leads, rotated the propeller, and produced spark at all plug electrodes.

The IIC removed the top spark plugs from the rear engine. All spark plugs were clean and oval shaped with no mechanical deformation. The spark plug electrodes were gray, which corresponded to normal operation according to the Champion Aviation Check-A-Plug AV-27 Chart.

The IIC manually rotated the crankshaft with the propeller. The crankshaft rotated freely, and the valves moved approximately the same amount of lift in firing order. The gears in the accessory case turned freely, and he obtained thumb compression on all cylinders in firing order. He connected the spark plugs to the respective ignition harness leads, rotated the propeller, and produced spark at all plug electrodes.

Recovery personnel plumbed a fuel supply to the left wing inlet line, and installed a propeller that was not certified for this airplane. The front engine was started without difficulty; there were no fuel flow indications due to impact damage. After the engine temperature stabilized, they applied full throttle and obtained 26 inches of manifold pressure and a maximum of 1,400

engine revolutions per minute (rpm). Initially black smoke came from the exhaust, but then it cleared. Movement of the mixture control had no effect until the last inch of travel toward the idle cutoff position. The engine idled smoothly at 700 rpm, and was shut off smoothly with the mixture control.

Recovery personnel plumbed a fuel supply to the right wing inlet line. The rear engine was started without difficulty; there were no fuel flow indications due to impact damage. After the engine temperature stabilized, they applied full throttle and the manifold pressure went to the top of the green arc. The engine rpm increased and was climbing through 2,500 rpm. They did not go higher as the rear propeller was deformed, and the engine started to vibrate. They set the rpm at 1,800 and completed a magneto check; the rpm dropped 100 rpm on the left magneto and 50 rpm on the right magneto. Aft movement of the mixture control smoothed out engine operation. The engine idled smoothly at 750 rpm, and was shut off smoothly by the mixture control with a 50-rpm rise.

## History of Flight

<b>Enroute-cruise</b>	Loss of engine power (total) (Defining event)
<b>Emergency descent</b>	Off-field or emergency landing
<b>Landing-landing roll</b>	Collision with terr/obj (non-CFIT)

## Pilot Information

<b>Certificate:</b>	Airline Transport; Commercial	<b>Age:</b>	71, Male
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	Airplane; Helicopter	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane Multi-engine; Airplane Single-engine; Helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With Waivers/Limitations	<b>Last Medical Exam:</b>	03/17/2009
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	03/17/2009
<b>Flight Time:</b>	19000 hours (Total, all aircraft), 3000 hours (Total, this make and model), 15000 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Manufacturer:	CESSNA	Registration:	N222G
Model/Series:	337G	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	33701783
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	04/17/2008, Annual	Certified Max Gross Wt.:	4630 lbs
Time Since Last Inspection:	30 Hours	Engines:	2 Reciprocating
Airframe Total Time:	1698 Hours	Engine Manufacturer:	Teledyne Continental Motors
ELT:	Installed, not activated	Engine Model/Series:	IO-360-G
Registered Owner:	Roger L Levander	Rated Power:	210 hp
Operator:	Roger L Levander	Air Carrier Operating Certificate:	None

## Meteorological Information and Flight Plan

Observation Facility, Elevation:	KDAG, 1927 ft msl	Observation Time:	1651 PDT
Distance from Accident Site:	40 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:	220°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Clear	Temperature/Dew Point:	27° C / -7° C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	28 knots/ 36 knots, 260°	Visibility (RVR):	
Altimeter Setting:	30 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Corona, CA (AJO)	Type of Flight Plan Filed:	None
Destination:	Henderson, NV (HND)	Type of Clearance:	VFR Flight Following
Departure Time:	1545 PDT	Type of Airspace:	

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor		

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Howard D Plagens	<b>Adopted Date:</b>	04/22/2010
<b>Additional Participating Persons:</b>	Ron Allen; FAA Riverside FSDO; Riverside, CA		
<b>Publish Date:</b>	04/22/2010		
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.