



National Transportation Safety Board Aviation Accident Final Report

Location:	Addison, TX	Accident Number:	CEN09LA274
Date & Time:	05/03/2009, 2106 CDT	Registration:	N528BM
Aircraft:	BEECH 35-C33	Aircraft Damage:	Substantial
Defining Event:	Fuel exhaustion	Injuries:	2 Serious
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The two commercial pilots (one of which was the owner) flew to the accident location and dropped off a passenger. Prior to the first flight the owner pilot had checked the fuel levels and determined there was enough fuel to make their desired flights. Neither pilot ensured the fuel selector was selecting the fullest tank prior to the second takeoff. On departure and about 200 feet above the ground the engine began sputtering and then lost power. The pilots switched fuel tanks in-flight, but the engine did not restart. The airplane landed short of the runway, resulting in substantial damage to the airplane and serious injuries to both pilots. Examination of the airplane revealed the right main tank was empty and the fuel selector was selected to the left main tank.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A loss of engine power in flight due to fuel starvation as a result of the pilots' inadequate fuel management.

Findings

Aircraft	Fuel - Fluid management (Cause)
Personnel issues	Use of equip/system - Flight crew (Cause)

Factual Information

On May 3, 2009, about 2106 central daylight time, a Beech 35-C33 airplane, N528BM, was substantially damaged during a forced landing following a loss of engine power after takeoff from Addison Airport (ADS), Addison, Texas. Both commercial pilots were seriously injured. The flight was being conducted under the provisions of Title 14 Code of Federal Regulations Part 91 without a flight plan. The repositioning flight was originating from ADS, and was en-route to Hicks Airfield (T67), Fort Worth, Texas. Night, visual meteorological conditions prevailed at the time of the accident.

The pilot was flying in the left seat to build high performance pilot in command (PIC) time. His first flight in the airplane was the afternoon of the accident, when he and the airplane owner, who was also a commercial pilot, flew the owner's son from T67 to ADS. The pilot stated he was unfamiliar with the airplane.

The owner-pilot, who was in the right seat, stated he had checked the fuel before flying to ADS and determined each main tank had between 15 and 20 gallons of fuel and the fuel selector was on the right main tank.

The airplane was on departure from initial takeoff and about 200 feet above the ground when the engine started sputtering. The owner-pilot immediately suspected the problem was that the fuel selector was still on the right main tank and it should have been switched to the left main tank. He reached for the fuel selector switch, which was located under the pilot's left leg, but he could not reach it. He then took control of the airplane and the pilot switched the fuel selector. The pilot stated he could not recall which tank it was on. The owner-pilot then attempted to return to ADS and land, but the airplane landed short of the runway on airport property.

The owner-pilot stated on the Accident/Incident Report (NTSB Form 6120.1) "I believe we took-off on the [right main fuel tank] and ran it empty. There [was not] time for the fuel in the [left main fuel tank] to restart the engine before we hit the ground. Other factors were that [the pilot] was unfamiliar with the airplane and I [was not] double checking him." "The aircraft hit the ground before I could see [the ground]."

Examination of the airplane revealed the left main landing gear strut was sheared off and pushed up through the left wing. The left horizontal stabilizer was damaged and the fuselage was partially buckled. Investigators on scene found the left wing tank was intact and contained approximately five to six gallons of fuel and the right wing tank was empty. The fuel selector was found in the left tank position.

A post accident engine inspection revealed the fuel inlet line and fuel vapor line were both dry and did not contain any fuel. Fuel was observed in the fuel manifold. The inspection did not reveal any abnormalities that would have prevented normal operation.

History of Flight

Prior to flight	Miscellaneous/other
Initial climb	Fuel exhaustion (Defining event) Loss of engine power (total) Off-field or emergency landing

Co-Pilot Information

Certificate:	Commercial; Private	Age:	40, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 With Waivers/Limitations	Last Medical Exam:	03/27/2009
Occupational Pilot:	No	Last Flight Review or Equivalent:	11/08/2008
Flight Time:	1020 hours (Total, all aircraft), 816 hours (Total, this make and model), 923 hours (Pilot In Command, all aircraft), 60 hours (Last 90 days, all aircraft), 16 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Flight Instructor; Commercial	Age:	34, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Without Waivers/Limitations	Last Medical Exam:	06/03/2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	09/23/2008
Flight Time:	905 hours (Total, all aircraft), 1 hours (Total, this make and model), 858 hours (Pilot In Command, all aircraft), 419 hours (Last 90 days, all aircraft), 144 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	BEECH	Registration:	N528BM
Model/Series:	35-C33	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal; Utility	Serial Number:	CD-1056
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	01/16/2009, Unknown	Certified Max Gross Wt.:	3858 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	577 Hours	Engine Manufacturer:	CONT MOTOR
ELT:	Installed, not activated	Engine Model/Series:	IO-520-BB
Registered Owner:	MARTIN BRYAN S	Rated Power:	260 hp
Operator:	MARTIN BRYAN S	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Observation Facility, Elevation:	ADS	Observation Time:	2110 CDT
Distance from Accident Site:	0 Nautical Miles	Condition of Light:	Night
Direction from Accident Site:	0°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Thin Overcast / 2900 ft agl	Temperature/Dew Point:	16° C / 13° C
Lowest Ceiling:	Overcast / 2900 ft agl	Visibility	13 Miles
Wind Speed/Gusts, Direction:	8 knots, 320°	Visibility (RVR):	
Altimeter Setting:	29.94 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:			
Departure Point:	Addison, TX (ADS)	Type of Flight Plan Filed:	None
Destination:	Hicks Airfield, TX (T67)	Type of Clearance:	Unknown
Departure Time:	2105 CDT	Type of Airspace:	

Airport Information

Airport:	Addison Airport (ADS)	Runway Surface Type:	N/A
Airport Elevation:	644 ft	Runway Surface Condition:	Dry
Runway Used:	33	IFR Approach:	None
Runway Length/Width:	7202 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	2 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious		

Administrative Information

Investigator In Charge (IIC):	Daniel Baker	Adopted Date:	04/22/2010
Additional Participating Persons:	Benoit Lafargue; Federal Aviation Administration; Dallas, TX John Kent; Teledyne Continental Motors; Mobile, AL		
Publish Date:	04/22/2010		
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.