



National Transportation Safety Board Aviation Accident Final Report

Location:	Los Banos, CA	Accident Number:	WPR10LA127
Date & Time:	02/02/2010, 1320 PST	Registration:	N36MV
Aircraft:	HILLER UH-12E	Aircraft Damage:	Substantial
Defining Event:	Powerplant sys/comp malf/fail	Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

Analysis

The pilot of the helicopter had just completed an aerial application flight and was returning to land. As he approached the landing area, he began to apply power, but the engine did not respond. He continued to twist the throttle, but it felt loose with no resistance and the engine speed did not change. He aborted the landing approach and performed a run-on landing in a field; during the approach the engine speed began to decrease and the helicopter landed hard, causing substantial damage to the tail boom and lower fuselage. Postaccident examination revealed that the throttle control attach fitting located in the aft section of the collective control had become separated. The nuts and bolts attaching the fitting were not located. The lack of witness marks on the throttle fitting indicates that either the attachment bolt failed or rapidly unscrewed from its associated nut. The disconnection resulted in a loss of engine control and subsequent partial loss of engine power. The last annual inspection occurred 11 months and 250 flight hours prior to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A partial loss of engine power due to a failure of the throttle interconnect hardware, which resulted in a hard landing.

Findings

Aircraft	Power lever - Failure (Cause)
----------	-------------------------------

Factual Information

HISTORY OF FLIGHT

On February 2, 2010, about 1320 Pacific standard time, a Hiller UH-12E helicopter, N36MV, landed hard near Los Banos, California. S and S Helicopters was operating the helicopter under the provisions of Title 14 Code of Federal Regulations Part 137 as an aerial application flight. The certificated commercial pilot was not injured. The helicopter sustained substantial damage. The local flight departed from a field near Los Banos. Visual meteorological conditions prevailed, and no flight plan had been filed.

The pilot reported that he had just completed an aerial application over a wheat field, and was returning to land. As he approached the landing area at an altitude of about 30 feet above ground level, he began to apply power, but the engine did not respond. He continued to twist the throttle, but it felt loose with no resistance, and the engine speed did not change. He aborted the landing approach, and turned the helicopter towards a larger open field. He circled the field about three times while attempting to diagnose the problem. He then elected to perform a run-on landing; during the landing approach, the engine speed began to decrease, and the helicopter landed hard.

During the landing sequence, the tailboom separated from the aft bulkhead, and the lower fuselage sustained crush damage.

Post accident examination revealed that the throttle control fitting, located at the aft end of the collective stick assembly, had become separated from the cam lever rod bearing.

According to the Hiller service manual applicable to this helicopter, the throttle control fitting is connected to the cam lever rod with an AN23-16A bolt, NAS43DD3-4 spacer, AN960PD10L washer, and a NAS679A3 nut. None of these fittings were located on the engine deck, and examination of the control arm mating surfaces revealed no gouges or fretting signatures.

According to maintenance logbook entries, the helicopter underwent an annual inspection on February 25, 2009, at an airframe total time of 6,815 flight hours. According to the FAA inspector who responded to the accident, the helicopter's total flight time at the time of the accident was 7,064 hours.

History of Flight

Approach-VFR pattern final	Powerplant sys/comp malf/fail (Defining event)
Emergency descent	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Commercial	Age:	54, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	Seatbelt, Shoulder harness
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With Waivers/Limitations	Last Medical Exam:	11/05/2009
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	11/24/2009
Flight Time:	18500 hours (Total, all aircraft), 7000 hours (Total, this make and model), 18500 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	HILLER	Registration:	N36MV
Model/Series:	UH-12E	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Restricted	Serial Number:	5060
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	02/25/2009, Annual	Certified Max Gross Wt.:	2700 lbs
Time Since Last Inspection:	249 Hours	Engines:	1 Reciprocating
Airframe Total Time:	7064 Hours	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	VO-540 SERIES
Registered Owner:	JEFF STREETER MOTOR SPORTS INC	Rated Power:	310 hp
Operator:	JEFF STREETER MOTOR SPORTS INC	Air Carrier Operating Certificate:	
Operator Does Business As:	S and S Helicopters	Operator Designator Code:	JF5G

Meteorological Information and Flight Plan

Observation Facility, Elevation:	MCE, 155 ft msl	Observation Time:	1301 PST
Distance from Accident Site:	28 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:	55°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Few / 700 ft agl	Temperature/Dew Point:	11° C / 9° C
Lowest Ceiling:	None	Visibility	3 Miles
Wind Speed/Gusts, Direction:	Calm	Visibility (RVR):	
Altimeter Setting:	29.83 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	Mist		
Departure Point:	Los Banos, CA	Type of Flight Plan Filed:	None
Destination:	Los Banos, CA	Type of Clearance:	None
Departure Time:	1300 PST	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None		

Administrative Information

Investigator In Charge (IIC):	Elliott Simpson	Adopted Date:	10/21/2010
Additional Participating Persons:	Gregg H Schmidt; Federal Aviation Administration FSDO; Fresno, CA		
Publish Date:	10/21/2010		
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=75334		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.