



# National Transportation Safety Board Aviation Accident Final Report

---

<b>Location:</b>	Winterset, IA	<b>Accident Number:</b>	CEN12LA224
<b>Date &amp; Time:</b>	04/01/2012, 1515 CDT	<b>Registration:</b>	N3830G
<b>Aircraft:</b>	CESSNA U206B	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	7 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Skydiving		

---

## Analysis

The pilot stated that he departed the airport with six parachutists for a jump flight. As the airplane approached 1,000 feet above ground level, he noticed that the airplane wasn't climbing. He checked the engine gauges and noticed that the engine analyzer was flashing "CHT" and the cylinder head temperature was 454 degrees F. As the pilot pitched the nose down and turned back to the airport, he heard a muffled "thud" sound and saw white smoke pour from the engine. As he prepared for a forced landing, four of the parachutists jumped from the airplane. The pilot then performed a forced landing in a field, coming to a stop near a dirt berm. An examination revealed a hole in the engine crankcase, near the No. 4 cylinder. Various pieces of metal, including part of a "quick oil drain plug" were found in the engine oil sump. The No. 4 connecting rod journal appeared distorted and displayed extensive heat signatures. The crankshaft journals on either side of the No. 4 rod journals did not appear to be distorted or to contain the same heat signatures and were coated with engine oil. The rod and crankshaft bearings were scored. The signatures on the engine were consistent with the loss of lubricant to the No. 4 connecting rod journal. A reason for the loss of engine oil to the journal was not found.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of oil pressure to the No. 4 connecting rod journal and the subsequent loss of engine power.

## Findings

---

<b>Aircraft</b>	Power plant - Failure (Cause)
	Oil - Not specified (Cause)

## Factual Information

On April 1, 2012, about 1515 central daylight time, a Cessna U206B airplane, N3830G, experienced a loss of engine power shortly after departure from the Winterset Municipal Airport (3Y3), Winterset, Iowa. The commercial rated pilot and six passengers were not injured and the airplane sustained substantial damage. The airplane was registered to and operated by Des Moines Skydivers, LLC, Des Moines, Iowa under the provision of 14 Code of Federal Regulation Part 91 as a parachute jump flight. Day visual meteorological conditions prevailed and the airplane was not on a flight plan.

The pilot reported that he departed the airport on a jump flight and turned crosswind, and headed north. When the airplane was about 1,000 feet above ground level, the airplane seemed to stop climbing, so he looked at the engine gauges and everything seemed normal. However, as he turned back to the engine analyzer, the analyzer was flashing “CHT” and the cylinder temperature read 454 degrees F. The pilot then pitched the airplane’s nose down to cool the engine, and turned back towards the airfield. The pilot heard a muffled “thud” sound and white smoke poured from the engine. The pilot pulled the mixture control, turned the ignition and master switches off. He then yelled for the jumpers to get out, and four of the parachutists were able to exit the airplane. He performed a forced landing in a plowed field and the airplane came to stop near a dirt berm.

The responding Federal Aviation Administration (FAA) inspector reported that the airplane sustained extensive firewall damage, when the nose landing gear was torn from the airplane during the forced landing. The inspector also noted that there was a hole in the engine’s crankcase near the number four cylinder.

The engine was removed from the airframe and sent to Continental Motor’s engine test facility, in Mobile, Alabama. The engine was examined under the supervision of the NTSB Investigator in Charge, and technical representatives from Continental Motors.

A visual exam of the engine confirmed the hole in the crankcase near the number four cylinder; the engine was then disassembled. Various pieces of metal, including part of a “quick oil drain plug” was found in the engine oil sump. The number four connecting rod journal appeared distorted and had displayed extensive heat signatures. The crankshaft journals on either side of the number four rod journals did not appear distorted nor contain the same heat signatures and were coated with engine oil. The rod and crankshaft bearings appeared scored. The crankcase and crankshaft oil galleys appeared open. A reason for the loss of engine oil to the journal was not found.

A review of the engine maintenance log book revealed that the engine had approximately 3,233 total hours and about 1,730 hours since major overhaul.

## History of Flight

Enroute-climb to cruise	Loss of engine power (total) (Defining event)
Emergency descent	Off-field or emergency landing

## Pilot Information

Certificate:	Commercial	Age:	45, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without Waivers/Limitations	Last Medical Exam:	09/29/2011
Occupational Pilot:		Last Flight Review or Equivalent:	09/09/2011
Flight Time:	1045 hours (Total, all aircraft), 177 hours (Total, this make and model), 981 hours (Pilot In Command, all aircraft), 20 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Manufacturer:	CESSNA	Registration:	N3830G
Model/Series:	U206B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Utility	Serial Number:	U206-0830
Landing Gear Type:	Tricycle	Seats:	6
Date/Type of Last Inspection:	03/22/2012, Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	6966 Hours	Engine Manufacturer:	CONT MOTOR
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO 520 SERIES
Registered Owner:	DES MOINES SKYDIVERS LLC	Rated Power:	285 hp
Operator:	DES MOINES SKYDIVERS LLC	Air Carrier Operating Certificate:	None

## Meteorological Information and Flight Plan

Observation Facility, Elevation:	KDSM	Observation Time:	1454 CDT
Distance from Accident Site:	19 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:	45°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Few / 25000 ft agl	Temperature/Dew Point:	29° C / 17° C
Lowest Ceiling:	None	Visibility	
Wind Speed/Gusts, Direction:	10 knots, 170°	Visibility (RVR):	
Altimeter Setting:	29.54 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Precipitation		
Departure Point:	Winterset, IA (3Y3)	Type of Flight Plan Filed:	Unknown
Destination:	Winterset, IA (3Y3)	Type of Clearance:	None
Departure Time:	CDT	Type of Airspace:	

## Airport Information

Airport:	Winterset Municipal Airport (3Y3)	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	N/A	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced Landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	6 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	7 None		

## Administrative Information

Investigator In Charge (IIC):	Craig Hatch	Adopted Date:	04/25/2013
Additional Participating Persons:	Harrison McNaughton; FAA FSDO; Des Moines, IA John Kent; Continental Motors; Mobile, AL		
Publish Date:	04/25/2013		
Investigation Docket:	<a href="http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=83294">http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=83294</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.