



# National Transportation Safety Board Aviation Accident Final Report

---

<b>Location:</b>	Tampa, FL	<b>Accident Number:</b>	ERA13LA104
<b>Date &amp; Time:</b>	01/02/2013, 1810 EST	<b>Registration:</b>	N345VH
<b>Aircraft:</b>	ROBINSON HELICOPTER R22 BETA	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Hard landing	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Instructional		

---

## Analysis

The flight instructor and her student were practicing autorotations. The student entered a practice autorotation at 500 feet above ground level (agl) and at 70 knots. About 40 feet agl, the student bled off airspeed by flaring the helicopter. The student advanced the throttle, but the rpm started to decay. The instructor had her hands on the controls and added throttle to arrest the rpm decay. When the rpm continued to decay, she took the controls and performed a hovering autorotation. The helicopter impacted a grassy area next to the runway, bounced, and rolled over, coming to an immediate stop. The fuselage and main rotor sustained substantial damage. The flight instructor reported that there was excessive play in the left throttle and that she had reported the condition to the operator's mechanic twice previously. Examination of the throttle system found it to be in an airworthy condition.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's delayed throttle application during the practice autorotation and the flight instructor's lack of immediate remedial action, which resulted in a hard landing.

## Findings

---

<b>Aircraft</b>	Descent rate - Not attained/maintained (Cause)
<b>Personnel issues</b>	Use of equip/system - Student pilot (Cause) Delayed action - Instructor/check pilot (Cause)

## Factual Information

On January 2, 2013, about 1810 eastern standard time, a Robinson R22 Beta, N345VH, was substantially damaged following a practice autorotation to runway 22 at Peter O Knight Airport (TPF), Tampa, Florida. The flight instructor and a student pilot were not injured. The helicopter was operated by Helicopter Academy under the provisions of 14 Code of Federal Regulations Part 91 as an instructional flight. Visual meteorological conditions prevailed and no flight plan was filed. The flight originated at Clearwater, Florida (PIE) about 1715.

The flight instructor reported that she landed at PIE to pick up her student and proceeded to TPF for approaches and practice autorotations. The first three approaches were uneventful. During the fourth approach to runway 22, the student entered a practice autorotation at 500 feet above ground level (agl) and at 70 knots. About 40 feet agl, the student bled off airspeed by making “baby flares.” She reported that the student rolled on the throttle, but the governor did not catch and the rpm started to decay. The instructor had her hands on the controls and added throttle to arrest the rpm decay. When the rpm continued to decay, she took the controls and performed a hovering autorotation. The helicopter impacted a grassy area next to the runway, bounced, and rolled over, coming to an immediate stop.

A Federal Aviation Administration (FAA) inspector responded to the accident site and examined the wreckage. The inspector confirmed substantial damage to the airframe. Both main rotor blades were bent in several places. The engine firewall was buckled. The tail boom was crushed at the fuselage attachment point and the horizontal stabilizer was bent about 90 degrees. The flight instructor reported to the inspector that there was excessive “play” in the left throttle and she had reported the condition to the operator’s maintenance personnel twice previously, and was informed that the play was normal.

On January 8, 2013, the FAA re-inspected the helicopter throttle system with the assistance of a technical representative from Robinson Helicopter Company. The inspector reported that, based on the description of the throttle rigging provided to the technical representative, the throttle was in an airworthy condition.

Recorded weather at PTF at the time of the accident included calm surface wind.

## History of Flight

Autorotation	Hard landing (Defining event)
--------------	-------------------------------

## Flight Instructor Information

<b>Certificate:</b>	Flight Instructor; Commercial	<b>Age:</b>	41, Female
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Helicopter	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With Waivers/Limitations	<b>Last Medical Exam:</b>	09/05/2012
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	08/15/2012
<b>Flight Time:</b>	871 hours (Total, all aircraft), 820 hours (Pilot In Command, all aircraft), 89 hours (Last 90 days, all aircraft), 56 hours (Last 30 days, all aircraft)		

## Student Pilot Information

<b>Certificate:</b>	Student	<b>Age:</b>	35, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 With Waivers/Limitations	<b>Last Medical Exam:</b>	08/05/2011
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	68 hours (Total, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Manufacturer:</b>	ROBINSON HELICOPTER	<b>Registration:</b>	N345VH
<b>Model/Series:</b>	R22 BETA	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	No
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	2314
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	11/12/2012, 100 Hour	<b>Certified Max Gross Wt.:</b>	1370 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	3417 Hours	<b>Engine Manufacturer:</b>	LYCOMING
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	O-320 SERIES
<b>Registered Owner:</b>	SPITZER MATTHEW L	<b>Rated Power:</b>	180 hp
<b>Operator:</b>	Helicopter Academy	<b>Air Carrier Operating Certificate:</b>	None

## Meteorological Information and Flight Plan

Observation Facility, Elevation:	TPF, 7 ft msl	Observation Time:	1815 EST
Distance from Accident Site:	0 Nautical Miles	Condition of Light:	Dusk
Direction from Accident Site:		Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Scattered / 6000 ft agl	Temperature/Dew Point:	21° C / 17° C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	Calm	Visibility (RVR):	
Altimeter Setting:	30.04 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Clearwater, FL (PIE)	Type of Flight Plan Filed:	None
Destination:	Tampa, FL (TPF)	Type of Clearance:	None
Departure Time:	1715 EST	Type of Airspace:	

## Airport Information

Airport:	Peter O Knight Airport (TPF)	Runway Surface Type:	Asphalt
Airport Elevation:	7 ft	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	3580 ft / 100 ft	VFR Approach/Landing:	Simulated Forced Landing

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None		

## Administrative Information

Investigator In Charge (IIC):	Ralph E Hicks	Adopted Date:	08/07/2013
Additional Participating Persons:	Michael Singleton; FAA/FSDO; Tampa, FL		
Publish Date:	08/07/2013		
Investigation Docket:	<a href="http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=85946">http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=85946</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.