



National Transportation Safety Board

Aviation Accident Data Summary

Location:	Yellow Pine, ID	Accident Number:	WPR14FA094
Date & Time:	12/01/2013, 1303 MST	Registration:	N36ML
Aircraft:	BEECH B36TC	Injuries:	5 Fatal
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The instrument-rated pilot was on a 234-nm instrument flight rules (IFR) cross-country flight over mountainous terrain; instrument meteorological conditions prevailed at the time. During the flight, the pilot notified a controller at the Air Route Traffic Control Center (ARTCC) that the airplane was picking up too much ice and requested to divert to an airport located about 96 miles ahead of his position and to descend to 11,000 feet mean sea level (msl). The controller informed the pilot that he could descend to 12,000 feet msl for terrain clearance. Over the following few minutes, the ARTCC controller notified the pilot several times that he had to maintain an altitude of 12,000 feet or above due to terrain clearance, all of which the pilot acknowledged. Following a low-altitude alert issued by the controller, the pilot stated his altitude was 11,500 feet. Subsequently, the pilot advised the controller that he was having engine problems and needed to go to an airport immediately.

When the controller asked the pilot to verify his altitude, the pilot responded that he was at 10,000 feet. The controller then asked the pilot if he was able to climb, and the pilot responded “negative.” The controller advised the pilot of an airport that was 24 miles behind his position and asked if he wanted to divert. The pilot responded affirmatively and asked for guidance to the airport. About 1 minute later, the pilot advised the controller that the airplane had “just lost its engine.” The controller advised the pilot that the airport was at the pilot’s six o’clock position and suggested a heading of 253 degrees, adding that another airport was right below their position. There were no further communications with the accident airplane.

Wreckage and impact signatures were found consistent with a wings-level, slightly nose-low descent into trees and terrain. Postaccident examination of the airframe and engine revealed no evidence of any preexisting mechanical malfunction that would have precluded normal operation.

Airmen’s Meteorological Information (AIRMETs) for IFR and mountain obscuration conditions, low-level wind shear and turbulence, and moderate icing were issued for the flight track area and timeframe. In addition to the AIRMETs, multiple pilot reports included reports of light rime-type icing between 8,000 feet and 13,000 feet throughout the region and National Weather Service data was consistent with the pilot reports and AIRMET that were current at the time. The investigation was unable to determine whether the pilot obtained weather information regarding his planned flight. It is likely that the loss of engine power was due to a combination of structural and induction icing during the continued flight in icing conditions in an airplane that was not certified for flight in icing conditions.

Flight Events

Enroute-cruise - Structural icing

Enroute-cruise - Altitude deviation
 Enroute-cruise - Fuel related
 Enroute-cruise - Loss of engine power (partial)
 Enroute-cruise - Controlled flight into terr/obj (CFIT)

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:
 The pilot's continued flight into known light-to-moderate icing conditions over mountainous terrain.
 Contributing to the accident was the loss of engine power due to induction icing.

Findings

Aircraft-Aircraft power plant-Power plant-Air intake-Not specified - F
 Personnel issues-Action/decision-Info processing/decision-Decision making/judgment-Pilot - C
 Personnel issues-Task performance-Use of equip/info-Use of equip/system-Pilot - C
 Environmental issues-Conditions/weather/phenomena-Temp/humidity/pressure-Conducive to structural icing-Effect on equipment - C

Pilot Information

Certificate:	Private	Age:	51
Airplane Rating(s):	Single-engine Land	Instrument Rating(s):	Airplane
Other Aircraft Rating(s):	None	Instructor Rating(s):	None
Flight Time:	(Estimated) 1050 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	BEECH	Registration:	N36ML
Model/Series:	B36TC TC	Engines:	1 Reciprocating
Operator:	On file	Engine Manufacturer:	Continental Motors
Air Carrier Operating Certificate:	None	Engine Model/Series:	TSIO-520-UB3F
Flight Conducted Under:	Part 91: General Aviation - Personal		

Meteorological Information and Flight Plan

Observation Facility, Elevation:	KMYL, 5020 ft msl	Weather Information Source:	Weather Observation Facility
Conditions at Accident Site:	Instrument Conditions	Lowest Ceiling:	Overcast / 2400 ft agl
Condition of Light:	Day	Wind Speed/Gusts, Direction:	11 knots, 140°
Temperature:	2°C / 0°C	Visibility	9 Miles
Precipitation and Obscuration:	Light - Rain; No Obscuration		
Departure Point:	Baker City, OR	Destination:	Butte, MT

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	4 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None

Administrative Information

Investigator In Charge (IIC):	Joshua Cawthra	Adopted Date:	08/28/2014
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=88552		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.