



# National Transportation Safety Board Aviation Accident Final Report

---

<b>Location:</b>	Lee's Summit, MO	<b>Accident Number:</b>	CEN15CA165
<b>Date &amp; Time:</b>	03/01/2015, 1530 CST	<b>Registration:</b>	N3575X
<b>Aircraft:</b>	PIPER PA 28-181	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Aerodynamic stall/spin	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Instructional		

---

## Analysis

The pilot-receiving-instruction reported that the purpose of the flight was to receive a checkout in the flying club airplane. After completing three uneventful takeoffs and landings, the flight instructor asked the pilot-receiving-instruction to perform a simulated soft-field takeoff from a high-altitude airport. The pilot-receiving-instruction had not performed the requested maneuver previously, which was described as a soft-field takeoff at 50-percent engine power to simulate the atmospheric conditions of a high-altitude airport. Before attempting the takeoff, both pilots agreed that the pilot-receiving-instruction would manipulate the flight controls and that the throttle would be separately controlled by the flight instructor. The pilot-receiving-instruction reported that during the takeoff, shortly after becoming airborne, while still in ground-effect, the airplane encountered an aerodynamic stall. The pilot-receiving-instruction briefly reduced airplane pitch to recover from the aerodynamic stall, but as the airplane drifted toward the right side of the runway he subsequently increased yoke backpressure to keep the airplane airborne. The pilot-receiving-instruction reported that the airplane encountered a second aerodynamic stall after he increased airplane pitch. The airplane subsequently drifted left, crossing back over the runway, before the airplane landed along the left side of the runway. The flight was terminated and the aircraft inspected for damage. The airplane exhibited damage to the tail skid, tail tie-down ring, left wingtip, the nose and left main landing gear, and the propeller. An additional examination established that the aft fuselage bulkhead had sustained substantial damage when the tail struck the runway. The pilot-receiving-instruction reported there were no mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

The flight instructor reported that the engine power had been set at 2,100 rpm to simulate the available engine power while operating at a high-altitude airport. He reported that the pilot-receiving-instruction had used excessive pitch control inputs during the initial takeoff roll to keep the nose wheel off the runway, the airplane veered to the right before coming airborne, and that the airplane encountered an aerodynamic stall upon liftoff. The flight instructor reported that the airplane subsequently bounced, drifted to the left, and eventually landed along the left side of the runway.

The flight crew's decision to have the flight instructor separately control the throttle during the accident takeoff likely prevented the pilot-receiving-instruction from adequately recovering from the initial aerodynamic stall. Additionally, following the initial aerodynamic stall, there was likely inadequate coordination between the flight crew to reestablish control of the airplane before it impacted the ground.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot-receiving-instruction's excessive pitch control during takeoff, which resulted in an aerodynamic stall shortly after liftoff and the subsequent loss of control. Contributing to the accident was the flight crew's decision to have the flight instructor separately control the throttle while the pilot-receiving-instruction manipulated the flight controls, which resulted in inadequate coordination between the flight crew during the attempted stall recovery.

### Findings

<b>Aircraft</b>	Angle of attack - Not attained/maintained (Cause)
<b>Personnel issues</b>	Aircraft control - Student pilot (Cause) Decision making/judgment - Flight crew (Factor) Lack of communication - Pilot (Factor) Lack of communication - Student pilot (Factor)

## Factual Information

### History of Flight

<b>Takeoff</b>	Aerodynamic stall/spin (Defining event) Loss of control in flight Abnormal runway contact
----------------	---

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	31, Male
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 1 Without Waivers/Limitations	<b>Last Medical Exam:</b>	04/19/2013
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	02/16/2015
<b>Flight Time:</b>	112 hours (Total, all aircraft), 6 hours (Total, this make and model), 79 hours (Pilot In Command, all aircraft), 34 hours (Last 90 days, all aircraft), 17 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

### Flight Instructor Information

<b>Certificate:</b>	Airline Transport; Flight Instructor; Flight Engineer	<b>Age:</b>	77, Male
<b>Airplane Rating(s):</b>	Multi-engine Land; Single-engine Land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	Yes
<b>Instructor Rating(s):</b>	Airplane Single-engine; Instrument Airplane	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With Waivers/Limitations	<b>Last Medical Exam:</b>	09/29/2014
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	04/13/2013
<b>Flight Time:</b>	(Estimated) 24945 hours (Total, all aircraft), 14438 hours (Pilot In Command, all aircraft), 34 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Manufacturer:	PIPER	Registration:	N3575X
Model/Series:	PA 28-181	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	28-8090199
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	01/01/2015, Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	8605 Hours	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-360-A4M
Registered Owner:	Wing Flying Club, Inc.	Rated Power:	180 hp
Operator:	Wing Flying Club, Inc.	Air Carrier Operating Certificate:	None

## Meteorological Information and Flight Plan

Observation Facility, Elevation:	LXT, 1004 ft msl	Observation Time:	1515 CST
Distance from Accident Site:	0 Nautical Miles	Condition of Light:	Day
Direction from Accident Site:		Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:		Temperature/Dew Point:	0°C / -7°C
Lowest Ceiling:	Overcast / 3000 ft agl	Visibility	10 Miles
Wind Speed/Gusts, Direction:	6 knots, 310°	Visibility (RVR):	
Altimeter Setting:	30.38 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Lee's Summit, MO (LXT)	Type of Flight Plan Filed:	None
Destination:	Lee's Summit, MO (LXT)	Type of Clearance:	None
Departure Time:	1500 CST	Type of Airspace:	Class G

## Airport Information

Airport:	Lee's Summit Municipal Airport (LXT)	Runway Surface Type:	Concrete
Airport Elevation:	1004 ft	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	4016 ft / 75 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None		

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Andrew T Fox	<b>Adopted Date:</b>	12/17/2015
<b>Additional Participating Persons:</b>	Thomas Bartels; Federal Aviation Administration, Kansas City FSDO; Kansas City, MO		
<b>Publish Date:</b>	12/17/2015		
<b>Note:</b>	This accident report documents the factual circumstances of this accident as described to the NTSB.		
<b>Investigation Docket:</b>	<a href="http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=90833">http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=90833</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.