



# National Transportation Safety Board Aviation Accident Data Summary

<b>Location:</b>	Raton, NM	<b>Accident Number:</b>	CEN15FA255
<b>Date &amp; Time:</b>	06/05/2015, 0628 MDT	<b>Registration:</b>	N162WR
<b>Aircraft:</b>	CUB CRAFTERS CC18-180	<b>Injuries:</b>	2 Fatal
<b>Flight Conducted Under:</b>	Public Aircraft		

## Analysis

The airplane, which was being operated as a public aircraft, departed with the pilot and a gunner on board for the local flight. The purpose of the flight was to locate and kill coyotes in a geographical area with a history of livestock damage. According to the ground-based spotter, the pilot established radio contact with him after the airplane passed over the mesa that bordered the western edge of the target area. The pilot transmitted that he had observed a coyote behind the spotter's position and that they were going to perform a low-altitude pass for the gunner to kill the coyote. The spotter turned around and located the coyote using his binoculars. He reported that he heard 2 to 3 shotgun blasts as the airplane passed through his field of view on a northeast heading. He remained focused on the coyote as the airplane exited his field of view, and, shortly thereafter, he heard it impact the ground.

A review of recovered GPS data indicated that the airplane descended to about 41 ft above the ground and then entered a climbing left turn. The airplane's calculated groundspeed decreased from 77 mph to 55 mph during the climbing left turn. According to the airplane flight manual, the wings-level aerodynamic stall speed was 52 mph with the flaps retracted; however, the stall speed increased to 56 mph when the airplane was in a coordinated 30° banked turn and 74 mph when the airplane was in a coordinated 60° banked turn. A postaccident examination established that the airplane had crashed in a nose-low, near-vertical attitude. Based on the GPS data and the near-vertical impact angle, the pilot likely did not maintain adequate airspeed during the climbing left turn, which resulted in the airplane exceeding its critical angle of attack and experiencing an aerodynamic stall at a low altitude. The postaccident wreckage examination did not reveal any anomalies that would have precluded normal operation of the airplane during the flight.

Although postaccident toxicological testing of the pilot identified three over-the-counter sedating antihistamines, the lack of available blood for testing prevented a determination as to whether they affected the pilot's psychomotor or cognitive functioning during the accident flight.

## Flight Events

Maneuvering-low-alt flying - Loss of control in flight  
Maneuvering-low-alt flying - Collision with terr/obj (non-CFIT)

## Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain adequate airspeed while maneuvering at a low altitude, which resulted in the airplane exceeding its critical angle of attack and experiencing an aerodynamic stall.

## Findings

Aircraft-Aircraft oper/perf/capability-Performance/control parameters-Airspeed-Not attained/maintained - C

Aircraft-Aircraft oper/perf/capability-Performance/control parameters-Angle of attack-Not attained/maintained - C

Personnel issues-Task performance-Use of equip/info-Aircraft control-Pilot - C

Personnel issues-Physical-Health/Fitness-Use of medication/drugs-Pilot

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	54
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Instrument Rating(s):</b>	Airplane
<b>Other Aircraft Rating(s):</b>	None	<b>Instructor Rating(s):</b>	None
<b>Flight Time:</b>	13484 hours (Total, all aircraft), 13034 hours (Pilot In Command, all aircraft), 142.4 hours (Last 90 days, all aircraft), 62.4 hours (Last 30 days, all aircraft), 5.3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	CUB CRAFTERS	<b>Registration:</b>	N162WR
<b>Model/Series:</b>	CC18-180	<b>Engines:</b>	1 Reciprocating
<b>Operator:</b>	USDA-APHIS-WS	<b>Engine Manufacturer:</b>	Lycoming
<b>Operating Certificate(s) Held:</b>	None	<b>Engine Model/Series:</b>	O-360-C4P
<b>Flight Conducted Under:</b>	Public Aircraft		

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual Conditions	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	RTN, 6352 ft msl	<b>Weather Information Source:</b>	Weather Observation Facility
<b>Lowest Ceiling:</b>	None	<b>Wind Speed/Gusts, Direction:</b>	7 knots / , 50°
<b>Temperature:</b>	12° C	<b>Visibility</b>	10 Miles
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Raton, NM (RTN)	<b>Destination:</b>	Raton, NM (RTN)

## Wreckage and Impact Information

Crew Injuries:	2 Fatal	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Latitude, Longitude:	36.716389, -104.133333		

## Administrative Information

Investigator In Charge (IIC):	Andrew T Fox	Adopted Date:	05/11/2017
Note:	The NTSB traveled to the scene of this accident.		
Investigation Docket:	<a href="http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=91312">http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=91312</a>		

---

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.