



National Transportation Safety Board Aviation Accident Final Report

Location:	Lovelock, NV	Accident Number:	WPR17LA012
Date & Time:	10/20/2016, 0730 PDT	Registration:	N4YB
Aircraft:	NORTHLAND AVIATION LLC IVP	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Business		

Analysis

The airline transport pilot reported that, while climbing to cruise altitude, about 9 minutes into the cross-country flight, he felt a severe shudder and the engine experienced a total loss of power. Simultaneously, oil began to coat the windscreen. The pilot maneuvered for a nearby airport; however, as he neared the airport, he realized that the airplane would not reach the runway and elected to land in an open area of desert vegetation.

Postaccident examination of the engine revealed a hole in the crankcase above the Nos. 3 and 4 connecting rod journals. The Nos. 3 and 4 pistons were fractured into several pieces, which were located within the engine. The No. 3 connecting rod had separated from the crankshaft. The No. 3 cylinder intake valve head was broken at the bottom of the valve guide; the valve head was not located within the engine.

A visual examination by a metallurgist was unable to determine the initial failure mode given the postfracture mechanical damage to the fractured end of the valve stem and the absence of the separated valve head; however, due to the quantity and severity of damage found throughout the engine, the likely initial point of failure was a fracture to the intake valve in the No. 3 cylinder.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to the failure of the intake valve in the No. 3 cylinder for reasons that could not be determined based on the available information.

Findings

Aircraft	Recip engine power section - Failure (Cause)
Not determined	Not determined - Unknown/Not determined (Cause)

Factual Information

On October 20, 2016, about 0730 Pacific daylight time, an experimental amateur-built Northland Aviation LLC Lancair IV-P airplane, N4YB, made a forced landing, following a total loss of engine power, near Lovelock, Nevada. The airline transport pilot sustained minor injuries. The airplane was substantially damaged to the wings and fuselage. The airplane was registered to Northland Aviation LLC and operated by the pilot under the provisions of Title 14 *Code of Federal Regulations* Part 91 as a personal cross-country flight. Visual meteorological conditions prevailed, and no flight plan was filed. The flight departed from Fallon Municipal Airport (FLX), Fallon, Nevada, about 0710, and was destined for Burns, Oregon.

The pilot reported that he was climbing to his cruise altitude of 16,500 ft when, about 9 minutes into the flight, he felt a severe shudder and the engine lost power. Simultaneous to the shudder, oil began to coat the windshield. The pilot headed for Derby Field Airport, Lovelock, for landing, however as he neared the airport, he realized that he was not going to make the runway and elected to land the airplane in an open area of desert vegetation.

A review of maintenance records indicated that the experimental Lancair IV-P, serial number LIV-482 was issued a special airworthiness certificate on February 7, 2003. The airplane was equipped with a Continental Motors TSIO-550-E, serial number 803075, 350 hp engine. The pilot reported at the time of the accident, the engine had accumulated about 865 hours since new.

Postaccident examination of the engine revealed a hole in the crankcase above the #3 and #4 connecting rod journals. The #3 and #4 pistons were fractured into several pieces that were located within the engine. The #3 connecting rod had separated from the crankshaft. The connecting rods and crankshaft journals exhibited signs of thermal distress. The camshaft was fractured into four pieces. The top and bottom spark plugs from cylinder #3 exhibited debris damage and the electrodes were missing. The combustion chamber of cylinder #3 exhibited impact marks from debris. The intake valve in cylinder #3 was broken at the bottom of the valve guide. The broken intake valve head was not located within the engine and the fracture surface of the valve stem was severely damaged from debris. A metallurgist from Continental Motors visually examined the parts and determined that further examination would prove to be inconclusive due to the mechanical damage the parts sustained.

History of Flight

Enroute-climb to cruise	Loss of engine power (total) (Defining event)
Landing	Off-field or emergency landing Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Airline Transport	Age:	79, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Waiver Time Limited Special	Last FAA Medical Exam:	09/05/2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	7087 hours (Total, all aircraft), 865 hours (Total, this make and model), 12 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 0.3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	NORTHLAND AVIATION LLC	Registration:	N4YB
Model/Series:	IVP NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	2003	Amateur Built:	Yes
Airworthiness Certificate:	Experimental	Serial Number:	LIV-482
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	08/01/2016, Condition	Certified Max Gross Wt.:	3500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	865 Hours at time of accident	Engine Manufacturer:	CONT MOTOR
ELT:	C126 installed, not activated	Engine Model/Series:	TSIO-550 SER
Registered Owner:	NORTHLAND AVIATION LLC	Rated Power:	350 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	KLOL, 3904 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1453 UTC	Direction from Accident Site:	29°
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.36 inches Hg	Temperature/Dew Point:	-1° C / -3° C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Fallon, NV (FLX)	Type of Flight Plan Filed:	None
Destination:	Burns, OR (BNO)	Type of Clearance:	None
Departure Time:	0710 PDT	Type of Airspace:	Class E

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	40.056111, -118.577778 (est)

Administrative Information

Investigator In Charge (IIC):	Christopher R Shaver	Report Date:	09/10/2018
Additional Participating Persons:	Jim Richardson; FAA Reno FSDO; Reno, NV Christopher Lang; Continental Motors; Mobile, AL		
Publish Date:	09/10/2018		
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=94280		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).