



National Transportation Safety Board Aviation Accident Factual Report

Location:	Fort Mohave, AZ	Accident Number:	GAA17CA126
Date & Time:	01/26/2017, 1100 MST	Registration:	N6885F
Aircraft:	PIPER PA32R	Aircraft Damage:	Substantial
Defining Event:	Landing gear not configured	Injuries:	2 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

The pilot reported that during the initial climb he retracted the landing gear normally and then "a few minutes later the radios went blank." The pilot further reported that he believed he had a radio problem, so he decided to return to the airport. During the return, the pilot reported that he moved the landing gear selector to the down position, but the three gear down indicator lights did not illuminate. Subsequently, the pilot reported that he circled a few miles east of the airport to troubleshoot the issue.

During the circling, the pilot reported that he "cycled the master switch and the radio master a couple times with no results." The pilot further reported that the airplane was equipped with an "automatic gear extension system," so he verified that the override switch was not engaged, fully extended the flaps, and slowed the airplane to 85 knots. Subsequently, the pilot believed the landing gear was down, so he returned to the airport for landing. During touchdown, the left main landing gear and nose gear collapsed (or were not extended) and the airplane veered off the runway into dirt, which resulted in substantial damage to the left wing. During a postaccident interview, the pilot reported that he believed he had "a total electrical failure."

According to a witness who owns a house on the airport property, he observed the airplane depart and about 5 minutes later saw that the airplane had returned for landing. The witness reported that the airplane's landing gear were retracted until the point at which the pilot began the landing flare over the runway. The witness further reported, when the airplane was about 5 feet above the runway, each landing gear began to extend, but the airplane touched down before the nose gear and left main landing gear could extend fully.

According to a Federal Aviation Administration (FAA) Aviation Safety Inspector (ASI) who arrived at the accident site about two to three hours after the event, when he "switched the master switch on," he observed electrical equipment turn on and heard the landing gear extension motor running. During a subsequent postaccident examination, the FAA ASI reported that he found no abnormalities with the electrical system. He also extended the landing gear to the down and locked position with the electric/ hydraulic system and observed three green indicator lights illuminated.

According to the Pilot's Operating Handbook (POH) for the accident airplane, a "pressure sensing device" in the landing gear system will lower the gear "regardless of the gear selection position," pending that the override switch is not engaged. The POH further stated in part: "The gear is designed to extend at airspeeds below approximately 103 KIAS [Knots Indicated Airspeed] with power off even if the selector is in the up position. The extension speeds will vary from approximately 81 KTS [Knots] to approximately 103 KIAS depending on power settings and altitude."

Pilot Information

Certificate:	Private	Age:	74, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With Waivers/Limitations	Last FAA Medical Exam:	02/17/2015
Occupational Pilot:	No	Last Flight Review or Equivalent:	01/21/2016
Flight Time:	(Estimated) 2570 hours (Total, all aircraft), 1870 hours (Total, this make and model), 2570 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6885F
Model/Series:	PA32R 300	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	32R-7780048
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	01/25/2016, Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3767 Hours at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-540-KIG5D
Registered Owner:	B&B INVESTMENT	Rated Power:	300 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	KIFP, 698 ft msl	Distance from Accident Site:	13 Nautical Miles
Observation Time:	1835 UTC	Direction from Accident Site:	50°
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	17 knots / 23 knots	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.39 inches Hg	Temperature/Dew Point:	11 °C / -5 °C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	BULLHEAD CITY, AZ (A20)	Type of Flight Plan Filed:	None
Destination:	REDLANDS, CA (REI)	Type of Clearance:	None
Departure Time:	1100 MST	Type of Airspace:	Class G

Airport Information

Airport:	SUN VALLEY (A20)	Runway Surface Type:	Asphalt
Airport Elevation:	725 ft	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	3700 ft / 42 ft	VFR Approach/Landing:	Full Stop; Precautionary Landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.005556, -114.565000 (est)

Administrative Information

Investigator In Charge (IIC):	Adam M Gerhardt
Additional Participating Persons:	Gary R Rucker; FAA; Las Vegas, NV
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=94665