



National Transportation Safety Board Aviation Accident Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | Sidney, NY | Accident Number: | GAA18CA015 |
| Date & Time: | 10/18/2017, 1715 EDT | Registration: | N37TP |
| Aircraft: | THOMAS G PARKHURST KITFOX IV | Aircraft Damage: | Substantial |
| Defining Event: | Loss of control in flight | Injuries: | 2 Minor |
| Flight Conducted Under: | Part 91: General Aviation - Personal | | |

Analysis

The pilot reported that, during final approach, the airplane was "out of alignment to the left edge of the runway." He decided to add throttle and realign with the runway, but as he reached for the throttle to add power, at that instant, he was "blinded" by sun glare, and he had "no memory of [the] events for approximately 6 seconds" after that point. He added that, just before impact, he saw the ground, but "there was nothing that could be done." The airplane impacted a parking lot in a nose-low, left-wing-down attitude.

The airplane sustained substantial damage to the fuselage, empennage, and both wings.

During a telephone conversation with the National Transportation Safety Board investigator-in-charge, the passenger reported that, during landing, the airplane was crabbing to the left but traveling forward. He reported that, before the runway threshold, there was a momentary sun flash that "lit up the plastic windscreen." He further reported that the pilot applied power, pulled back on the control stick, and the airplane "spiraled" and "twisted" left and downward into a parking lot.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

It is likely that the pilot exceeded the airplane's critical angle of attack and then entered an aerodynamic stall/spin.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's exceedance of the airplane's critical angle of attack following a loss of ground reference during landing in glaring sun conditions, which resulted in an aerodynamic stall/spin.

Findings

| | |
|-----------------------------|---|
| Aircraft | Angle of attack - Capability exceeded (Cause) Airspeed - Not attained/maintained (Cause) |
| Personnel issues | Aircraft control - Pilot (Cause) Situational awareness - Pilot (Cause) |
| Environmental issues | Glare - Effect on personnel |

Factual Information

History of Flight

| | |
|----------------------------|---|
| Approach-VFR pattern final | Other weather encounter Loss of visual reference Loss of control in flight (Defining event) |
| Approach-VFR go-around | Aerodynamic stall/spin Collision with terr/obj (non-CFIT) |

Pilot Information

| | | | |
|---------------------------|---|-----------------------------------|------------|
| Certificate: | Flight Instructor; Recreational; Sport Pilot | Age: | 68, Male |
| Airplane Rating(s): | Single-engine Land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 4-point |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | Sport Pilot | Toxicology Performed: | No |
| Medical Certification: | Sport Pilot None | Last FAA Medical Exam: | |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | 07/08/2017 |
| Flight Time: | (Estimated) 394 hours (Total, all aircraft), 90 hours (Total, this make and model), 302 hours (Pilot In Command, all aircraft), 13 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|-------------------------------|---|-----------------------------------|-----------------|
| Aircraft Make: | THOMAS G PARKHURST | Registration: | N37TP |
| Model/Series: | KITFOX IV NO SERIES | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | Yes |
| Airworthiness Certificate: | Experimental | Serial Number: | ASC-199 |
| Landing Gear Type: | Tailwheel | Seats: | 2 |
| Date/Type of Last Inspection: | 05/02/2017, Condition | Certified Max Gross Wt.: | 1200 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 81 Hours as of last inspection | Engine Manufacturer: | Rotax |
| ELT: | C91A installed, activated, did not aid in locating accident | Engine Model/Series: | 912 |
| Registered Owner: | On file | Rated Power: | 80 hp |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Conditions at Accident Site: | Visual Conditions | Condition of Light: | Day |
| Observation Facility, Elevation: | KBGM, 1636 ft msl | Distance from Accident Site: | 25 Nautical Miles |
| Observation Time: | 2153 UTC | Direction from Accident Site: | 240° |
| Lowest Cloud Condition: | Clear | Visibility | 10 Miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / | Turbulence Type Forecast/Actual: | / None |
| Wind Direction: | 220° | Turbulence Severity Forecast/Actual: | / N/A |
| Altimeter Setting: | 30.23 inches Hg | Temperature/Dew Point: | 17° C / 6° C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | SIDNEY, NY (N23) | Type of Flight Plan Filed: | None |
| Destination: | Sidney, NY (N23) | Type of Clearance: | None |
| Departure Time: | 1630 EST | Type of Airspace: | Class G |

Airport Information

| | | | |
|----------------------|-------------------|---------------------------|----------------------------|
| Airport: | SIDNEY MUNI (N23) | Runway Surface Type: | Asphalt |
| Airport Elevation: | 1026 ft | Runway Surface Condition: | Dry |
| Runway Used: | 25 | IFR Approach: | None |
| Runway Length/Width: | 4201 ft / 75 ft | VFR Approach/Landing: | Go Around; Traffic Pattern |

Wreckage and Impact Information

| | | | |
|---------------------|---------|----------------------|-----------------------------|
| Crew Injuries: | 1 Minor | Aircraft Damage: | Substantial |
| Passenger Injuries: | 1 Minor | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 Minor | Latitude, Longitude: | 42.305278, -75.408889 (est) |

Preventing Similar Accidents

Prevent Aerodynamic Stalls at Low Altitude

While maneuvering an airplane at low altitude in visual meteorological conditions, many pilots fail to avoid conditions that lead to an aerodynamic stall, recognize the warning signs of a stall onset, and apply appropriate recovery techniques. Many stall accidents result when a pilot is momentarily distracted from the primary task of flying, such as while maneuvering in the airport traffic pattern, during an emergency, or when fixating on ground objects.

An aerodynamic stall can happen at any airspeed, at any altitude, and with any engine power setting. Pilots need to be honest with themselves about their knowledge of stalls and preparedness to recognize and handle a stall situation. Training can help pilots fully

understand the stall phenomenon, including angle-of-attack (AOA) concepts and how weight, center of gravity, turbulence, maneuvering loads, and other factors can affect an airplane's stall characteristics. The stall characteristics may be different in each type of airplane, so learn them before you fly.

The stall airspeeds marked on the airspeed indicator (for example, the bottom of the green arc and the bottom of the white arc) typically represent steady flight speeds at 1G at the airplane's maximum gross weight in the specified configuration. Maneuvering loads and other factors can increase the airspeed at which the airplane will stall. For example, increasing bank angle can increase stall speed exponentially.

Reducing AOA by lowering the airplane's nose at the first indication of a stall is the most important immediate response for stall avoidance and stall recovery. This may seem counterintuitive at low altitudes, but is a necessary first step.

See http://www.nts.gov/safety/safety-alerts/documents/SA_019.pdf for additional resources.

The NTSB presents this information to prevent recurrence of similar accidents. Note that this should not be considered guidance from the regulator, nor does this supersede existing FAA Regulations (FARs).

Administrative Information

| | | | |
|--|---|---------------------|------------|
| Investigator In Charge (IIC): | Adam M Gerhardt | Report Date: | 02/21/2018 |
| Additional Participating Persons: | Todd Moses; FAA/ FSDO; Albany, NY | | |
| Publish Date: | 10/04/2019 | | |
| Note: | This accident report documents the factual circumstances of this accident as described to the NTSB. | | |
| Investigation Docket: | http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=96214 | | |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).