



National Transportation Safety Board Aviation Accident Final Report

Location:	Longmont, CO	Accident Number:	CEN18LA102
Date & Time:	02/16/2018, 1320 MST	Registration:	N89ER
Aircraft:	SCHEINEMAN-VAN BUREN T 18	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	2 Serious
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The tailwheel-qualified private pilot was conducting his first flight in the T-18 airplane with a flight instructor. After several local flight maneuvers and about seven uneventful landings, he planned to execute a full-stop landing. During the landing roll, the airplane turned right as it decelerated. The pilot attempted to correct the turn with left rudder control and braking, but the airplane groundlooped, departed the runway surface, and nosed over, which resulted in damage to the left wing and vertical stabilizer. The pilot was unsure if he had applied any braking pressure during the landing before having directional control issues. The flight instructor did not recall the accident sequence due to his injuries. Postaccident examination of the airplane revealed no evidence of mechanical malfunctions or failures, except for a fractured rudder cable. Examination of the cable revealed an overstress separation, which was consistent with accident damage. Thus, the pilot likely failed to maintain directional control during the landing roll and the flight instructor did not take timely remedial action to maintain runway heading.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll and the flight instructor's delayed remedial action, which resulted in a groundloop and nose over.

Findings

Aircraft	Directional control - Not attained/maintained (Cause)
Personnel issues	Aircraft control - Pilot (Cause)
	Delayed action - Instructor/check pilot (Cause)

Factual Information

On February 16, 2018, about 1320 mountain standard time, a Scheineman-Van Buren T-18 airplane, N89ER, was substantially damaged while landing at Vance Brand Airport (LMO), Longmont, Colorado. The pilot and flight instructor were seriously injured. The airplane was registered to and operated by the pilot under the provisions of Title 14 *Code of Federal Regulations* Part 91 as a training flight. Day visual meteorological conditions prevailed for the local flight, which departed without a flight plan about 1220.

The purpose of the flight was to orient the pilot to the airplane, which he had recently purchased. The pilot had flown about 200 hours in other tailwheel airplanes. After the pilot and flight instructor departed LMO, the pilot flew several local flight maneuvers, including slow flight, stalls, and steep turns. Returning to LMO, the pilot executed about uneventful seven landings. During the last landing, planned as a full stop, the airplane turned to the right as it decelerated below about 40 knots. The pilot attempted to correct the turn by applying left rudder control and with braking, but the airplane ground looped, departed the runway surface, and nosed over, damaging the left wing and vertical stabilizer. The pilot was unsure if he had applied any braking during the landing prior to having directional control issues. The flight instructor did not recall the last landing due to his injuries.

Examination of the airplane by a Federal Aviation Administration inspector revealed no anomalies, except for a fractured rudder cable. No wear or chaffing marks were observed on the rudder cable, and no anomalies were noted with the installation. The rudder cable specifications matched the airplane build instructions. The National Transportation Safety Board Materials Laboratory examined the rudder cable with a 5x to 50x magnification stereo microscope and determined that fracture surfaces were consistent with an overstress separation.

History of Flight

Landing	Loss of control on ground (Defining event)
Landing-landing roll	Nose over/nose down

Pilot Information

Certificate:	Private	Age:	28, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without Waivers/Limitations	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	360 hours (Total, all aircraft), 1 hours (Total, this make and model)		

Flight Instructor Information

Certificate:	Airline Transport; Flight Instructor	Age:	81, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Right
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane Multi-engine; Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With Waivers/Limitations	Last FAA Medical Exam:	01/16/2017
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	11/18/2016
Flight Time:	15000 hours (Total, all aircraft), 500 hours (Total, this make and model), 25 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	SCHEINEMAN-VAN BUREN	Registration:	N89ER
Model/Series:	T 18 UNDESIGNAT	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	Yes
Airworthiness Certificate:	Experimental	Serial Number:	1106
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	07/03/2017, Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	Reciprocating
Airframe Total Time:	1634 Hours as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed	Engine Model/Series:	O-320-B3B
Registered Owner:	On file	Rated Power:	160 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	KLMO, 5056 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1315 MST	Direction from Accident Site:	315°
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	80°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.99 inches Hg	Temperature/Dew Point:	5°C / -8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Longmont, CO (LMO)	Type of Flight Plan Filed:	None
Destination:	Longmont, CO (LMO)	Type of Clearance:	None
Departure Time:	1220 MST	Type of Airspace:	Class E

Airport Information

Airport:	VANCE BRAND (LMO)	Runway Surface Type:	Concrete
Airport Elevation:	5055 ft	Runway Surface Condition:	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	4799 ft / 75 ft	VFR Approach/Landing:	Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	2 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious	Latitude, Longitude:	40.164444, -105.163611 (est)

Administrative Information

Investigator In Charge (IIC):	Michael J Folkerts	Report Date:	11/06/2019
Additional Participating Persons:	Mark Petrosky; Flight Standards District Office; Denver, CO		
Publish Date:	11/06/2019		
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	http://dms.ntsb.gov/pubdms/search/dockList.cfm?mKey=96754		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).