



National Transportation Safety Board Aviation Accident Final Report

Location:	Bend, OR	Accident Number:	GAA18CA459
Date & Time:	07/31/2018, 1330 PDT	Registration:	N116PM
Aircraft:	HERZOG AVIATION CCX-2000	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The pilot of the tailwheel-equipped, experimental, amateur-built airplane reported that, during the landing roll at his home airport, the left main landing gear (MLG) wheel exited the asphalt runway and entered gravel that bordered the runway. The pilot applied right rudder to steer the airplane back onto the runway, but at the point where the left MLG tire contacted the asphalt runway, the left MLG collapsed. The left wing struck the ground, and the airplane came to rest on the runway.

The airplane sustained substantial damage to the left wing spar and aileron.

The pilot reported that the left MLG shock absorber shaft had sheared off at the lock nut attached to the rod end, which he believed resulted in the left MLG collapsing. However, photographs provided by Federal Aviation Administration air safety inspectors revealed that the left MLG failed inward and underneath the fuselage of the airplane. Additionally, the photographs revealed ground scars on the asphalt runway from the left wing that could be traced from the runway centerline, about 90° back to that of the runway heading. Further, photographs revealed that the airplane was equipped with tundra tires, which would have put a lot of stress on the landing gear. The evidence indicates that the left MLG collapsed when the pilot attempted to steer the airplane back onto the runway.

The METAR at the airport reported that the wind about the time of the accident was variable at 3 knots, gusting to 12 knots. The pilot landed the airplane on runway 16.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll, which resulted in a runway excursion and the subsequent collapse of the left main landing gear when he attempted to steer the airplane back onto the runway.

Findings

Aircraft	Directional control - Not attained/maintained (Cause) Main landing gear - Failure (Cause)
Personnel issues	Aircraft control - Pilot (Cause)

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event) Attempted remediation/recovery
----------------------	--

Pilot Information

Certificate:	Private	Age:	75, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Front
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With Waivers/Limitations	Last FAA Medical Exam:	07/16/2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	07/27/2017
Flight Time:	(Estimated) 2044 hours (Total, all aircraft), 4 hours (Total, this make and model), 2044 hours (Pilot In Command, all aircraft), 35 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HERZOG AVIATION	Registration:	N116PM
Model/Series:	CCX-2000	Aircraft Category:	Airplane
Year of Manufacture:	2018	Amateur Built:	Yes
Airworthiness Certificate:	Experimental	Serial Number:	CCX-2000-0025
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	07/03/2018,	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	44.6 Hours	Engine Manufacturer:	Cub Crafter
ELT:	C126 installed, not activated	Engine Model/Series:	CC363i
Registered Owner:	On file	Rated Power:	186 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	KBDN, 3462 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	2035 UTC	Direction from Accident Site:	20°
Lowest Cloud Condition:	Clear	Visibility	9 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	Light and Variable / 12 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	33° C / 6° C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Bend, OR (BDN)	Type of Flight Plan Filed:	None
Destination:	Bend, OR (BDN)	Type of Clearance:	None
Departure Time:	1221 PDT	Type of Airspace:	Class G

Airport Information

Airport:	Bend Muni (BDN)	Runway Surface Type:	Asphalt
Airport Elevation:	3459 ft	Runway Surface Condition:	Dry
Runway Used:	16	IFR Approach:	None
Runway Length/Width:	5200 ft / 75 ft	VFR Approach/Landing:	Full Stop; Traffic Pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.094444, -121.200278 (est)

Administrative Information

Investigator In Charge (IIC):	Michael A Hicks	Report Date:	06/05/2019
Additional Participating Persons:	Kevin Marpet; FAA; Portland, OR		
Publish Date:	08/20/2020		
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=97959		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).