



National Transportation Safety Board Aviation Accident Final Report

Location:	Shreveport, LA	Accident Number:	CEN18LA346
Date & Time:	08/22/2018, 1050 CDT	Registration:	N4275Q
Aircraft:	Cessna 172	Aircraft Damage:	Substantial
Defining Event:	Miscellaneous/other	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Instructional		

Analysis

The student pilot was departing on a solo cross-country flight when she observed a decrease in climb performance and airspeed shortly after takeoff. She reduced airplane pitch to increase airspeed and avoid an aerodynamic stall. Although the engine continued to operate normally at full throttle, the pilot concluded that there was an engine issue because she was unable to maintain a normal climb pitch attitude without a decrease in airspeed. She told the tower controller that she was going to land and made an immediate turn near midfield to land on a crossing runway. She stated that, after aligning with the crossing runway, the airplane's airspeed had increased to 95-100 knots and that the airplane was too high to make a normal landing. She reduced engine power to idle and attempted to glide to the runway; however, the airplane landed in a grassy area past the end of the runway and bounced three times before the nose gear collapsed.

The pilot acknowledged after the accident that the engine did not malfunction during the flight and postulated that the airplane had encountered a wingtip vortex from another airplane. However, a review of available air traffic control radar track data did not identify any departing or landing aircraft during the 15 minutes before the accident that would have resulted in a wake turbulence encounter. Additionally, the postaccident examination of the airplane's flight controls and engine did not reveal any evidence of a mechanical malfunction or failure that would have precluded normal operation. Based on the pilot's statement and the lack of any evidence of a mechanical malfunction or failure, it is likely that she overshot the runway after her misperception of an engine issue due to her failure to maintain proper pitch control during initial climb.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's overshoot of the runway, which resulted from her misperception of an engine issue due to her failure to maintain proper pitch control during initial climb.

Findings

Aircraft	Pitch control - Not attained/maintained (Cause)
Personnel issues	Perception - Pilot (Cause)

Factual Information

On August 22, 2018, about 1050 central daylight time, a Cessna 172L, N4275Q, made a precautionary landing shortly after takeoff from Shreveport Regional Airport (SHV), Shreveport, Louisiana. The student pilot sustained minor injuries, and the airplane was substantially damaged. The airplane was registered to and operated by a private individual under the provisions of Title 14 *Code of Federal Regulations (CFR)* Part 91. Day visual meteorological conditions prevailed at the accident site. The intended solo cross-country flight to Texarkana Regional Airport-Webb Field (TXK), Texarkana, Arkansas, was departing at the time of the accident.

The student pilot reported that she arrived at SHV around 0930 to preflight the airplane. She stated that her preflight inspection was routine and that she did not observe any anomalies besides low tire pressure on both main landing gear. The engine had about 7 quarts of oil and both fuel tanks were full (topped-off) before the flight. She obtained a taxi clearance from her hangar to an aircraft maintenance facility on the airport that her father owned. After repositioning the airplane to the maintenance facility, she and her father inflated both main tires and polished the windscreen. The pilot reported that the engine restarted without hesitation and ran normally before she taxied to the runway. She obtained a taxi clearance to runway 24 and requested visual flight rules flight following to TXK from ground control. The pilot stated that the surface wind was from 100° magnetic at 4 knots, according to the automatic terminal information service broadcast. She reported the before-takeoff engine runup was uneventful; increased engine speed to 1,700 rpm, verified both magnetos were functional, applied carburetor heat and observed a corresponding decrease of engine speed, and observed normal engine oil temperature and pressure indications. She then verified that the flight controls moved freely through their entire range-of-movements, the elevator trim was set for takeoff (slightly nose-up), and verified correct radio frequencies before calling the tower controller for a takeoff clearance. The tower controller told her to hold short of the runway; however, she received a takeoff clearance about 30 seconds later.

The pilot reported that the takeoff run was normal and that she rotated for liftoff at 60 knots. She stated that after liftoff the elevator force feedback through the control wheel and the kinetic forces were less than normal. The pilot established a normal climb pitch attitude and the airplane climbed to about 800 ft mean sea level where she perceived a continued degradation of airplane climb performance and observed the airspeed decrease from 75 knots to 70 knots. She recalled that the airplane would not climb without a loss of airspeed. The pilot reduced airplane pitch to increase airspeed and avoid an aerodynamic stall. The throttle remained at full power and the engine continued to run smoothly. The pilot stated that despite not observing any anomalies with engine operation, she concluded that the airplane was having engine issues because she was unable to maintain a normal climb pitch attitude without a loss of airspeed. She told the tower controller that she was having engine issues and that she was going to land. The tower controller cleared her to land on any runway. She made an immediate left turn near midfield to land on runway 14. The pilot stated that after aligning with runway 14 the airplane's airspeed had increased to 95-100 knots and that the airplane was too high to make a normal landing. She reduced engine power to idle and attempted to glide to the runway. The pilot reported that the airplane was not able to land on the remaining runway and

that she made a slight left turn to land in the grass area southeast of the runway. The airplane bounced three times in the grass before the nose gear collapsed. The airplane then impacted a drainage ditch at the airport perimeter. The pilot reported that she was not wearing the available shoulder harness, and consequently she was briefly knocked unconscious when her forehead impacted the glare shield and her chin impacted the instrument panel.

The pilot acknowledged that the engine did not malfunction during the flight and postulated that the airplane had encountered a wingtip vortex from another airplane. The pilot further acknowledged that she likely did not have enough experience to correctly identify and recover from a wake turbulence encounter. The pilot stated that she began flight training on June 15, 2018, and all flights were completed in a Cessna 172 airplane. The pilot had flown 63 hours total, of which 9 hours were solo.

A postaccident review of available air traffic control radar track data did not identify any departing or landing aircraft during the 15 minutes before the accident that would have resulted in a wake turbulence encounter.

The airplane was examined by a Federal Aviation Administration (FAA) inspector with the Baton Rouge Flight Standards District Office. The FAA inspector reported that the airplane had landed in the grass to the southeast of runway 14. The landing rollout measured 553 ft long before the airplane impacted a drainage ditch and embankment. The nose landing gear had collapsed, and the airplane came to rest on the lower engine cowl. The cabin floor boards were buckled. The ignition switch and fuel selector were repositioned to OFF by the fire department. The positive battery terminal was disconnected from the battery by the fire department. The FAA inspector confirmed flight control cable continuity from the cockpit controls to each flight control surface. Engine control continuity was confirmed from the cockpit controls to their respective engine controls. There was sufficient fuel observed in each wing fuel tank and neither tank appeared damaged. Fuel samples obtained from both wing tanks, the fuel strainer assembly, and the fuel line to the carburetor were blue in color and had an odor consistent with 100 low-lead aviation fuel. There was no water or particulate contamination observed in any of the fuel samples.

The engine remained partially attached to the firewall. Several engine mounts were bent or fractured. The propeller remained attached to the propeller flange. One propeller blade was bent aft about 90° and the other blade appeared undamaged. There were no anomalies observed with the engine crankcase or its exterior-mounted components. The sparkplugs were removed and exhibited features consistent with normal engine operation. Internal engine and valve train continuity were confirmed as the engine crankshaft was rotated. Compression and suction were noted on all cylinders in conjunction with crankshaft rotation, and acceptable cylinder pressures were measured using a differential pressure gauge. The left magneto remained attached to its installation point and provided spark on all posts while the crankshaft was rotated. The right magneto remained attached to its installation point and was not equipped with an impulse coupling. The engine had about 6 quarts of oil when measured with its calibrated dipstick. The oil cooler was impact damaged and leaking oil. The carburetor fuel inlet screen was free of contamination. The carburetor bowl contained fuel and no contamination was observed in the carburetor bowl. Disassembly of the carburetor did not reveal any anomalies with the venturi, metal floats, accelerator pump, or needle valve. The

postaccident examination did not reveal any evidence of a mechanical malfunction that would have precluded normal engine operation during the flight.

A review of available meteorological data established that day visual meteorological conditions prevailed at the accident site. At 1056, about 6 minutes after the accident, the SHV automated surface observing system reported: wind direction variable at 3 knots, 10 miles surface visibility, few clouds at 4,500 ft above ground level (agl), scattered clouds at 28,000 ft agl, temperature 29°C, dew point 18°C, and an altimeter setting 30.17 inches of mercury.

History of Flight

Initial climb	Miscellaneous/other (Defining event)
Landing	Landing area overshoot Hard landing Landing gear collapse Collision with terr/obj (non-CFIT)

Student Pilot Information

Certificate:	Student	Age:	25, Female
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap Only
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without Waivers/Limitations	Last FAA Medical Exam:	07/10/2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	08/09/2018
Flight Time:	63 hours (Total, all aircraft), 63 hours (Total, this make and model), 9 hours (Pilot In Command, all aircraft), 63 hours (Last 90 days, all aircraft), 30 hours (Last 30 days, all aircraft), 0 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N4275Q
Model/Series:	172 L	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	17260175
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	06/01/2018, Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:	47 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3190 Hours at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	O-320-E2D
Registered Owner:	On file	Rated Power:	150 hp
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	SHV, 258 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	1056 CDT	Direction from Accident Site:	303°
Lowest Cloud Condition:	Few / 4500 ft agl	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	Variable	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.17 inches Hg	Temperature/Dew Point:	29° C / 18° C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Shreveport, LA (SHV)	Type of Flight Plan Filed:	VFR
Destination:	Texarkana, AR (TXK)	Type of Clearance:	VFR Flight Following
Departure Time:	1050 CDT	Type of Airspace:	Class C

Airport Information

Airport:	Shreveport Regional (SHV)	Runway Surface Type:	N/A
Airport Elevation:	258 ft	Runway Surface Condition:	Dry; Vegetation
Runway Used:	N/A	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Precautionary Landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	32.438889, -93.814167

Administrative Information

Investigator In Charge (IIC):	Andrew T Fox	Report Date:	09/27/2019
Additional Participating Persons:	Paul A Marks; Federal Aviation Administration, Baton Rouge FSDO; Baton Rouge, LA		
Publish Date:	09/27/2019		
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	http://dms.nts.gov/pubdms/search/dockList.cfm?mKey=98132		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).