



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	ONEONTA, NY	<b>Accident Number:</b>	BF094LA059
<b>Date &amp; Time:</b>	04/02/1994, 1415 EST	<b>Registration:</b>	N28224
<b>Aircraft:</b>	GULFSTREAM AMERICAN AA-5B	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None

**Flight Conducted Under:** Part 91: General Aviation - Instructional

---

On April 2, 1994, at 1415 eastern standard time, a Gulfstream American AA-5B, struck a snowbank during takeoff on runway 24 at Oneonta Municipal Airport, Oneonta, New York. The student pilot was not injured while the airplane sustained substantial damage. The instructional flight was being operated under 14 CFR 91. Visual meteorological conditions prevailed and a flight plan was not filed.

The pilot stated that during the takeoff roll as he was about to rotate, the airplane started to veer to the left. He stated that he applied right rudder, but he was unsuccessful. The pilot stated that he continued to apply right rudder and right brake, but the airplane continued to veer off the left side of the runway and struck a snowbank. The pilot stated that he believed there was a problem with the left wheel or brake.

An FAA Aviation Safety Inspector examined the airplane after the accident and reported that there was no mechanical malfunction. He stated that the winds at the time of the accident were 150 degrees at 14 knots gusting to 20 knots.

## Pilot Information

---

<b>Certificate:</b>	Student	<b>Age:</b>	52, Male
<b>Airplane Rating(s):</b>	None	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	12/01/1993
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	46 hours (Total, all aircraft), 27 hours (Total, this make and model), 13 hours (Pilot In Command, all aircraft), 27 hours (Last 90 days, all aircraft), 11 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	GULFSTREAM AMERICAN	Registration:	N28224
Model/Series:	AA-5B AA-5B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal; Utility	Serial Number:	AA5B0946
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	02/23/1994, Annual	Certified Max Gross Wt.:	2400 lbs
Time Since Last Inspection:	20 Hours	Engines:	1 Reciprocating
Airframe Total Time:	3115 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-360-A4K
Registered Owner:	BERT COOK/ BERNARD KAMP,	Rated Power:	180 hp
Operator:	KAMP AIR AVIATION INC.	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	BGM, 1636 ft msl	Distance from Accident Site:	40 Nautical Miles
Observation Time:	1350 EST	Direction from Accident Site:	76°
Lowest Cloud Condition:	Thin Broken / 25000 ft agl	Visibility	15 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	14 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	150°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	13° C / -1° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	1400 EST	Type of Airspace:	Class D; Class G

## Airport Information

Airport:	ONEONTA MUNI (N66)	Runway Surface Type:	Asphalt
Airport Elevation:	1764 ft	Runway Surface Condition:	Snow--dry
Runway Used:	24	IFR Approach:	None
Runway Length/Width:	4200 ft / 75 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	BEVERLEY JOHNSON,
<b>Additional Participating Persons:</b>	RICHARD PECK; ALBANY, NY
<b>Investigation Docket:</b>	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .