



National Transportation Safety Board Aviation Accident Data Summary

Location:	HOMER, AK	Accident Number:	ANC90LA106
Date & Time:	07/01/1990, 1100 AKD	Registration:	N820AK
Aircraft:	CESSNA 180K	Injuries:	1 None
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

THE PILOT REPORTED THAT HE LOST DIRECTIONAL CONTROL DURING THE LANDING ROLL AND GROUND LOOPED THE AIRPLANE TO THE RIGHT, DAMAGING THE LEFT WING. THE PILOT NOTED IN HIS ACCIDENT REPORT TO NTSB THAT HIS LAST BIENNIAL FLIGHT REVIEW WAS ACCOMPLISHED APPROXIMATELY 44 MONTHS PRIOR TO THE ACCIDENT FLIGHT.

Probable Cause

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT LOSS OF DIRECTIONAL CONTROL.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

- 1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: DRAGGED WING, ROTOR, POD, FLOAT OR TAIL/SKID
Phase of Operation: LANDING - ROLL

Pilot Information

Certificate:	Private	Age:	42
Airplane Rating(s):	Single-engine Land	Instrument Rating(s):	None
Other Aircraft Rating(s):	None	Instructor Rating(s):	
Flight Time:	1050 hours (Total, all aircraft), 900 hours (Total, this make and model), 50 hours (Last 90 days, all aircraft), 25 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N820AK
Model/Series:	180K 180K	Engines:	1 Reciprocating
Operator:	COTTRELL, DAVID J	Engine Manufacturer:	CONTINENTAL
Operating Certificate(s) Held:	None	Engine Model/Series:	O-470U
Flight Conducted Under:	Part 91: General Aviation - Personal		

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Weather Information Source:	Pilot
Lowest Ceiling:	None / 0 ft agl	Wind Speed/Gusts, Direction:	5 knots / , 160°
Temperature:	10° C	Visibility	50 Miles
Precipitation and Obscuration:			
Departure Point:	SELDOVIA, AK (SOV)	Destination:	

Airport Information

Airport:	HOMER (HOM)	Runway Surface Type:	Asphalt
Runway Used:	0	Runway Surface Condition:	Dry
Runway Length/Width:	7400 ft / 150 ft		

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None

Latitude, Longitude:

Administrative Information

Investigator In Charge (IIC):	JAMES LA BELLE	Adopted Date:	02/12/1993
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.