



# National Transportation Safety Board Aviation Accident Factual Report

---

<b>Location:</b>	WINDHAM, CT	<b>Accident Number:</b>	NYC88LA232
<b>Date &amp; Time:</b>	09/01/1988, 1700 EDT	<b>Registration:</b>	N94502
<b>Aircraft:</b>	CESSNA 152	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 Serious
<b>Flight Conducted Under:</b>	Part 91: General Aviation - Instructional		

---

## Pilot Information

---

<b>Certificate:</b>	Student	<b>Age:</b>	26, Female
<b>Airplane Rating(s):</b>	Single-engine Land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Seatbelt, Shoulder harness
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--w/ waivers/lim.	<b>Last FAA Medical Exam:</b>	02/05/1988
<b>Occupational Pilot:</b>		<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	98 hours (Total, all aircraft), 98 hours (Total, this make and model), 13 hours (Pilot In Command, all aircraft), 26 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N94502
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal; Utility	Serial Number:	85693
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	08/16/1988, AAIP	Certified Max Gross Wt.:	1670 lbs
Time Since Last Inspection:	33 Hours	Engines:	1 Reciprocating
Airframe Total Time:	2368 Hours	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-235-L2C
Registered Owner:	KING SERVICES OF AVIATION INC	Rated Power:	108 hp
Operator:	KING SERVICE AVIATION, INC.	Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	, 0 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	0000	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear / 0 ft agl	Visibility	0 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	Calm /	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24° C
Precipitation and Obscuration:			
Departure Point:	E TAUNTON, MA (IAN)	Type of Flight Plan Filed:	VFR
Destination:	WINDHAM, CT (5B0)	Type of Clearance:	None
Departure Time:	1600 EDT	Type of Airspace:	Class G

## Airport Information

Airport:	WINDHAM (5B0)	Runway Surface Type:	Asphalt
Airport Elevation:	246 ft	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	
Runway Length/Width:	4360 ft / 150 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	N/A	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious	<b>Latitude, Longitude:</b>	

## Administrative Information

<b>Investigator In Charge (IIC):</b>	REUBEN DENSLEY
<b>Additional Participating Persons:</b>	R SULLIVAN; WESTFIELD, MA
<b>Investigation Docket:</b>	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at <a href="mailto:pubinq@ntsb.gov">pubinq@ntsb.gov</a> , or at 800-877-6799. Dockets released after this date are available at <a href="http://dms.nts.gov/pubdms/">http://dms.nts.gov/pubdms/</a> .