



National Transportation Safety Board Aviation Incident Final Report

Location:	NEWARK, NJ	Incident Number:	MIA88IA055A
Date & Time:	11/01/1987, 1712 EST	Registration:	N806NY
Aircraft:	MCDONNELL DOUGLAS DC-9-82	Aircraft Damage:	None
Defining Event:		Injuries:	84 None

Flight Conducted Under: Part 121: Air Carrier - Scheduled

Analysis

AT 1710:53 EST, THE LCL TWR CTLR (LC) AT THE NEWARK INTL ARPT CLRD CONTINENTAL FLT 321 (DC-9-82, N806NY) FOR TAKEOFF ON RWY 22L; 11 SEC LATER, CONTINENTAL FLT 688 (BOEING 727, N577PE) RPRTD 'LEFT DOWNWIND FOR RWY 29.' LC TOLD FLT 688 TO 'MAINTAIN 1500 AS YOU CROSS OVER THE FIELD.' RWY 22L (9300' LONG) WAS LOCATED SOUTH OF RWY 29; THUS, THE LEFT DOWNWIND FOR RWY 29 WAS NR THE DEP END OF THE 22L. AT 1712:12, LC TOLD FLT 321 THAT FLT 688 WAS PASSING 'OVERHEAD & BEHIND YOU AT 1800' . . .' AT ABOUT THAT TIME, THE CREW OF FLT 321 NOTED THEY WERE CLBG THRU 1000' WHEN THEY SAW FLT 688 PASSING DIRECTLY OVERHEAD. THE CAPT OF FLT 688 SAW FLT 321 TAKING OFF & ESTD THE SEPN REMAINED IN EXCESS OF 1000', BUT THE CAPT OF FLT 321 WAS CONCERNED ABOUT THE CLOSE PROXIMITY & CALLED THE TWR AFTER LNDG. RADAR DATA SHOWED THE PLANES PASSED WITHAPRX 400' VERTICAL & 1000' LATERAL SEPN, APRX 1/4 MI SOUTH OF THE ARPT. BOTH FLTS WERE OPERG ON IFR FLT PLANS. LC DID NOT ADZ EITHER FLT CREW OF THEIR TRAFFIC UNTIL 1712:12, MOMENTS BFR THEIR FLT PATHS CROSSED. THE ARPT HAD HVY TRAFFIC.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this incident to be:

Findings

Occurrence #1: NEAR COLLISION BETWEEN AIRCRAFT
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) CONTROL TOWER SERVICE - INADEQUATE - ATC PERSONNEL(LCL/GND/CLNC)
2. (C) VISUAL SEPARATION - IMPROPER USE OF - ATC PERSONNEL(LCL/GND/CLNC)
3. (C) TRAFFIC ADVISORY - DELAYED - ATC PERSONNEL(LCL/GND/CLNC)

Factual Information

Pilot Information

Certificate:	Airline Transport; Flight Instructor	Age:	37, Male
Airplane Rating(s):	Multi-engine Land; Single-engine Land; Single-engine Sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane Single-engine	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	09/21/1987
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	8000 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	MCDONNELL DOUGLAS	Registration:	N806NY
Model/Series:	DC-9-82 DC-9-82	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Transport	Serial Number:	49260
Landing Gear Type:	Retractable - Tricycle	Seats:	172
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	147000 lbs
Time Since Last Inspection:		Engines:	2 Turbo Fan
Airframe Total Time:		Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	JT8D-217
Registered Owner:	NEWYORK AIRLINES INC.	Rated Power:	20850 lbs
Operator:	CONTINENTAL AIRLINES	Operating Certificate(s) Held:	Flag carrier (121)
Operator Does Business As:		Operator Designator Code:	CALA

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:	EWK, 18 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	1650 EST	Direction from Accident Site:	0°
Lowest Cloud Condition:	Scattered / 12000 ft agl	Visibility	10 Miles
Lowest Ceiling:	None / 0 ft agl	Visibility (RVR):	0 ft
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	170°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	14° C / 8° C
Precipitation and Obscuration:			
Departure Point:		Type of Flight Plan Filed:	IFR
Destination:	WASHINGTON, DC (IAD)	Type of Clearance:	IFR
Departure Time:	1710 EST	Type of Airspace:	Class B

Airport Information

Airport:	NEWARK INTL (EWR)	Runway Surface Type:	Asphalt
Airport Elevation:	18 ft	Runway Surface Condition:	Dry
Runway Used:	22L	IFR Approach:	None
Runway Length/Width:	9300 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	6 None	Aircraft Damage:	None
Passenger Injuries:	78 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	84 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	ANDREW A ALSTON	Report Date:	09/12/1988
Additional Participating Persons:	JOHN FERRATT; WASHINGTON, DC RICHARD WENTWORTH; WASHINGTON, DC		
Publish Date:			
Investigation Docket:	NTSB accident and incident dockets serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).