



National Transportation Safety Board Aviation Accident Factual Report

Location:	Winston, OR	Accident Number:	SEA01LA164
Date & Time:	09/01/2001, 1830 PDT	Registration:	N95223
Aircraft:	Taylorcraft BC12-D	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 Minor
Flight Conducted Under:	Part 91: General Aviation - Personal		

On September 1, 2001, about 1830 Pacific daylight time, a Taylorcraft BC12-D, N95223, registered to a private owner and operated by the pilot as a 14 CFR Part 91 personal flight, collided with a fence during takeoff from an open pasture located about seven miles southwest of Winston, OR. Visual meteorological conditions prevailed at the time and no flight plan was filed. The aircraft was substantially damaged and the private pilot, the sole occupant, received minor injuries.

During a telephone interview with the NTSB IIC, and subsequent statements to the Federal Aviation Administration inspector from the Portland, Oregon, Flight Standards District Office, the pilot reported that the flight began from Roseburg, Oregon, and was flown to a farm near Winston. The pilot reported that the aircraft had not undergone an annual inspection for about three years and he was repositioning the aircraft to this area so that "major rework" could be accomplished. The pilot over flew the farm several times to determine the wind direction then proceeded to land. While on the ground, the pilot noted that the wind was "swirling," but appeared to be blowing from the north to southwest. In order for the aircraft to be closer to his residence, the pilot got back in the aircraft to move it to another field. The pilot stated that he applied full throttle with the brakes on in preparation for a short field takeoff to the north. The pilot thought that the aircraft attained an altitude of about ten feet, about 150 feet before the fence line, when the aircraft started to steadily lose altitude. One of the main landing gear wheels caught on the fence. The aircraft continued flying but "mushed" along before colliding with another fence on the north end of the field, substantially damaging both wings and collapsing the landing gear. The pilot reported no mechanical failures or malfunctions with the aircraft at the time of the accident.

Two witnesses reported that the aircraft pulled up just before colliding with the three to four foot high fence. The aircraft continued on over the next field, subsequently colliding with the fence on the north end of the field. One witness reported that the takeoff was "going with the wind," while the other reported that the breeze was light from the south.

Pilot Information

Certificate:	Private	Age:	46, Male
Airplane Rating(s):	Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Seatbelt
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Expired	Last FAA Medical Exam:	
Occupational Pilot:		Last Flight Review or Equivalent:	
Flight Time:	338 hours (Total, all aircraft), 300 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Taylorcraft	Registration:	N95223
Model/Series:	BC12-D	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	9623
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	12/03/1996, Annual	Certified Max Gross Wt.:	1500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:	Installed	Engine Model/Series:	A-65-8
Registered Owner:	Keith A. Graham	Rated Power:	65 hp
Operator:	Calvin W. Graham	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual Conditions	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 Miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24° C
Precipitation and Obscuration:			
Departure Point:	Winston, OR	Type of Flight Plan Filed:	None
Destination:	Winston, WA	Type of Clearance:	None
Departure Time:	PDT	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Debra J Eckrote
Additional Participating Persons:	Robert J Bilak; FAA-FSDO; Hillsboro, OR
Investigation Docket:	NTSB accident and incident docket serve as permanent archival information for the NTSB's investigations. Dockets released prior to June 1, 2009 are publicly available from the NTSB's Record Management Division at pubinq@ntsb.gov , or at 800-877-6799. Dockets released after this date are available at http://dms.nts.gov/pubdms/ .