



National Transportation Safety Board Aviation Accident Final Report

Location:	Wetumpka, AL	Accident Number:	ERA15CA176
Date & Time:	04/03/2015, 2015 CDT	Registration:	N9172Q
Aircraft:	BEECH V35B	Aircraft Damage:	Substantial
Defining Event:	Controlled flight into terr/obj (CFIT)	Injuries:	1 Serious
Flight Conducted Under:	Part 91: General Aviation - Personal		

Analysis

The pilot reported that he was landing his airplane at night and mistook the hangar lights for runway lights. The airplane struck trees on the final approach, then the ground before coming to rest, inverted. The pilot said that, in retrospect, he was on the incorrect radio frequency when he attempted to turn on the pilot-activated runway lights. A Federal Aviation Administration inspector examined the wreckage and reported that the airplane sustained substantial damage. The pilot reported that there were no mechanical problems with the airplane at the time of the accident. The runway lights operated normally after the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's use of an incorrect radio frequency when attempting to turn on the runway lights, resulting in an attempt to land the airplane while aligned with airport hangar lights.

Findings

Aircraft	Descent/approach/glide path - Not attained/maintained (Cause)
Personnel issues	Use of equip/system - Pilot (Cause)
Environmental issues	Dark - Contributed to outcome

Factual Information

History of Flight

Approach-VFR pattern final	Controlled flight into terr/obj (CFIT) (Defining event)
Uncontrolled descent	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	77
Airplane Rating(s):	Multi-engine Land; Single-engine Land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With Waivers/Limitations	Last Medical Exam:	09/11/2014
Occupational Pilot:	No	Last Flight Review or Equivalent:	03/06/2015
Flight Time:	3326 hours (Total, all aircraft), 1909 hours (Total, this make and model), 10 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Manufacturer:	BEECH	Registration:	N9172Q
Model/Series:	V35B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	No
Airworthiness Certificate:	Normal	Serial Number:	D-9250
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	11/01/2014, Annual	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	6137 Hours	Engine Manufacturer:	Continental
ELT:	C126 installed, not activated	Engine Model/Series:	IO-520 Series
Registered Owner:	POWER DANIEL N	Rated Power:	285 hp
Operator:	POWER DANIEL N	Air Carrier Operating Certificate:	None

Meteorological Information and Flight Plan

Observation Facility, Elevation:	MGM, 221 ft msl	Observation Time:	2053 CDT
Distance from Accident Site:	9 Nautical Miles	Condition of Light:	Night/Dark
Direction from Accident Site:	190°	Conditions at Accident Site:	Visual Conditions
Lowest Cloud Condition:	Clear	Temperature/Dew Point:	25° C / 16° C
Lowest Ceiling:	None	Visibility	10 Miles
Wind Speed/Gusts, Direction:	9 knots/ 18 knots, 200°	Visibility (RVR):	
Altimeter Setting:	30 inches Hg	Visibility (RVV):	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Galveston, TX (GLS)	Type of Flight Plan Filed:	None
Destination:	Wetumpka, AL (08A)	Type of Clearance:	None
Departure Time:	CDT	Type of Airspace:	

Airport Information

Airport:	Wetumpka Muni (08A)	Runway Surface Type:	Asphalt
Airport Elevation:	197 ft	Runway Surface Condition:	Unknown
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3011 ft / 80 ft	VFR Approach/Landing:	Full Stop

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious		

Administrative Information

Investigator In Charge (IIC):	Ralph E Hicks	Adopted Date:	08/11/2015
Additional Participating Persons:	John Park; FAA FSDO; Vestavia Hills, AL		
Publish Date:	08/11/2015		
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.		
Investigation Docket:	http://dms.ntsb.gov/pubdms/search/dockList.cfm?mKey=90988		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report.